

### Asbestos Building Materials Inspection Services

Client: The City of Grand Junction, 250 N. 5<sup>th</sup> Street, Grand Junction, CO 81501

Project Site: 2844 Patterson Road, Grand Junction, CO 81506

(House, Large Metal Shop, Metal Carport and Small Metal Shop Structures)

Inspection Date: January 22, 2024

Phase Con Project #: 24-01-22D1

2166 Peregrine Court Grand Junction, CO 81507 970-260-3341 -- office@phasecon.com

### 2844 Patterson Road, Grand Junction, CO -- House (SFRD) & Outbuildings

### **Sampling Description**

Phase Con provided asbestos building inspection services at 2844 Patterson Road in Grand Junction, Colorado on January 22, 2024. The inspection was performed by Mr. Douglas Close, a Colorado State and EPA Asbestos Building Inspector/Management Planner. This house (SFRD) and outbuildings are scheduled for demolition in the near future. Suspect materials within the scope of work were sampled and analyzed as per Colorado State Regulation #8.

A random sampling scheme was utilized in choosing sampling locations. This scheme used a grid system and randomly generated numbers. The Inspector, Mr. Douglas Close, classified the suspect materials by type (Thermal System Insulation (TSI), Surfacing Materials, and Miscellaneous Materials), and obtained the appropriate number of samples of each material based upon material type, and quantity.

Tables are provided which detail the individual samples obtained, the laboratory analysis results for these samples, the quantity and condition of Asbestos Containing Building Materials (ACBM), the locations of each homogeneous area, and other material specific information. Potential for damage to materials information is provided in the following sampling information tables.

### **Discussion & Recommendations**

House Structure

### The following materials were positive for Colorado State and EPA regulated asbestos content (>1% asbestos):

- Popcorn Type Ceiling Texture & Joint Compound in Associated Gypsum Board Systems - present in the basement as shown on the attached diagram. Areas of overspray on the walls were observed and will need to be properly abated (removed) as part of the abatement process. There is an estimated 400 sf of this ACBM present.
- <u>9x9 Vinyl Floor Tile & Associated Black Mastic</u> present in the front entry area beneath carpeting. There is an estimated 65 sf of this ACBM present.

• <u>Paper Type Duct Insulation Wrap</u> – present on original ductwork in the house. Visible in the basement as a single large duct with a few branches with insulation also present at the vent openings on the main floor. There is an estimated 60 sf of this ACBM present.

The prior listed ACBMs are regulated by the State of Colorado and the EPA and <u>must</u> be handled, removed and disposed of by a State of Colorado licensed asbestos abatement contractor (General Abatement Certificate holder) in accordance with Colorado State Regulation #8 prior to building demolition.

### The following materials were positive for 'trace' asbestos content (<=1% asbestos) as verified by point count analysis:

• <u>Interior Plaster</u> – present on most walls and ceilings on the main level of the house and the stairway leading to the basement. There is an estimated 3000 sf of this trace asbestos content plaster present.

The trace asbestos content (<=1% asbestos as verified by point count analysis) building materials listed above are NOT considered to be Asbestos Containing Building Materials (ACBMs) by the State of Colorado or the EPA and therefore are not regulated by these two bodies; however, OSHA regulations apply to damage, disturbance or handling of this trace asbestos content material and landfills will require special packaging and disposal of these materials. OSHA regulations only apply to employee exposure. The presence of any amount of asbestos in building debris/waste will result in landfill packaging requirements, fees and dumping restrictions. The client must contact the landfill to ensure appropriate packaging and disposal compliance. OSHA requirements are detailed here:

- Exposure monitoring of personnel during the first work shift to determine exposure levels. If exposure levels are within the OSHA PEL and STEL, then the requirements listed below apply...if exposure levels are above the OSHA PEL/STEL then work must proceed as Class I OSHA asbestos work.
- Use of wet methods, or wetting agents, to control employee exposures during asbestos handling.
- Prompt clean-up and disposal of wastes and debris contaminated with asbestos in leak-tight containers.
- Prohibition of high speed abrasive disc saws not equipped with

HEPA filtration.

- Prohibition of compressed air used to remove asbestos, or as a clean-up technique.
- Prohibition of employee rotation as a means of reducing employee exposure to asbestos.
- Asbestos awareness training for all personnel (typically eight hours of training).

Furthermore, I recommend the use of half-face negative pressure respirators equipped with HEPA filtered cartridges by all personnel along with other appropriate Personal Protective Equipment (PPE) and establishment of a regulated work area with negative air pressure produced by HEPA filtration of interior air exhausted outside of the building.

Although not required by the State and the EPA for trace asbestos content materials; I recommend that any materials which contain asbestos in any quantity only be damaged or disturbed by properly trained and protected personnel in the employ of a licensed asbestos abatement contractor utilizing appropriate engineering controls and methods. Even trace asbestos content materials can release significant asbestos into the air potentially contaminating portions of the building and resulting in personnel exposure.

The trace asbestos containing materials will need to be packaged appropriately for disposal in the landfill. The property owner should contact the landfill for specifics.

### Large Metal Shop Building

No asbestos containing building materials are present in this structure. There are no building materials present which are suspect for potential asbestos content; only wood structural members and metal siding/roof panels.

### Metal Carport Structure

No asbestos containing building materials are present in this structure. There are no building materials present which are suspect for potential asbestos content; only wood structural members and metal siding/roof panels.

### Small Metal Shop Structure

No asbestos containing building materials are present in this structure. There are no building materials present which are suspect for potential asbestos content; only wood structural members and metal siding/roof panels.

If any previously unknown or undiscovered materials are found during demolition activities which are suspect for asbestos content then these materials should be tested for potential asbestos content prior to continuing any further demolition work.

### **Disclaimer**

Identified asbestos containing materials may be in areas which are inaccessible or hidden due to their application during the construction process and their subsequent enclosure or covering with building and finish materials. Areas behind walls, inside chases, or other hidden, covered or enclosed areas should be inspected whenever renovation or demolition activities are scheduled which may disturb the materials within or beneath these barriers. Care to watch for hidden or undiscovered materials should be taken by the demolition contractor during the demolition process. A discovery of unknown materials will necessitate stopping demolition until the materials can be inspected by a certified asbestos building inspector. 'Overspray' or excess materials from the installation or application process of asbestos containing materials is common, should be expected in the vicinity of installed asbestos containing materials, and is often present either covered by other building materials or in hidden or unexpected locations.

Bulk material samples are obtained in accordance with applicable regulations, industry standard techniques and analyzed by a NVLAP accredited laboratory; however, due to the asbestos content fluctuations which may occur in a building material due to the application and/or initial mixing process no guarantee can be made as to an 'exact' percentage asbestos content (this includes 'no asbestos detected' and 'trace' contents) which represents the entirety of the material (asbestos content fluctuations can and will occur throughout a building material).

Abatement cost estimates and material quantity estimates are approximate only (due to the hidden nature of many of the materials), and are provided only as a general guideline to the client. More than one licensed Colorado State asbestos abatement contractor should be


consulted to determine actual abatement costs of the ACBMs described above. Actual material quantities can only be determined by complete removal of covering materials.

Please call us with any questions which you may have concerning this report and our recommendations. Thank you.

Douglas A. Close

Colorado State and EPA Certified Asbestos Building

Ínspector/Management Planner #2930



Sampling & Materials Description Table -- 2844 Patterson, GJ, CO

ASB EST OS (Y/N)	Z	z	z	z	Z	z	z	z	z	z	Z
FNF	Ľ.	ΑN	11_	<u>LL</u> ,	L	<u>L</u>	Ī.L.	LL.	Ш	N.	NF
REA SON for POT DMG	ı	1	•	3	•	t	ī	t	•	1	
POTE NTIA L for DAM AGE	NPD	NPD	NPD	NPD	NPD	NPD	NPD	NPD	NPD	NPD	NPD
REASON for CONDN ASSESS MENT	1	-	1	1	l .	ī	t	ı	1	ı	-
TIOND	Э	ව	മ	ග	g	g	g	g	<u>ත</u>	ව	ڻ ت
OUA COND NTIT TION	1 sf	1 sf	1200 sf	1200 sf	1200 sf	1200 sf	1200 sf	50 sf	50 sf	1300 sf	1300 sf
MTR.	M	Σ	S	S	S	S	S	Σ	Σ	Σ	Σ
MATERIAL	original windows	All original windows	House exterior	House bricks	House bricks	Roof	Roof				
MATERIAL DESCRIPTION	Window glazing	Window glazing	Exterior brick coating	Brick mortar	Brick mortar	Asphalt roofing shingles	Asphalt roofing shingles				
HMG NS AREA	A	A	В	В	В	В	В	Ö	O	Q	۵
WS.	-	Ċ	က	4	ഹ	9	7	ω	6	10	Ţ-

Sampling & Materials Description Table -- 2844 Patterson, GJ, CO

ASB EST OS (YN)	z	z	z	Trace	Trace	z	z	z	Z	Y, both
FMF	ட	LL.	11_	ഥ	<b>L</b> L	L	Щ	ட	ட	N N
REA SON for POT DMG	t	•	•	•	•	1	1	1	I	1.
POTE NTIA L for DAM	NPD	NPD	NPD	NPD	NPD	NPD	NPD	NPD	NPD	NPD
REASON for CONDN ASSESS MENT	ı	1	3	1	1	1	1	1	1	1
COND	മ	G	G	ප	ල	9	9	5		ڻ ت
OUA NTITI Y	3000 sf	3000 sf	3000 sf	3000 sf	3000 sf	300 sf	300 sf	250 sf	250 sf	65 sf
MTR	တ	S	S	S	S	∑	Σ	Σ	Σ	Σ
MATERIAL LOCATION(S)	Main floor interior walls/ ceilings	Kitchen, DR, bathrooms top layer	Kitchen, DR, bathrooms top layer	Bottom layer, kitchen, DR, rear entry & east bathroom	Bottom layer, kitchen, DR, rear entry & east bathroom	South entry area				
MATERIAL DESCRIPTION	Plaster	Plaster	Plaster	Plaster	Plaster	White square pattern sheet vinyl flooring	White square pattern sheet vinyl flooring	Black tar impregnated felt	Black tar impregnated felt	9x9 vinyl floor tile & black mastic
HMG NS AREA	Ш	ш	Ш	Ш	Ш	ட	Ц.	g g	g	Τ
SM PL	12	13	14	15	16	17	18	19	20	21

Sampling & Materials Description Table -- 2844 Patterson, GJ, CO


		)			The state of the s		ALCOHOLOGICAL PROPERTY OF THE	Committee of the Commit	The second secon		THE REAL PROPERTY.
MS Td.	HMG NS AREA	MATERIAL DESCRIPTION	MATERIAL	MTR	ÖÜA NTIT Y	COND	REASON for CONDN ASSESS MENT	POTE NTIA L'for DAM AGE	REA SON for POT	F	ASB EST OS (Y/N)
22	エ	9x9 vinyl floor tile & black mastic	South entry area	M	65 sf	Б	1	NPD	ı	HZ HZ	Υ, both
23	_	Grey paper type duct wrap	Original ductwork & vent boots	M	60 sf	G	t	NPD	ŧ	ட	>
24		Grey paper type duct wrap	Original ductwork & vent boots	M	60 sf	മ	t	NPD	1	ഥ	<b>\</b>
25	<b>-</b>	Popcorn type ceiling texture	Basement	S	400 sf	മ	t.	NPD	1	ഥ	<b>&gt;</b>
26	<u>ا</u>	Popcorn type ceiling texture	Basement	S	400 sf	ව	•	NPD	1	[_	>-
27	٦	Popcorn type ceiling texture	Basement	S	400 sf	<u>ත</u>	•	NPD	t	<b>L</b>	>-
28	エ	Interior plaster	Basement walls & basement perimeter walls	S	900 sf	<u>ග</u>	1	NPD	8	L	z
29	×	Interior plaster	Basement walls & basement perimeter walls	S	900 sf	ច	ı	NPD	•	LL.	z
30	ス	Interior plaster	Basement walls & basement perimeter walls	S	900 sf	Q	1	NPD	1	LL_	z
31	-J	Gypsum board core sample, Homogeneous Area J	Basement	M	400 sf	Ō	-	NPD	1	ட	>


### <u>Abbreviations</u>

pd -- potential for damage F -- Friable spd -- sig. potential for damage S -- Surfacing material M -- Miscellaneous material

Tr, comp - composite trace content g -- good npd -- no potential for damage NF -- Non-Friable sd - significant damage TSI -- Thermal System Insulation Trace -- <1% asbestos Tr, c d -- damaged







Dedicated to Quality CA Labs. L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 CDPHE #AL-18111 LELAP #03069

### Polarized Light Asbestiform Materials Point Count

**Laboratory Analysis Report - Point Count** 

### **Analysis and Method**

Point counting was performed on a polarized light microscope with a calibrated reticle according to the revised NESHAP method of November 20, 1990 (Federal Register, V.55, N.224, 11/20/90). Original asbestos content of bulk materials was determined using procedures outlined in the interim method (40 CFR part 763, Appendix E to subpart E) and AHERA method (EPA-600/R-93/116). Samples were prepared using HCL acid washing for carbonate based samples, chemical reduction for organically bound components, oil immersion for identification of asbestos types by dispersion staining / becke line method.

### **Qualifications**

CA Labs is accredited by the National Voluntary Accreditation Program (NVLAP) for selected test methods for airborne fiber analysis (TEM), and for bulk asbestos fiber analysis (PLM). All analysts have a college degree in a natural science (geology, biology, or environmental science) or are recognized by a state professional board in one of these disciplines. Extensive in-house training programs are used to augment education background of the analyst. The group leader of polarized light has received supplemental McCrone Research training for asbestos identification. This report is not covered by the scope of NVLAP or AIHA accreditation. Analysis performed at CA Labs, LLC 12232 Industriplex, Suite 32 Baton Rouge, LA 70809.

CA Labs Project #: **Customer Project:** Customer Info: Attn: Doug Close CBR24010361B 2844 Patterson Road Phase Con Environmental Consultants, LLC 2166 Peregrine Court 1/26/2024 Grand Junction, CO 81507 Date: Turnaround Time: 2 Day Samples Received: 1/25/2024 Date Of Sampling: 970-241-6480 Phone # Purchase Order #: Fax# 970-241-6584 Point Counted % / Sample # Layer Analysts Physical Homo-geneous Description of (Y/N)Asbestos Type Subsample Y 0.25% Chrvsotile 15 Gray Plaster 16 16-2 Grav Plaster 0.50% Chrysotile

This report relates to the items tested. This report is not to be used by the customer to claim product certification, approval or endorsement by NVLAP, NIST or any other agency of the federal government. This report may not be reproduced except in full without written permission from CA Labs. These results are submitted pursuant to CA Labs' current terms and sale, condition of sale, including the company's standard warranty and limitations of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, CA Labs will store the samples for a period of ninety (90) days before discarding. A shipping or handling fee may be assessed for the return of any samples.

Approved Signatories:

Zo Andriampenomanana Analyst Senior Analyst Alicia Stretz Laboratory Director Chris Williams

This VIII

Dedicated to Quality

CA Labs, L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634

NVLAP #200772-0 TDSHS #300370 **CDPHE #AL-18111** LELAP #03069

### Materials Characterization - Bulk Asbestos Analysis

Laboratory Analysis Report - Polarized Light

Phase Con Environmental Consultants, LLC

2166 Peregrine Court Grand Junction, CO 81507

Attn: Doug Close Customer Project: 2844 Patterson Road

CBR24010361 Reference #:

1/24/2024 Date:

**Analysis and Method** 

Summary of polarizing light microscopy (PLM / Stereomicroscopy bulk asbestos analysis) using the methods described in 40CFR Part 763 Appendix E to Subpart E (Interim and EPA 600 / R-93 / 116 (Improved). The sample is first viewed with the aid of stereomicroscopy. Numerous liquid slide preparations are created for analysis under the polarized microscope where identifications and quantifications are preformed. Calibrated liquid refractive oils are used as liquid mouting medium. These oils are used for identification (dispersion staining). A calibrated visual estimation is reported, should any asbestiform mineral be present. Other techniques such as acid washing are used in conjugation with refractive oils for detection of smaller quantities of asbestos. All asbestos percentages are based on calibrated visual estimation traceable to NIST standards for regulated of asbestos. Traceability to measurement and calibration is achieved by using known amounts and types of asbestos from standards where analyst and laboratory accuracy are measured. As little as 0.001% asbestos can be detected in favorable samples, while detection in unfavorable samples may approach the detection limit of 0.50% (well above the laboratory definition of trace).

### Discussion

Vermiculite containing samples may have trace amounts of actinolite-tremolite, where not found be PLM should be analyzed using TEM methods and / or water separation techniques. Suspected actinolite/vermiculite presence will be indicated through the sample comment section of this report.

Fibrous talc containing samples may even contain a related asbestos fiber known as anthophyllite. Under certain conditions the same fiber may actually contain both talc and anthophyllite (a phenomenon called intergrowth). Again, TEM detection methods are recommended. CA Labs PLM report comments will denote suspected amounts of asbestiform anthophyllite with talc, where further analysis is recommended.

Some samples (floor tiles, surfacings, etc.) may contain fibers too small to be detectable by PLM analysis and should be analyzed by TEM bulk protocols.

A "trace asbestos" will be reported if the analyst observes far less than 1% asbestos. CA Labs defines "trace asbestos" as a few fibers detected by the analyst in several preparations and will indicate as such under these circumstances.

Quantification of <1% will actually be reported as <=1% (allowable variance close to 1% is high). Such results are ideal for point counting, and the technique is mandatory for friable samples (NESHAP, Nov. 1990 and clarification letter 8 May 1991) under 1% percent asbestos and the "trace asbestos". In order to make all initial PLM reports issued from CA Labs NESHAP compliant, all <1% asbestos results (except floor tiles) will be point counted at no additional charge.

### **Oualifications**

CA Labs is accredited by the National Voluntary Accreditation Program (NVLAP) for selected test methods for airborne fiber analysis (TEM), and for bulk asbestos fiber analysis (PLM). All analysis have a college degree in a natural science (geology, biology, or environmental science) or are recognized by a state professional board in one these disciplines .Extensive in-house training programs are used to augment education background of the analyst. The group leader of polarized light has received supplemental McCrone Research training for asbestos identification. This report is not covered by the scope of AIHA accreditation. Analysis performed at CA Labs, LLC 12232 Industriplex, Suite 32 Baton Rouge, LA 70809.

Dedicated to Quality

### CA Labs, L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 CDPHE #AL-18111 LELAP #03069

### Overview of Project Sample Material Containing Asbestos

Customer Pro	iect:	2844 Patterson Road		CA Labs Project #: CBR24010361
Sample #	Layer #	Analysts Physical Description of Subsample	Asbestos type / calibrated visual estimate percent	List of Affected Building Material Types
15	15-2	Gray Plaster	2% Chrysotile	Gray Plaster Brown Floor Tile Black Mastic
16	16-2	Gray Plaster	2% Chrysotile	Gray Felt White Textured Surfacing
21	21-1	Brown Floor Tile	4% Chrysotile	_
	21-2	Black Mastic	6% Chrysotile	<del></del>
22	22-1	Brown Floor Tile	4% Chrysotile	_
	22-2	Black Mastic	6% Chrysotile	<del></del>
23	23-1	Gray Felt	70% Chrysotile	<del>-</del>
24	24-1	Gray Felt	70% Chrysotile	_

### Glossary of abbreviations (non-asbestos fibers and non-fibrous minerals):

ca - carbonate pe - perlite
gypsum - gypsum qu - quartz
bi - binder
or - organic
ma - matrix
mi - mica
ve - vermiculite
ot - other

pe - perlite fg - fiberglass
qu - quartz mw - mineral wool
wo - wollastinite
ta - talc
sy - synthetic
ce - cellulose
br - brucite
ka - kaolin (clay)

pa - palygorskite (clay)

This report relates to the items tested. This report is not to be used by the customer to claim product certification, approval or endorsement by NVLAP, NIST, AlHA LAP, LLC, or any other agency of the federal government. This report may not be reproduced except in full without written permission from CA Labs. These results are submitted pursuant to CA Labs current terms and sale, condition of sale, including the company's standard warranty and limitations of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, CA Labs will store the samples for a period of ninety (90) days before discarding. A shipping or handling fee may be assessed for the return of any samples.

Dedicated to Quality

### CA Labs, L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 CDPHE #AL-18111 LELAP #03069

### Overview of Project Sample Material Containing Asbestos

Customer Project:	2844 Patterson Road		CA Labs Project #:	CBR24010361
Sample # Layer #	Analysts Physical Description of Subsample	Asbestos type / calibrated visual estimate percent		ected Building ial Types

25	25-1	White Textured Surfacing	2% Chrysotile
26	26-1	White Textured Surfacing	2% Chrysotile
27	27-1	White Textured Surfacing	2% Chrysotile
31	31-1	White Textured Surfacing	3% Chrysotile
32	32-1	White Textured Surfacing	3% Chrysotile

### Glossary of abbreviations (non-asbestos fibers and non-fibrous minerals):

ca - carbonate
gypsum - gypsum
bi - binder
or - organic
ma - matrix
mi - mica
ve - vermiculite

ot - other

pe - perlite qu - quartz fg - fiberglass mw - mineral wool pa - palygorskite (clay)

wo - wollastinite
ta - talc
sy - synthetic
ce - cellulose
br - brucite
ka - kaolin (clay)

This report relates to the items tested. This report is not to be used by the customer to claim product certification, approval or endorsement by NVLAP, NIST, AIHA LAP, LLC, or any other agency of the federal government. This report may not be reproduced except in full without written permission from CA Labs. These results are submitted pursuant to CA Labs' current terms and sale, condition of sale, including the company's standard warranty and limitations of liability provisions and no responsibility or liability is assumed for the manner in which the results are used or interpreted. Unless notified in writing to return the samples covered by this report, CA Labs will store the samples for a period of ninety (90) days before discarding. A shipping or handling fee may be assessed for the return of any samples.

**Dedicated to** Quality

CA Labs. L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 **CDPHE #AL-18111** LELAP #03069

### Polarized Light Asbestiform Materials Characterization

CA Labs Project #: Attn: Doug Close **Customer Project: Customer Info:** CBR24010361 2844 Patterson Road Phase Con Environmental Consultants, LLC 2166 Peregrine Court 1/24/2024 Date: Grand Junction, CO 81507 Turnaround Time: 24 hr 1/23/2024 Samples Received: Date Of Sampling: Phone # 970-241-6480 Purchase Order #: Fax# 970-241-6584 Non-fibrous type Non-asbestos fiber Analysts Physical Description of Homo-Asbestos type / Sample # Com Layer type / percent / percent calibrated visual geneo ment Subsample estimate percent LIS (Y/N) 100% gu, ma, bi, None Detected Ν Tan Surfaced White Sealant 100% qu, ma, bi, Tan Surfaced Gray Sealant Ν None Detected 2-1 100% qu, mi, bi, None Detected Ν ca Tan Surfaced White Compound 3-1 100% qu, mi, bi, Ν None Detected ca Tan Surfaced White Compound 4-1 100% qu, mi, bi, None Detected Tan Surfaced White Compound 5-1 100% qu, mi, bi, Ν None Detected ca Tan Surfaced White Compound 6 6-1 100% qu, mi, bi, ca Tan Surfaced White Compound None Detected 7-1

> Analysis Method: Interim (40CFR Part 763 Appendix E to Subpart E) / Improved (EPA-600 / R-93/116) Preparation Method: HCL acid washing for carbonate based samples, chemical reduction for organically bound components, oil immersion for identification of asbestos types by dispersion attaining / becke line method.

ca - carbonate gypsum - gypsum

bi - binder

or - organic

ma - matrix

mi - mica ve - vermiculite ot -other pe - perlite

qu - quartz

fg - fiberglass mw - mineral wool wo - wollastinite ta - talc

sy - synthetic

ce - cellulose br - brucite ka - kaolin (clay) pa - palygorskite (clay)

Approved Signatories:

David Darby Analyst

Senior Analyst Alicia Stretz

Laboratory Director Chris Williams

1. Fire Damage significant fiber damage - reported percentages reflect unaltered fibers

2. Fire Damage no significant fiber damages effecting fibrous percentages 3, Actinolite in association with Vermiculite

4. Layer not analyzed - attached to previous positive layer and contamination is suspected

5. Not enough sample to analyze

6. Anthophyllite in association with Fibrous Talc

7. Contamination suspected from other building materials

8. Favorable scenario for water separation on vermiculite for possible analysis by another method

9. < 1% Result point counted positive

10. TEM analysis suggested

**Dedicated to** Quality

CA Labs, L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 **CDPHE #AL-18111** LELAP #03069

### Polarized Light Asbestiform Materials Characterization

CA Labs Project #: **Customer Project:** Attn: Doug Close **Customer Info:** CBR24010361 2844 Patterson Road Phase Con Environmental Consultants. LLC 2166 Peregrine Court 1/24/2024 Grand Junction, CO 81507 Date: 1/23/2024 Turnaround Time: 24 hr Samples Received: Date Of Sampling: Phone # 970-241-6480 Purchase Order #: 970-241-6584 Fax# Non-fibrous type Non-asbestos fiber Analysts Physical Description of Homo-Asbestos type / Layer Sample # Com type / percent / percent geneo calibrated visual ment Subsample estimate percent us (Y/N) None Detected 100% qu, ma, ca Gray Plaster 8 8-1 100% qu, ma, ca None Detected Gray Plaster 9-1 30% qu, ma, bi Y None Detected 70% fa Black Shingle with Tan Gravel 10 10-1 70% fg 30% qu, ma, bi Black Shingle with Tan Gravel None Detected 11 100% qu, ma, bi, Tan Surfaced White Finishing None Detected N 12 12-1 Plaster 100% qu, ma, Y None Detected pe, ca 12-2 Gray Plaster 100% qu, ma, bi, White Surfaced White None Detected ca 13-1 Compound 13

> Analysis Method: Interim (40CFR Part 763 Appendix E to Subpart E) / Improved (EPA-600 / R-93/116) Preparation Method: HCL acid washing for carbonate based samples, chemical reduction for organically bound components, oil immersion for identification of asbestos types by dispersion attaining / becke line method.

ca - carbonate gypsum - gypsum bi - binder or - organic

ma - matrix

mi - mica ve - vermiculite ot -other pe - perlite au - quartz

fa - fiberalass mw - mineral wool wo - wollastinite ta - talc sy - synthetic

ce - cellulose br - brucite ka - kaolin (clay) pa - palygorskite (clay)

Approved Signatories:

David Darby Analyst

Senior Analyst Alicia Stretz

Laboratory Director Chris Williams

Fire Damage significant fiber damage - reported percentages reflect unaltered fibers
 Fire Damage no significant fiber damages effecting fibrous percentages

<sup>3.</sup> Actinolite in association with Vermiculite

Layer not analyzed - attached to previous positive layer and contamination is suspected

<sup>5.</sup> Not enough sample to analyze

<sup>6.</sup> Anthophyllite in association with Fibrous Talc

<sup>7.</sup> Contamination suspected from other building materials

<sup>8.</sup> Favorable scenario for water separation on vermiculite for possible analysis by another method 9. < 1% Result point counted positive

<sup>10.</sup> TEM analysis suggested

**Dedicated to** Quality

CA Labs. L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 **CDPHE #AL-18111** LELAP #03069

### Polarized Light Asbestiform Materials Characterization

**Customer Info:** 

Attn: Doug Close

Phase Con Environmental Consultants, LLC

**Customer Project:** 

CA Labs Project #:

2166 Peregrine Court

Grand Junction, CO 81507

2844 Patterson Road

CBR24010361

Turnaround Time: 24 hr Samples Received: 1/24/2024

geneo

นร (Y/N) **Date Of Sampling:** 

Date:

1/23/2024

Phone # Fax# Sample # 970-241-6480 970-241-6584

Com Laver ment

Analysts Physical Description of Subsample

Asbestos type / Homocalibrated visual estimate percent Purchase Order #: Non-asbestos fiber type / percent

Non-fibrous type / percent

	13-2	White Drywall with Paper	N	None Detected	10% ce	90% qu, gy
		To a Company White Finishing				100% qu, ma, bi,
14	14-1	Tan Surfaced White Finishing Plaster	N	None Detected		ca
						100% qu, ma,
	14-2	Gray Plaster	Y	None Detected		pe, ca
		Tan Surfaced White Finishing				100% qu, ma, bi,
15	15-1	Plaster	N	None Detected		ca
	15-2	Gray Plaster	Υ	2% Chrysotile		98% qu, ma, ca
		Tan Surfaced White Finishing				100% qu, ma, bi,
16	16-1	Plaster	Ν	None Detected		ca

Analysis Method: Interim (40CFR Part 763 Appendix E to Subpart E) / Improved (EPA-600 / R-93/116) Preparation Method: HCL acid washing for carbonate based samples, chemical reduction for organically bound components, oil immersion for identification of asbestos types by dispersion attaining / becke line method.

ca - carbonate

16-2 Gray Plaster

mi - mica

fg - fiberglass

sy - synthetic

ce - cellulose

gypsum - gypsum bi - binder or - organic

ma - matrix

ve - vermiculite ot -other pe - perlite au - auartz

mw - mineral wool wo - wollastinite ta - talc

br - brucite ka - kaolin (clav)

pa - palygorskite (clay)

Approved Signatories:

David Darby

Senior Analyst Alicia Stretz

Laboratory Director Chris Williams

Chris Will

98% qu, ma, ca

3. Actinolite in association with Vermiculite

5. Not enough sample to analyze

6. Anthophyllite in association with Fibrous Talc

10. TEM analysis suggested

2% Chrysotile

Fire Damage significant fiber damage - reported percentages reflect unaltered fibers
 Fire Damage no significant fiber damages effecting fibrous percentages

<sup>4.</sup> Layer not analyzed - attached to previous positive layer and contamination is suspected

<sup>7.</sup> Contamination suspected from other building materials
8. Favorable scenario for water separation on vermiculite for possible analysis by another method

<sup>&</sup>lt; 1% Result point counted positive

Dedicated to Quality CA Labs, L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 CDPHE #AL-18111 LELAP #03069

### Polarized Light Asbestiform Materials Characterization

CA Labs Project #: **Customer Project: Customer Info:** Attn: Doug Close CBR24010361 2844 Patterson Road Phase Con Environmental Consultants, LLC 2166 Peregrine Court 1/24/2024 Grand Junction, CO 81507 Date: 1/23/2024 Turnaround Time: 24 hr Samples Received: Date Of Sampling: Phone # 970-241-6480 Purchase Order #: Fax# 970-241-6584 Non-asbestos fiber Non-fibrous type Analysts Physical Description of Homo-Asbestos type / Com Sample # Layer type / percent / percent calibrated visual Subsample geneo ment us estimate percent (Y/N) None Detected 20% ce 80% qu, ma 17 Tan Linoleum 20% ce 80% qu, ma Tan Linoleum None Detected 18 18-1 None Detected 100% qu, bi 18-2 Tan Mastic 20% qu, ma, bi 80% ce None Detected 19 19-1 Black Felt None Detected 80% ce 20% qu, ma, bi Black Felt 20 20-1 96% qu, ma, ca 21-1 Brown Floor Tile 4% Chrysotile 21 94% qu, bi 6% Chrysotile 21-2 Black Mastic

Analysis Method: Interim (40CFR Part 763 Appendix E to Subpart E) / Improved (EPA-600 / R-93/116)
Preparation Method: HCL acid washing for carbonate based samples, chemical reduction for organically bound components, oil immersion for identification of asbestos types by dispersion attaining / becke line method.

ca - carbonate

ate mi - mica

fg - fiberglass

sv - synthetic

ce - cellulose

gypsum - gypsum bi - binder

ve - vermiculite ot -other mw - mineral wool
wo - wollastinite

br - brucite ka - kaolin (clay)

or - organic ma - matrix pe - perlite qu - quartz wo - wollasi ta - talc pa - palygorskite (clay)

Approved Signatories:

David Darby Analyst

Senior Analyst Alicia Stretz Laboratory Director Chris Williams

Chris Oll

3. Actinolite in association with Vermiculite

5. Not enough sample to analyze

Fire Damage significant fiber damage - reported percentages reflect unaltered fibers
 Fire Damage no significant fiber damages effecting fibrous percentages

Layer not analyzed - attached to previous positive layer and contamination is suspected

<sup>6.</sup> Anthophyllite in association with Fibrous Talc

<sup>7.</sup> Contamination suspected from other building materials8. Favorable scenario for water separation on vermiculite for possible analysis by another method

Pavorable scenario for water separati
 Separation of the s

 <sup>1%</sup> Hesuit point counte
 TEM analysis suggested

**Dedicated to** Quality

**Customer Info:** 

Sample #

CA Labs, L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 **CDPHE #AL-18111** LELAP #03069

### Polarized Light Asbestiform Materials Characterization

us

(Y/N)

Phase Con Environmental Consultants, LLC

Attn: Doug Close

2166 Peregrine Court Grand Junction, CO 81507 **Customer Project:** 

2844 Patterson Road

Turnaround Time: 24 hr

CA Labs Project #: CBR24010361

Date: Samples Received:

Date Of Sampling:

1/24/2024 1/23/2024

970-241-6480 Phone # Fax#

Com

ment

970-241-6584

Laver

Analysts Physical Description of Subsample

Asbestos type / Homogeneo calibrated visual estimate percent Purchase Order #: Non-asbestos fiber type / percent

Non-fibrous type / percent

22-1 Brown Floor Tile 4% Chrysotile 96% qu, ma, ca 22 94% au, bi 6% Chrysotile Black Mastic 70% Chrysotile 10% ce 20% qu, ma Gray Felt 23 23-1 70% Chrysotile 10% ce 20% qu, ma 24 24-1 Gray Felt 98% qu, mi, bi, 2% Chrysotile White Textured Surfacing Ν 25 25-1 98% qu, mi, bi, Ν 2% Chrysotile ca 26-1 White Textured Surfacing 26 98% qu, mi, bi, Ν 2% Chrysotile ca White Textured Surfacing 27

> Analysis Method: Interim (40CFR Part 763 Appendix E to Subpart E) / Improved (EPA-600 / R-93/116) Preparation Method: HCL acid washing for carbonate based samples, chemical reduction for organically bound components, oil immersion for identification of asbestos types by dispersion attaining / becke line method.

ca - carbonate gypsum - gypsum bi - binder

or - organic ma - matrix

mi - mica ve - vermiculite ot -other pe - perlite

qu - quartz

fg - fiberglass mw - mineral wool wo - wollastinite

ta - talc

sy - synthetic

ce - cellulose br - brucite

ka - kaolin (clay) pa - palygorskite (clay)

Approved Signatories:

David Darby

Analyst

Senior Analyst Alicia Stretz

Laboratory Director Chris Williams

<sup>1.</sup> Fire Damage significant fiber damage - reported percentages reflect unaltered fiber

Fire Damage no significant fiber damages effecting fibrous percentages
 Actinolite in association with Vermiculite

<sup>4.</sup> Layer not analyzed: - attached to previous positive layer and contamination is suspected

<sup>5.</sup> Not enough sample to analyze

<sup>6.</sup> Anthophyllite in association with Fibrous Talc

<sup>7.</sup> Contamination suspected from other building materials

<sup>8.</sup> Favorable scenario for water separation on vermiculite for possible analysis by another method

<sup>&</sup>lt; 1% Result point counted positive

<sup>10.</sup> TEM analysis suggested

**Dedicated to** Quality

CA Labs, L.L.C.

12232 Industriplex, Suite 32 Baton Rouge, LA 70809 Phone 225-751-5632 Fax 225-751-5634



NVLAP #200772-0 TDSHS #300370 **CDPHE #AL-18111** LELAP #03069

### Polarized Light Asbestiform Materials Characterization

**Customer Info:** 

Attn: Doug Close

**Customer Project:** 

CA Labs Project #:

Phase Con Environmental Consultants, LLC

Com

2844 Patterson Road

CBR24010361

2166 Peregrine Court Grand Junction, CO 81507

Date:

1/24/2024

Phone #

970-241-6480

Turnaround Time: 24 hr

Samples Received: Date Of Sampling: Purchase Order #:

1/23/2024

Fax# Sample #

28

30

970-241-6584

Analysts Physical Description of Subsample

White Surfaced Gray Plaster

White Surfaced Gray Plaster

White Drywall with Paper

White Drywall with Paper

Asbestos type / calibrated visual estimate percent

Non-asbestos fiber type / percent

Non-fibrous type / percent

ment

Layer

geneo us (Y/N)

Ν

Ν

Homo-

100% qu, ma, bi,

29 29-1 Grav Plaster

30-1

31-2

None Detected

None Detected

100% qu, ma, ca 100% qu, ma, bi,

ca

ca

White Textured Surfacing 31

3% Chrysotile

None Detected

None Detected

None Detected

10% ce

90% qu, gy

97% qu, mi, bi,

97% qu, mi, bi,

White Textured Surfacing 32 32-1

Ν 3% Chrysotile

10% ce

90% qu, gy

Analysis Method: Interim (40CFR Part 763 Appendix E to Subpart E) / Improved (EPA-600 / R-93/116) Preparation Method: HCL acid washing for carbonate based samples, chemical reduction for organically bound components, oil immersion for identification of asbestos types by dispersion attaining / becke line method.

ca - carbonate

mi - mica ve - vermiculite fa - fiberalass

ce - cellulose br - brucite

gypsum - gypsum bi - binder or - organic ma - matrix

ot -other pe - perlite qu - quartz mw - mineral wool wo - wollastinite sy - synthetic

ka - kaolin (clay) pa - palygorskite (clay)

Approved Signatories:

David Darby Analyst

Senior Analyst Alicia Stretz

Laboratory Director Chris Williams

<sup>1.</sup> Fire Damage significant fiber damage - reported percentages reflect unaltered fiber

Fire Damage no significant fiber damages effecting fibrous percentages
 Actinolite in association with Vermiculite

<sup>4.</sup> Layer not analyzed - attached to previous positive layer and contamination is suspected

<sup>5.</sup> Not enough sample to analyze

<sup>6.</sup> Anthophyllite in association with Fibrous Talc

<sup>7.</sup> Contamination suspected from other building materials

<sup>8.</sup> Favorable scenario for water separation on vermiculite for possible analysis by another method

<sup>9. &</sup>lt; 1% Result point counted positive

<sup>10.</sup> TEM analysis suggested



C.A. Labs, LLC. 12232 Industriplex Suite 32 Baton Rouge, LA 70809


Phone: 225-751-5632 Fax: 225-751-5634 Mobile: 225-993-3471

### Chain of Custody

Client Name:	Litatio: Plase Coll Litation Herical Constitution College			abs job# .	CBR 🥽	40103	6	
Client Address:	2166 Peregrine C	ourt	Billin	ng Address:	Same			
	Grand Junction, C		(if di	fferent)				
	0,0,10	•	·· · · · · · · · · · · · · · · · · · ·					
phone number:	970-260-3341							
fax number:	888-966-0231	<u> </u>	Send	Reports to:	Douglas Cli	ose	3 /	_ 1
Project Number			Proje	ect Name:	784	4 10	itterson	Road
110,0001			Repo	rts Results		p <sup>*</sup>		
Contact:	Douglas Close			VIA:	EMAIL_/	FAX	_VERBAL	
Total # Sampl	ec Submitted.	Total # Sa	mples to be	e Analyzed	· N	Iaterial M	atrix:	
Idla: # Gampi	32		32	•	I	ir (Bulk)	Water	
<u> </u>	20							1
Asbestos:		please ca	all ahead for	availability of	all rush and	i/or after ho	urs samples.	<del>.</del>
TEM	TA Time	PL		TA Time		l/IAQ	TA Time	
Circle analysis and TA Lin	iz	Circle analysis an	d TA time	2 hour	Allergen	Particle:	2 hour	
AHERA	4 hour	Improved		4 hour	tape/bull	c/swab	4 hour	
EPA Level II	8 hour	Interim		8 hour	Cyclex-d cassettes		8 hour	
Drinking Water	r 16 hour			16 hour	Air-o-cell cassettes		16 hour	į
Wipe	24 hour	AHERA)		24 hour	Anderson cultures 24 hour		24 hour	
Micro-vac	2 days			2 days			2 days	
NIOSH 7402	3 days	Point Cou	nt -	3 days	Bacteria	cultures	3 days	
Chatfield Bulk	5 days	(NESHAP	S)	5 days	PCM: NI	OSH 7400	5-10 days	]
<u> </u>								
-	Paint Chips	Soil	Air	Wip	es Wa	stewater	TCLP	]
Matrix:					days 5 days		6-10 days	4
TA Time:	8 hour	1 day	2 days	J Jua.	ys	o aays	010 11130	<u>.l</u>
Cample Information	n							
Sample Information		ample Locati	on:	Sample D	ate/Time:	Sample	Volume (L)	7
1					,			1
								1
thru				· ·				]
77		_						_
20								j
\data\wordpro\formsiC	ChainofCustody.lwp	Revision 2	3/12/01	Page 1				16-10
Custody Informat Samples relinqui	shed:	nature / Date / T		OO Samples receive		Nol:	- RSCOLLE	10:30 1/23/24
Samples relinqui	- //	.t		Samples receiv	eđ:			
oampies i cintilui		nature / Date / T		-		Signature / D	ate / Time	_
	01.5	, <del>-</del> /						

٠.







Colorado Department
of Public Health
and Environment

### ASBESTOS \*\* CERTIFICATION\*

This certifies that

### Douglas A. Close

Certification No.: 2930

has met the requirements of 25-7-507. C.R.S. and Air Quality Control.
Commission Regulation No. 8, Part B, and is hereby certified by the
state of Colorado in the following discipline:

### Project Designer\*

Issued: / October 27, 2023

Expires: October 25, 2024

\*This certificate is valid only with the possession of a current Division-approved training course certification in the discipling specified above:

Authorized APCD Representative

SEAL



Colorado Department of Public Health' and Environment !

### ASBESTOS \* CERTIFICATION\*

This certifies that

### Douglas A. Close

Certification No.: 2930

has met the requirements of 25-7-507, C.R.S. and Air Quality Control Commission Regulation No. 8, Part B, and is hereby certified by the state of Colorado in the following discipline.

### Air Monitoring Specialist\*

Issued: October 27, 2023

Expires: October 25, 2024

\* This certificate is valid only with the possession of a current Division approved training course certification in the discipline specified above.

Authorized APCD Representative

SEAL



### Colorado Department and Environment of Public Health

# ASBESTOS CONSULTING FIRM

This certifies that


# Phase Con Environmental Consultants, LLC

Registration No.: ACF - 14801

Commission Regulation No. 8, Part B, and is hereby authorized to perform asbestos consulting activities as required under Regulation No 8, Part B, in the state of Colorado. has met the registration requirements of 25-7-507, C.R.S. and the Air Quality Control

January 30, 2023 Issued:

January 30, 2024 Expires:





Colorado Department of Public Health and Environment

# ASBESTOS LABORATORY

This certifies that

## CA Labs, LLC

Registration No.: AL - 27819

has met the registration requirements of 25-7-507, C.R.S. and the Arr Quality Control Commission Regulation No. 8, Part B, and is hereby authorized to perform asbestos laboratory testing activities, as required by Regulation No. 8, Part B, in the state of Colorado.

Issued: April 28, 2023

Expires; May 12, 2024

Authorized APCD Representative

## National Institute of Standards and Technology United States Department of Commerce



# Certificate of Accreditation to ISO/IEC 17025:2017

**NVLAP LAB CODE: 200772-0** 

## CA Labs L.L.C.

Baton Rouge, LA

is accredited by the National Voluntary Laboratory Accreditation Program for specific services, listed on the Scope of Accreditation, for:

# **Asbestos Fiber Analysis**

This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2017. management system (refer to joint ISO-ILAC-IAF Communique dated January 2009)

2024-01-01 through 2024-12-31

Effective Dates





For the National Voluntary Laboratory Accreditation Program