

CDH72WHI

TYPE OF RECORD: PERMANENT
CATEGORY OF RECORD: **UMTRA (REPORT)**
NAME OF CONTRACTOR: COLORADO DEPARTMENT OF HEALTH
SUBJECT/PROJECT: RADIATION SURVEY
STREET ADDRESS/PARCEL/SUBDIVISION: 521 WHITE AVENUE MESA
COUNTY LIBRARY - LOCATION 1313 - (NOW PART OF CITY HALL)
PARCEL NO.: 2945-143-08-941
CITY DEPARTMENT: PUBLIC WORKS
YEAR: 1972
EXPIRATION DATE: NONE
DESTRUCTION DATE: NONE



Re: Location 1313
 521 White Avenue
 Grand Junction, CO 81501

COLORADO

HEALTH

4210 EAST 11TH AVENUE • DENVER, COLORADO 80220 • PHONE 388-6111

R. L. CLEERE, M.D., M.P.H., DIRECTOR

May 18, 1972

RECEIVED MAY 23 1972

01019
 Mesa County Commissioners
 P.O. Box 897
 Grand Junction, CO 81501

L. AUBERT	
E. LAMM	
J. WADLOW	

We are pleased to report to you that no indication of uranium mill tailings was found either under or against the structure in our survey of your property.

We would like, however, to inform you that tailings have been located on your property as indicated on the attached survey report. This location does not present any problem of radiation exposure to you at this time. If, at a later date, construction is considered over the indicated area, we recommend corrective action be considered.

Our survey in Grand Junction is continuing. Because of the time-consuming nature of this evaluation, we are not able to notify all property owners simultaneously of our findings. Thus, some of your friends and neighbors whose homes we have evaluated may not receive notification letters, indicating either the presence or absence of tailings, for some months.

We appreciate your cooperation in this survey. If you have any questions, please feel free to call our Grand Junction office at 243-7830.

Sincerely,

R. L. Cleere

COLORADO DEPARTMENT OF HEALTH

OFFICIAL SURVEY REPORT

Property Address 521 White Avenue - Grand Junction, CO 81501

Property Owner Mesa County

Owner Address (if different than above) c/o Mesa County Commissioners
P.O. Box 897, Grand Junction

Date of Report May 18, 1972

I. No indication of uranium mill tailings has been found on this property. See Item III below.

Uranium Mill tailings are indicated to be on this property and are located:

in yard only (CITY SIDEWALK)

under or around garage or patio only

under or around the house

under or around the house and in yard

under or around the building (business, church, etc.)

II. RESULTS OF THE RADIATION SURVEY IN THE STRUCTURE INDICATE:

Average gamma radiation exposure rate of _____ mR/hr.
This compares with the Surgeon General's recommendation for corrective action at 0.05 mR/hr.

Average radon daughter concentration of _____ WL.
This compares with the Surgeon General's recommendation for corrective action at 0.010 WL.

The presence of uranium tailings under occupied areas necessitating corrective action.

III. RECOMMENDATION:

You are advised to remove tailings if feasible or take other means of corrective action to reduce the radiation exposure.