

CITY OF GRAND JUNCTION, COLORADO

MEMORANDUM

Reply Requested

Yes No

Date

October 27, 1981

To: (From:) Steve Hansen

From: (To:) Ralph Sterry

Re: Additional Problem Areas in Central Grand Valley Sewer Systems

1. 29 Road between D $\frac{1}{2}$ Road and I-70 Bypass line is overloaded and manhole at D&RG RR tracks is buried.
2. 30 Road and Hill Ct. excessive infiltration.
3. 31 Road and D Road line is overloaded.
4. 29 Road and Florida Dr., no manhole at end of sewer
5. C $\frac{1}{2}$ Road and 27 $\frac{1}{2}$ to 29 Road, line is overloaded.
6. 532- 29 Road, building on top of sewer line
7. 29 Road & D $\frac{1}{2}$, line is overloaded and manhole is in bad condition.
8. 30 Road and E Road to 30 $\frac{1}{4}$ and E Road, manholes are buried.
9. D $\frac{1}{2}$ and 30 Road east, map does not show new manholes.
10. 2972 D $\frac{1}{2}$ Road, line is overloaded and manhole is in bad condition.
11. 3007 Hill Ct., pipe is not cut out of manhole, water is standing in same manhole.
12. East of 30 Road on north side of Grand Valley Canal, apparent infiltration and manholes on east end of line where line turns northeast are under water. Check on line per sheet 11-11a-12, also check sheet 63-64.
13. 532 Teco, south of 533 Dodge, manhole buried.
14. 29 Road from Grand Valley Canal south, the line is overloaded or appears to be.