OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

# Architectural Inventory Form

1 of 4

	ial eligibility determination HP use only)
Date	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District
	Noncontributing to eligible NR District

<b>I.</b> I	iden	tification	
	1.	Resource number:	5ME.14624
	2.	Temporary resource number:_	1732.EIGT
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	1732 N. 18th Street
	8.	Owner name and address:	Beverly A Mcpeek
			Po Box 871071 Wasilla, AK 99687-1071
11.	. Geographic Information		
	9.	P.M. <u>Ute Principal Meridian</u>	Township 1 South Range 1 West
SE_1/4 of NE_1/4 of NE_1/4 of SW_1/4 of section 12  10. UTM reference  Zone 1 2; 7 1 2 4 3 8 mE 4 3 2 8 9 0 1 r  11. USGS quad name: Grand Junction Quadrangle  Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate is  12. Lot(s): 37 Block: 2			of <u>SW</u> 1/4 of section <u>12</u>
			3 8 mE 4 3 2 8 9 0 1 mN
			unction Quadrangle
			ale: 7.5' X 15' Attach photo copy of appropriate map section.
			+10
		Addition: Elmwood Plaza Amen	dment Year of Addition: 1946
13. Boundary Description and Justification: Legal description of the site is: Lot 37 Blk 2			fication: Legal description of the site is: Lot 37 Blk 2
		Elmwood Plaza Refile Sec 12 1s	s 1w
Assessors Office Parcel ID # 2945-123-09-014			45-123-09-014
		This description was chosen as	the most specific and customary description of the site.
		chitectural Description	Barton and Blanch
14. Building plan (footprint, shape): Rectangular Plan			
			x Width_ <u>24'</u>
16. Number of stories: 1			
			s) (enter no more than two): Wood Horizontal Siding
18. Roof configuration: (enter no more than one): Hipped Roof  19. Primary external roof material (enter no more than one): Asphalt Roof			
	20. Special features (enter all that apply): none		

Resource Number: 5ME.14624
Temporary Resource Number: 1732.EIGT

V.

#### Architectural Inventory Form (page 2 of 4)

	21.	. General architectural desc	ription: This is a small wood frame house with a moderately		
		pitched hipped roof. The h	ipped roof has a short ridge that runs northwest to southeast.		
		The principal façade faces	northwest. A front gable faces the street and shares the		
		southwest roof plane with t	the hipped roof. The principal façade has a single wall plane		
		and the door is located nea	ar the center just under the front gable. To the right of the door		
	is a picture window with narrow four paned windows flanking each side. This window fill				
		the wall surface to the corner. A single double hung is located around the corner, on the			
		corner. The remainder of the wall to the left of the door has a single double hung window			
		centered on the wall plane. The house sits on a concrete foundation and basement			
		windows are located on the perimeter. A vent is located in the peak of the hip on the			
		main roof plane. The remainder of the southwest wall has one larger and one smaller			
		double hung. The double hungs have a single horizontal muntin in both sashes.			
	22. Architectural style/building type: Hipped Box				
	23.	Landscaping or special set	ting features: The house is located on a cul-de-sac that sits off		
	the main street grid. Several shrubs are located around the perimeter of the house.				
	24.	Associated buildings, featu	res, or objects: A small shed outbuilding is located at the rear.		
IV.	Ar	chitectural History			
	25.	Date of Construction: Estim	ate: 1948 or earlier Actual:		
		Source of information:	Mesa County Assessors Office		
	26.	Architect:	unknown		
		Source of information:			
	27.	Builder/Contractor:	unknown		
		Source of information:			
	28.	Original owner:	Don Conley		
		Source of information:	1951 Polk Directory		
	29.	Construction history (includ	e description and dates of major additions, alterations, or		
		demolitions):	Early photo shows exposed rafter tails, multi-paned double		
		hung windows and a deep	skirt board. Dates of material and detail alterations unknown.		
	30.	Original location X	_MovedDate of move(s):		
V.	His	torical Associations			
	31.	Original use(s):	Domestic, Single Dwelling		
	32.	Intermediate use(s):			
	33.	Current use(s):	Domestic, Single Dwelling		
	34	Site type(s):	Residential Neighborhood		

Resource Number:	5ME.14624
Temporary Resource Numb	er: 1732.EIGT

### Architectural Inventory Form (page 3 of 4)

	35.	Historical background: <u>Don Conley is shown as owner in the 1951 directory. This is</u>
		the first instance of this address in the available directories. Ray M. Green is shown as
		owner in 1955 and 1956 directories. This building is part of Elmwood Plaza. The
		subdivision was created in 1946 from the larger Grandview Subdivision, whose owners
		are shown as Ira G. and Thelma L. Carpenter, Forrest M. and Mary J. Cochran, George
		M. and Thelma E. Saunders, and Adie Russell Maynard.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		<u>Archives; Polk Directories</u> 1951, 1955, 1956, 1957
/1.	Sig	gnificance
	37.	Local landmark designation: Yes No _X Date of designation:
		Designating authority:
	38.	Applicable National Register Criteria:
		X A. Associated with events that have made a significant contribution to the broad pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
	39.	Area(s) of significance: Architecture, Community Development and Planning
	40.	Period of significance: 1948 or earlier: 1943 to 1957 Uranium Boom
41. Level of significance: National State LocalX_		
	42.	Statement of significance: The development in this area is a direct result of the nation's
		involvement in WWII and the drive for the development of nuclear weapons. The
		discovery of significant sources of Uranium in the region initiated development in Grand
		Junction that supported both the mining of the materials and the administration of
		programs related to the development of weapons. The building types, materials and
		neighborhood layout are all indicative of the national trends which were driven by the
		proliferation of the automobile and the enormous demand for single family homes.
		House designs departed from the romantic and revival styles that were prevalent in the
		earlier part of the 20th century and took on a California inspired design that was
		characterized by simple horizontally proportioned forms. Houses were typically mass


Resource Number:		5ME.14624
Temporary Resource	Number:	1732.EIGT

#### Architectural Inventory Form (page 4 of 4)

	produced on previously undeveloped tracts of land at the periphery of earlier		
	development. These groups of houses were typically based on one or two plan types		
	with a limited number of roof and exterior finish variations, further reinforcing the		
	characteristics of mass production.		
4	43. Assessment of historic physical integrity related to significance: Some original details		
	have been lost, integrity is somewhat compromised.		
VII.	National Register Eligibility Assessment		
4	4. National Register eligibility field assessment:		
	Eligible Not Eligible _X Need Data		
4	5. Is there National Register district potential? Yes No _X	Discuss:	
	If there is National Register district potential, is this building	g: Contributing	
		Noncontributing	
4	6. If the building is in existing National Register district, is it:	Contributing	
		Noncontributing	
VIII.	Recording Information		
4	7. Photograph numbers: Roll # 5 Frame # 10		
	Negatives filed at: City of Grand Junction Planning Dept.  48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005		
4			
5	0. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia	a Herron	
5	1. Organization: Reid Architects, Inc.		
5	2. Address: PO Box 1303 Aspen, Colorado 81612	Well-red.	
53	3. Phone number(s): <u>970 920 9225</u>		

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




## 1732 N.18th Street



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



#### GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14624

1732 N. 18th Street

Roll #5 Frame #10

Looking northeast

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN- 1 5882 002927

010

share

57907