OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

	ial eligibility determination
	IP use only)
ate .	Initials
_	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District
	Noncontributing to eligible NR District

1. 1	den	tification	
	1.	Resource number:	5ME.14640
	2.	Temporary resource number:_	1443.ELM
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	1443 Elm Ave.
	8.	Owner name and address:	Ashlynn Johnson
		100000	1443 Elm Ave Grand Junction, CO 81501-6335
11.	Geo	ographic Information	
			Township_1 South Range_1 West
NE 1/4 of NE 1/4 of SW 1/4 of section 12			
	10.	UTM reference	
		Zone 1 2; 7 1 2	0 9 3 mE <u>4 3 2 8 6 1 1 m</u> N
11. USGS quad name: Grand Junction Quadrangle			unction Quadrangle
		Year: 1962 rev.1973 Map sc	ale: 7.5'_X 15' Attach photo copy of appropriate map section.
	12.	Lot(s): _7 Block:	
		Addition: Grandview Subdivision	on Year of Addition: 1905
	13.	Boundary Description and Just	ification: <u>Legal description of the site is: Beg 10ft S + 5ft W</u>
		of NE Cor Lot 7 Grandview Sub	odivision S59.6ft W 112.37ft N 59.6ft E To Beg
		Assessors Office Parcel ID # 29	45-123-00-020
		This description was chosen as	the most specific and customary description of the site.
111.	Arc	chitectural Description	
	14.	Building plan (footprint, shape)	: Irregular Plan
	15.	Dimensions in feet: Length_29	<u>'x Width_ 56'</u>
	16.	Number of stories: 1	1000000
	17.	Primary external wall material(s) (enter no more than two): Brick
	18.	Roof configuration: (enter no m	ore than one): Hipped Roof
	19.	Primary external roof material	(enter no more than one): Asphalt Roof
	20.	Special features (enter all that	apply): Porch, Chimney, Attached Garage

Resource Number:	5ME.14640
Temporary Resource Number:	1443.ELM

Architectural Inventory Form (page 2 of 4)

	21.	. General architectural desc	ription: This is a horizontally proportioned brick house with an	
		ell shaped primary form. 1	The main ridge runs east/west, with a small ridge running north	
		south. The main entry doo	r, with side light, is located in the corner of the ell, under a	
		cantilevered section of the	front facing section of the hipped roof. A wide picture window	
		with a casement on either	side, sits adjacent to the door on the right. The casements	
		have two horizontal muntin	s and a fixed unit above. On the left side of the façade a set of	
		three casement style windo	ows sit on the projecting face of wall. Two similar window	
		groups are located on either	er end of the east facing wall. These metal casements also	
		have two horizontal muntin	s in each sash. A garage with a flat roof and vertical wood	
		siding extends off the west	side with a single car garage door facing the street. A brick	
chimney sits on the rear of the house. A band of contrasting brick runs as			the house. A band of contrasting brick runs around the	
		perimeter of the house at the	he height of the picture window sill.	
	22.	Architectural style/building	type: Ranch Type	
	23.	Landscaping or special set	ting features: The house sits on a corner lot with few plantings.	
The yard is predominantly lawn. 24. Associated buildings, features, or objects: none seen			lawn.	
			res, or objects: none seen	
IV.	Ar	chitectural History		
	25.	Date of Construction: Estim	ate: 1951 Actual:	
		Source of information:	Mesa County Assessors Office	
	26.	Architect:	unknown	
		Source of information:		
	27.	Builder/Contractor:	unknown	
		Source of information:		
	28.	Original owner:	unknown	
		Source of information:	- A Million cont	
	29.	Construction history (include description and dates of major additions, alterations, or		
		demolitions):	Addition of garage and possibly chimney; dates unknown	
	30.		_MovedDate of move(s):	
v.	His	torical Associations		
	31.	Original use(s):	Domestic, Single Dwelling	
		Intermediate use(s):		
		Current use(s):		
			Residential Neighborhood	

Resource Number:		5ME.14640
Temporary Resource	Number:	1443.ELM

Architectural Inventory Form (page 3 of 4)

	35.	Historical background: Orville K. Lybarger is shown as owner in the 1951 and 1955		
	directories. Maurice R. Doyle is shown as occupant in the 1956 and 1957 directories.			
	This building is part of the Grandview Subdivision. The subdivision was created in 1905			
		by the Grand Junction Land & Investment Company. This investment group was formed		
		by R.J. Bolles, as President, Arlie B. Yeaton and James Ramey. Later the subdivision		
	was divided into smaller parcels.			
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado		
		Archives; Polk Directories 1951, 1955, 1956, 1957		
VI.	Sig	gnificance		
	37.	Local landmark designation: Yes No _X Date of designation:		
		Designating authority:		
	38.	Applicable National Register Criteria:		
		X A. Associated with events that have made a significant contribution to the broad		
		pattern of our history;		
		B. Associated with the lives of persons significant in our past;		
	X C. Embodies the distinctive characteristics of a type, period, or method of			
		construction, or represents the work of a master, or that possess high artistic		
	values, or represents a significant and distinguishable entity whose components			
	may lack individual distinction; or			
	D. Has yielded, or may be likely to yield, information important in history or			
		prehistory.		
		Qualifies under Criteria Considerations A through G (see Manual)		
		Does not meet any of the above National Register criteria		
	39.	Area(s) of significance: Architecture, Community Development and Planning		
		Period of significance: 1950; 1943 to 1957 Uranium Boom		
		Level of significance: National State LocalX		
	42.	Statement of significance: The development in this area is a direct result of the nation's		
		involvement in WWII and the drive for the development of nuclear weapons. The		
		discovery of significant sources of Uranium in the region initiated development in Grand		
	Junction that supported both the mining of the materials and the administration of			
		programs related to the development of weapons. The building types, materials and		
		neighborhood layout are all indicative of the national trends which were driven by the		
		proliferation of the automobile and the enormous demand for single family homes.		
		House designs departed from the romantic and revival styles that were prevalent in the		
		earlier part of the 20th century and took on a California inspired design that was		
		characterized by simple horizontally proportioned forms. Houses were typically mass		


Resource Number:	5ME.14640
Temporary Resource Number:	1443.ELM

Architectural Inventory Form (page 4 of 4)

produced on previously undeveloped tracts of land at the periphery of earlier				
development. These groups of houses were typically based on one or two plan types				
with a limited number of roof and exterior finish variations, further reinforcing the				
characteristics of r	nass production.			
43. Assessment of historic physical integrity related to significance: The house is gener				
intact, addition of	garage has minimal impact on integrity.			
ntional Register E	ligibility Assessment			
44. National Register eligibility field assessment:				
Eligible No	t EligibleX Need Data			
ls there National F	legister district potential? Yes No _X	Discuss:		
If there is National	Register district potential, is this building:	Contributing		
	Noncontributing			
If the building is in	existing National Register district, is it:	Contributing		
		Noncontributing		
ecording Informa	tion			
47. Photograph numbers: Roll # 5 Frame # 30				
Negatives filed at: <u>City of Grand Junction Planning Dept.</u> 48. Report title: <u>Grand Junction Phase 3 Survey</u> 49. Date(s): <u>March 2005</u>				
				Recorder(s):
-				
Address:	PO Box 1303 Aspen, Colorado 81612			
Phone number(s):	970 920 9225	24 2-34-1		
	development. The with a limited num characteristics of response to hist intact, addition of continuate, addition of continuate, addition of continuate the ligible Not lightly additional formation of the cording in lightly additional formation of the cording in the cordinal cordina	development. These groups of houses were typically based or with a limited number of roof and exterior finish variations, fur characteristics of mass production. Assessment of historic physical integrity related to significance intact, addition of garage has minimal impact on integrity. Itional Register Eligibility Assessment National Register eligibility field assessment: Eligible Not EligibleX Need Data ls there National Register district potential? Yes NoX lf there is National Register district potential, is this building: If the building is in existing National Register district, is it: Pecording Information Photograph numbers: Roll # 5 Frame # 30 Negatives filed at: City of Grand Junction Planning Dept. Report title:Grand Junction Phase 3 Survey 49. Date(s): M Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H Organization: Reid Architects, Inc. Address: PO Box 1303 Aspen, Colorado 81612		

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1443 Elm Ave.



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004

5ME.14640 1443 Elm Ave.
Roll # 5 Frame # 30
Looking southeast
Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN- 1 5882 002927

030

share

57927

