OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Offic	cial eligibility determination
(OAI	HP use only)
Date	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
1 2	Contributes to eligible NR District
	The state of the s

		1 07 4		Noncontributing to eligible NR District
I. I	lden	tification		
	1.	Resource number:	5ME.14768	
	2.	Temporary resource number:	530.ORC	11, 477
	3.	County:	Mesa	- Long Sall
	4.	City:	Grand Junct	ion
	5.	Historic building name:	n/a	16-
	6.	Current building name:	n/a	
	7.	Building address:	530 Orchard	Ave.
	8.	Owner name and address:	James S Ha	drath
			530 Orchard	Ave Grand Junction, CO 81501-2162
II.	Ged	ographic Information		
	9.	P.M. <u>Ute Principal Meridian</u>	Townshi	o <u>1 South</u> Range <u>1 West</u>
		_SW_1/4 of_SE_1/4 of_SE_1/4	of_ <u>NW_</u> 1/4 o	f section_11
	10.	UTM reference		
		Zone <u>1 2; 7 1 0</u>	<u>7 2 8 m</u>	E <u>4 3 2 9 0 1 6</u> mN
	11.	USGS quad name: Grand J	unction Quad	angle
		Year: 1962 rev.1973 Map so	ale: 7.5'_X_	15' Attach photo copy of appropriate map section.
	12.	Lot(s): _15 Block:_	7	
		Addition: Bookcliff Park		Year of Addition:_1946
13. Boundary Description and Justification: Legal description of the site is: Lot 15 Bl		I description of the site is: Lot 15 Blk 7		
Bookeliff Park				
	Assessors Office Parcel ID # 2945-112-06-015			5
		This description was chosen as	the most spe	cific and customary description of the site.
Ш.	Arc	chitectural Description		
	14.	Building plan (footprint, shape)	:_irregular_pi	an
	15.	Dimensions in feet: Length 24		x Width_42'
		·		
				ore than two): Aluminum
		Roof configuration: (enter no m		
		_		e than one): Asphalt Roof
		Special features (enter all that		

Resource Number:		5ME.14768
Temporary Resource	Number:	530.ORC

V.

Architectural Inventory Form (page 2 of 4)

	21.	. General architectural desc	ription: This is a simple wood frame house with a series of		
		additive volumes. The side	e gable roof runs east/west and the principal façade faces		
		south. The main entry doo	r is located near the east end of the façade with a large		
		horizontally proportioned v	vindow to the left. The large window has a casement style		
		window on each side. The	window and door are covered by a slightly extended roof		
		pported by three diagonal braces which run from the base of			
	of the overhang. Three horizontal boards run to the wall,				
equally dividing the triangle created by the braces. The remainder of the façad					
		double hung window and a	small rectangular window equally arranged on the wall plane.		
	The east side has a pair of double hungs and a single smaller unit near the center				
	wall. A stone planter runs across the façade from the landing at the door to the west				
		of the large window. A she	ed addition extends off the rear for part of its length.		
	22.	. Architectural style/building	type: Ranch Type		
	23.	Landscaping or special set	ting features: the driveway runs along the east side and a		
		large street tree sits at the	edge of the yard. There are a few shrubs at the house,		
		otherwise the yard is predo	ominantly lawn.		
	24.	Associated buildings, featu	res, or objects: A front gable two car garage is located at the		
	rear of the house.				
IV.	Ar	chitectural History			
IV.		·	ate:		
IV.		Date of Construction: Estim	ate: 1951 Actual: Mesa County Assessors Office		
IV.	25.	Date of Construction: Estim	Mesa County Assessors Office		
IV.	25.	Date of Construction: Estim Source of information: Architect:	Mesa County Assessors Office		
IV.	25. 26.	Date of Construction: Estim Source of information: Architect:	Mesa County Assessors Office unknown		
IV.	25. 26.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor:	Mesa County Assessors Office unknown		
IV.	25.26.27.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor:	Mesa County Assessors Office unknown unknown		
IV.	25.26.27.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information:	Mesa County Assessors Office unknown unknown		
IV.	25.26.27.28.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information:	Mesa County Assessors Office unknown unknown		
IV.	25.26.27.28.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (include	Mesa County Assessors Office unknown unknown		
IV.	25.26.27.28.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (include	Mesa County Assessors Office unknown unknown unknown de description and dates of major additions, alterations, or Siding replaced, some windows replaced and openings		
IV.	25.26.27.28.29.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): altered, addition at rear; date	Mesa County Assessors Office unknown unknown unknown de description and dates of major additions, alterations, or Siding replaced, some windows replaced and openings		
IV.	25.26.27.28.29.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): altered, addition at rear; date	Mesa County Assessors Office unknown unknown unknown de description and dates of major additions, alterations, or Siding replaced, some windows replaced and openings oftes unknown.		
	25.26.27.28.29.30.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): altered, addition at rear; date	Mesa County Assessors Office unknown unknown unknown de description and dates of major additions, alterations, or Siding replaced, some windows replaced and openings oftes unknown.		
	25. 26. 27. 28. 29.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): altered, addition at rear; day Original location X	Mesa County Assessors Office unknown unknown unknown de description and dates of major additions, alterations, or Siding replaced, some windows replaced and openings oftes unknown.		
	25. 26. 27. 28. 29. 30. His	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): altered, addition at rear; day Original location X	Mesa County Assessors Office unknown unknown de description and dates of major additions, alterations, or Siding replaced, some windows replaced and openings ates unknown. Moved Date of move(s): Domestic, Single Dwelling		
	25. 26. 27. 28. 29. 30. His 31. 32.	Date of Construction: Estim Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): altered, addition at rear; dated original location X storical Associations Original use(s):	Mesa County Assessors Office unknown unknown de description and dates of major additions, alterations, or Siding replaced, some windows replaced and openings interest unknown. Moved Date of move(s): Domestic, Single Dwelling		

Resource Number:	5ME.14768_
Temporary Resource Number:	530.ORC

Architectural Inventory Form (page 3 of 4)

	35.	Historical background: The 1951 directory indicates the building was vacant. In the
		directories of 1955 and 1956 Robert J. Wright is shown as owner. In the 1957 directory
		Robert Stott is shown as occupant. This building is part of Bookcliff Park developed in
		1946. The owners were Gertrude B. Smith, Claude D. Smith later the U. S. Bank of Grand
		Junction, and Thomas L. Brownson, Mabel L. Brownson, Bruce Brownson and Mary F.
		Brownson.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories 1951, 1955, 1956, 1957
./1	C:	
VI.		gnificance
	37.	Local landmark designation: Yes No _X Date of designation: Designating authority:
	20	
	JO.	Applicable National Register Criteria:
		X A. Associated with events that have made a significant contribution to the broad pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
	39.	Area(s) of significance: Architecture, Community Development and Planning
	40.	Period of significance: 1951; 1943 to 1957 Uranium Boom
		Level of significance: National State LocalX
	42.	Statement of significance: The development in this area is a direct result of the nation's
		involvement in WWII and the drive for the development of nuclear weapons. The
		discovery of significant sources of Uranium in the region initiated development in Grand
		Junction that supported both the mining of the materials and the administration of
		programs related to the development of weapons. The building types, materials and
		neighborhood layout are all indicative of the national trends which were driven by the
		proliferation of the automobile and the enormous demand for single family homes.
		House designs departed from the romantic and revival styles that were prevalent in the
		earlier part of the 20th century and took on a California inspired design that was
		characterized by simple horizontally proportioned forms. Houses were typically mass
		produced on previously undeveloped tracts of land at the periphery of earlier

Resource N	lumber:		5ME.14768
Temporary	Resource	Number:	530.ORC

Architectural Inventory Form (page 4 of 4)

development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production. In this particular subdivision there are examples of both repetitive house types and more high style individualized houses. The curvilinear street layout is characteristic of national planning trends and is unusual in this community, where new development tended to extend the existing street grid.

43. Assessment of historic physical integrity related to significance: Siding and window alterations have impacted some of the original character defining features. Integrity has been moderately compromised. Many alterations to the principal façade have compromised the building's ability to convey its original character.

VII.	National	Register	Eligibility	Assessment
------	----------	----------	-------------	------------


National Register Eligibility Assessment	
44. National Register eligibility field assessment:	
Eligible Not EligibleX Need Data	
45. Is there National Register district potential? Yes _X_ No	
Discuss: The Bookcliff Park Subdivision lies on the periphery of	of the historic city center
and was originally established by single group of investors.	he sites were built out to
accommodate the rapid growth associated with the Uranium E	Boom over a short period of
time. The architectural styles present in the area represent a	significant concentration
and continuity of dwellings and a subtle transition of styles ov	er the building period. Few
intrusions have been made into the original neighborhood and	d it retains a high level of
integrity.	
If there is National Register district potential, is this building:	Contributing
	Noncontributing X
46. If the building is in existing National Register district, is it:	Contributing
	Noncontributing
. Recording Information	
47. Photograph numbers: Roll # 10 Frame # 22	

VIII.

Negatives filed at: City of Grand Junction Planning Dept. 48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005 Suzannah Reid, Patrick Duffield and Lydia Herron 50. Recorder(s):___ 51. Organization: Reid Architects, Inc. PO Box 1303 Aspen, Colorado 81612 52. Address: 53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

> Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




530 Orchard Ave.



North
Grand Junction, Colorado

image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14768 530 Orchard Ave. Roll # 10 Frame # 22

Looking southeast Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN+ 1 5649 002912

023 share

54637