OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

### **Architectural Inventory Form**

1 of 4

	ial eligibility determination {P use only)
3.	Initials
2	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District
	Noncontributing to eligible NR District

1. 1	den	tification	
	1.	Resource number:	5ME.14772
	2.	Temporary resource number:_	570.ORC
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	570 Orchard Ave.
	8.	Owner name and address:	Thomas W Blake
	_	Tu-	425 Ridgewood Ln Grand Junction, CO 81505-7049
II.		ographic Information	
	9.	P.M. <u>Ute Principal Meridian</u>	Township_1_South Range_1 West
			of NW 1/4 of section 11
	10.	UTM reference	
			7 9 7 mE 4 3 2 9 0 1 6 mN
	11.	USGS quad name: Grand Ju	unction Quadrangle
		· ·	ale: 7.5'_X_ 15' Attach photo copy of appropriate map section.
	12.		7
			Year of Addition: 1946
	13.	·	ification: Legal description of the site is: Lot 11 Blk 7
		Assessors Office Parcel ID # 29	45-112-06-011
		This description was chosen as	the most specific and customary description of the site.
111.	Arc	chitectural Description	
		Building plan (footprint, shape):	: Rectangular Plan
			x Width 46'
	17.		s) (enter no more than two): Asphalt Siding
			ore than one):_ Hipped Roof
		_	(enter no more than one): Asphalt Roof
	20.	Special features (enter all that a	apply):Carport, Chimney

Resource Number:	5ME.14772
Temporary Resource Number:	570.ORC

#### **Architectural Inventory Form** (page 2 of 4)

21. General architectural description: This is a simple wood frame house with a low pitched hipped roof. The short ridge runs east/west and the principal facade faces south. The west portion of the facade consists of a shallow hipped roof projection, which is cut out on

		the east side creating a co	vered area at the main entry. The projection shares the west
		wall and roof planes with t	he main volume. A pair of double hungs are located on the
		west corner. The entry sit	s on the wall of the main volume with a single casement style
		window to the left. A singl	e post supports the overhanging roof and slats infill the space
		between the post and the	main wall. Contrasting vertical siding infills the wall from the
		roof support to the inside of	orner of the ell and a concrete landing fills the same width with
		several steps running to th	e grade. A picture window sits on the east corner with a double
		hung adjacent to it on the	eft. The west side has a single double hung on the front corner
		and a single double hung t	further down the wall. The east side also has a double hung at
		the front corner. The doub	le hung windows have a single horizontal muntin in each sash.
		A flat roofed carport exten	ds off the east side continuing the eave line of the main roof.
		The flat roof is supported by	by a series of thin columns on the east edge. A brick chimney
		sits off the ridge to the rea	r. A shed roof enclosed porch extends off the rear of the house
	22.	Architectural style/building	type: Ranch Type
	23.	Landscaping or special set	ting features: A large street tree sits at the front of the lot and
		several shrubs front the ho	use. A dirt driveway runs to the carport on the east, other wise
		the yard is predominantly	lawn.
	24.	Associated buildings, featu	res, or objects: none
V.	Ar	chitectural History	
	25.	Date of Construction: Estim	ate: 1949 Actual:
			Mesa County Assessors Office
	26.	Architect:	unknown
		Source of information:	The last Review Through the Control of the Control
	27.	Builder/Contractor:	unknown
		Source of information:	276 ( 6) Is - 11ku 3.03   25000 1720 - 1
	28.	Original owner:	Gerald J. Ashby
		Source of information:	1951 Polk Directory
	29.	Construction history (include	le description and dates of major additions, alterations, or
		demolitions):	No major alterations are apparent.
	30.	Original location X	Date of move(s):
<b>/</b> _	His	torical Associations	
	31.	Original use(s):	Domestic, Single Dwelling

Resource Number:	5ME.14772
Temporary Resource N	umber: 570.ORC

# Architectural Inventory Form (page 3 of 4)


	32.	. Intermediate use(s):		
	33.	. Current use(s):	Domestic, Single Dwelling	
	34.	. Site type(s):	Residential Neighborhood	
	35.	. Historical background:	Gerald J. Ashby is shown as owner in the directories of 1951	
	thorough 1957. This building is part of Bookcliff Park developed in 1946. The owner			
	were Gertrude B. Smith, Claude D. Smith, later the U. S. Bank of Grand Junction, a			
	Thomas L. Brownson, Mabel L. Brownson, Bruce Brownson and Mary F. Brownson			
	36.	. Sources of information:	Mesa County Assessors Office; Museum of Western Colorado	
		Archives; Polk Directories 1	951, 1955, 1956, 1957	
VI.	Sic	gnificance		
	37. Local landmark designation: Yes No _X_ Date of designation:			
		Designating authority:		
	38.	Applicable National Registe		
		•	nts that have made a significant contribution to the broad	
		pattern of our history		
B. Associated with the lives of persons significant in our past;			ives of persons significant in our past;	
		X C. Embodies the distinct	tive characteristics of a type, period, or method of	
construction, or represents the work of a master, or that possess high artistic				
values, or represents a significant and distinguishable entity whose compone			s a significant and distinguishable entity whose components	
	may lack individual distinction; or			
	D. Has yielded, or may be likely to yield, information important in history or			
		prehistory.		
		Qualifies under Criteri	a Considerations A through G (see Manual)	
		Does not meet any of t	he above National Register criteria	
	39.	Area(s) of significance: Arch	itecture, Community Development and Planning	
	40.	Period of significance: 1949	9; 1943 to 1957 Uranium Boom	
	41.	Level of significance: Nation	nal State LocalX	
	42.	Statement of significance: T	he development in this area is a direct result of the nation's	
		involvement in WWII and the	e drive for the development of nuclear weapons. The	
		discovery of significant sour	ces of Uranium in the region initiated development in Grand	
		Junction that supported both	the mining of the materials and the administration of	
		programs related to the deve	elopment of weapons. The building types, materials and	
		neighborhood layout are all	indicative of the national trends which were driven by the	
		proliferation of the automobi	le and the enormous demand for single family homes.	
			n the romantic and revival styles that were prevalent in the	
		earlier part of the 20th centu	ry and took on a California inspired design that was	

Resource Number:	5ME.14772
Temporary Resource Numbe	r: 570.ORC

# Architectural Inventory Form (page 4 of 4)

characterized by simple horizontally proportioned forms. Hou	ses were typically mass		
produced on previously undeveloped tracts of land at the periphery of earlier			
development. These groups of houses were typically based on one or two parts of the second of the se			
with a limited number of roof and exterior finish variations, further reinforcing the			
characteristics of mass production. In this particular subdivision there are exar			
both repetitive house types and more high style individualized houses. The curvilinea			
street layout is characteristic of national planning trends and is unusual in this			
community, where new development tended to extend the ex	sting street grid.		
43. Assessment of historic physical integrity related to significanc	e: The house appears to be		
intact in original form.			
VII. National Register Eligibility Assessment			
44. National Register eligibility field assessment:			
Eligible Not Eligible _X Need Data			
45. Is there National Register district potential? Yes X No			
Discuss: The Bookcliff Park Subdivision lies on the periphery of the historic city center			
and was originally established by single group of investors. The sites were built out to			
accommodate the rapid growth associated with the Uranium Boom over a short period of			
time. The architectural styles present in the area represent a	significant concentration		
and continuity of dwellings and a subtle transition of styles over the building period. Fev			
intrusions have been made into the original neighborhood and	d it retains a high level of		
integrity.			
If there is National Register district potential, is this building:	Contributing X		
	Noncontributing		
46. If the building is in existing National Register district, is it:	Contributing		
	Noncontributing		
VIII. Recording Information			
47. Photograph numbers: Roll # 11 Frame # 4			
Negatives filed at: City of Grand Junction Planning Dept.			
48. Report title: <u>Grand Junction Phase 3 Survey</u> 49. Date(s): M	larch 2005		
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H	50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron		
51. Organization: Reid Architects, Inc.			
52. Address: PO Box 1303 Aspen, Colorado 81612			
53. Phone number(s): 970 920 9225			
NOTE: Please attach a sketch map, a photocopy of the USGS quad, map ind	icating resource location, and		
photographs.			

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




570 Orchard Ave.



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



## GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14772

570 Orchard Ave.

manner resilient enter antitude executive executive enterestative enterest executive enterest executive enterest executive enterest executive enterest executive enterest executive enterest enterest executive enterest enterest executive enterest executive enterest executive enterest enterest enterest executive enterest ente

Roll #11 Frame #4

Looking south

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5885 002930

005

share

58002