OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Official eligibility determination (OAHP use only)

Date ______Initials _____ Determined Eligible- NR Determined Not Eligible- NR Determined Eligible- SR Determined Not Eligible- SR Need Data Contributes to eligible NR District Noncontributing to eligible NR District

I. Identification

- 1. Resource number: 5ME.14883
- 2. Temporary resource number: <u>445.ORC</u>
- 3. County: <u>Mesa</u>
- 4. City: _____ Grand Junction
- 5. Historic building name: _____n/a
- 6. Current building name: _____n/a___
- 7. Building address: _____ 445 Orchard Ave. _____
- 8. Owner name and address: <u>Marvin T Ellis</u>

445 Orchard Ave Grand Junction, CO 81501-2159

II. Geographic Information

9. P.M. Ute Principal Meridian Township <u>1 South</u> Range <u>1 West</u> <u>NE</u> 1/4 of <u>NW</u> 1/4 of <u>NE</u> 1/4 of <u>SW</u> 1/4 of section <u>11</u>

10. UTM reference Zone <u>1 2; 7 1 0 5 9 8 mE 4 3 2 8 9 6 2 mN</u>

- 11. USGS quad name: <u>Grand Junction Quadrangle</u> Year: <u>1962_rev.1973</u> Map scale: 7.5' **X** 15' <u>Attach photo copy of appropriate map section</u>.
- 12. Lot(s): __7____ Block:_1_____ Addition:_Sherwood Addition Year of Addition: 1950

13. Boundary Description and Justification: Legal description of the site is: Lot 7 Blk 1 Sherwood Addition

Assessors Office Parcel ID # 2945-113-08-007

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape):<u>Rectangular Plan</u>
- 15. Dimensions in feet: Length 25' x Width 48'
- 16. Number of stories: _1_____
- 17. Primary external wall material(s) (enter no more than two): Wood Horizontal Siding
- 18. Roof configuration: (enter no more than one): Side Gabled Roof
- 19. Primary external roof material (enter no more than one): Asphalt Roof
- 20. Special features (enter all that apply): <u>Porch</u>

21 81 24

Resource Number:

5ME.14883 Temporary Resource Number: ____445.ORC ____

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: This is a modest wood frame house with a side gable roof. The ridge runs east/west and the principal facade faces north. The building has two sections; the main section to the right and a smaller section to the left. The main section has a central front gable porch roof, which is supported by square wood posts. The main entry door is centered under the front gable. A single double hung is located on the wall to the left and a large picture window is located on the wall to the right. The small additive volume on the west side has a lower ridge and the north wall steps back slightly. A door is located in the corner of the step and a series of large windows run from the door to the west corner.
- 22. Architectural style/building type: Ranch Type
- 23. Landscaping or special setting features: The lot has a driveway along the west and two large street trees sits on the edge. Otherwise the yard is primarily lawn._____
- 24. Associated buildings, features, or objects: <u>Sheds are located at the rear.</u>

IV. Architectural History

- 25. Date of Construction: Estimate: 1950 Actual: Source of information: Mesa County Assessors Office 26. Architect: unknown
- Source of information:
- 27. Builder/Contractor: unknown Source of information:
- 28. Original owner: David W. Haynes Source of information: <u>1951 Polk Directory</u>
- 29. Construction history (include description and dates of major additions, alterations, or demolitions): Window alterations, possible siding replacement, enclosure of original carport on west side; dates unknown.
- 30. Original location X Moved Date of move(s):

V. Historical Associations

- 31. Original use(s): _____ Domestic, Single Dwelling_____
- 32. Intermediate use(s): ____
- 33. Current use(s): _____ Domestic, Single Dwelling
- 34. Site type(s): Residential Neighborhood
- 35. Historical background: _____ David W. Haynes is shown as the owner in the 1951____ directory. Robert J. Grigsby is shown as owner in the directories of 1955 and 1956. In. the 1957 directory Larry Thompson is shown as owner. This building is part of Sherwood Addition on property owned in 1950 by the Columbine Company. The

Architectural Inventory Form (page 3 of 4)

following individuals were party to the development: C. D. Smith, Jr., Frank Hall for Columbine Co., and William and Dorothy Knoch, John F. Thompson, Robert and Nora Kyle, Charles Bernal Howard, William and Belva Cross and E. D. Parmiter.

36. Sources of information: <u>Mesa County Assessors Office; Museum of Western Colorado</u> <u>Archives; Polk Directories 1951, 1955, 1956, 1957</u>

VI. Significance

- 37. Local landmark designation: Yes ____ No _X Date of designation: _____ Designating authority: _____
- 38. Applicable National Register Criteria:
 - X A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - ____ D. Has yielded, or may be likely to yield, information important in history or prehistory.
 - ____Qualifies under Criteria Considerations A through G (see Manual)
 - _____Does not meet any of the above National Register criteria
- 39. Area(s) of significance: Architecture, Community Development and Planning
- 40. Period of significance: 1950; 1943 to 1957 Uranium Boom
- 41. Level of significance: National ____ State ____ Local __X___
- 42. Statement of significance: <u>The development in this area is a direct result of the nation's involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types.</u>

۳,

Architectural Inventory Form (page 4 of 4)

with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production.

43. Assessment of historic physical integrity related to significance: <u>Alterations have</u> moderately impacted the integrity of the building.


VII. National Register Eligibility Assessment

44. National Register eligibility field assessment:			
Eligible No	t Eligible X No	eed Data	
45. Is there National R	45. Is there National Register district potential? Yes No _X		Discuss:
If there is National Register district potential, is this building:			Contributing
			Noncontributing
46. If the building is in existing National Register district, is it:			Contributing
			Noncontributing
VIII. Recording Information			
47. Photograph numbers: Roll # 10 Frame # 16			
Negatives filed at: City of Grand Junction Planning Dept.			
48. Report title: <u>Grand Junction Phase 3 Survey</u> 49. Date(s): <u>March 2005</u>			
50. Recorder(s):	0. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron		
51. Organization:	1. Organization: Reid Architects, Inc.		
52. Address:	52. Address: PO_Box_1303_Aspen, Colorado_81612		

53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




445 Orchard Ave.



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004
 5ME.14883
 445 Orchard Ave.

 Roll # 10 Frame # 16

 Looking south

 Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN- 1 5649 002912



