OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 5

	ial eligibility determination HP use only)
Date	Initials
	Determined Eligible- NR Determined Not Eligible- NR Determined Eligible- SR Determined Not Eligible- SR Need Data Contributes to eligible NR District Noncontributing to eligible NR District

I. I	den	tification	
	1.	Resource number:	5ME.14891
	2.	Temporary resource number:_	1450.ESER
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	1450 E. Sherwood
	8.	Owner name and address:	Irene O Learn
	_	***************************************	1450 E Sherwood Dr Grand Junction, CO 81501-7548
11.	Ged	ographic Information	
	9.	P.M. <u>Ute Principal Meridian</u>	Township_1_South Range_1 West
		NE_1/4 of_NE_1/4 of_SW_1/4	of SW_1/4 of section_11
	10.	UTM reference	
		Zone 1 2; 7 1 0	5 0 2 mE 4 3 2 8 5 6 0 mN
	11.	USGS quad name: Grand J	unction Quadrangle
		Year: 1962 rev.1973 Map sc	ale: 7.5'_X_ 15' Attach photo copy of appropriate map section
	12.		9
		Addition: Sherwood Addition	Year of Addition: 1950
	13.	Boundary Description and Just	ification: Legal description of the site is: Lot 5 Blk 9
		Sherwood Addition	
		Assessors Office Parcel ID # 29	45-113-13-005
		This description was chosen as	the most specific and customary description of the site.
THE -	0	shita atuusl Dagasintian	
		chitectural Description Building plan (footprint, shape)	Irrogular Plan
		_	<u>'</u> x Width <u>67'</u>
			(s) (enter no more than two): Brick, Wood Vertical Siding
		•	
		Roof configuration: (enter no m	
			(enter no more than one): Asphalt Roof
	20.	Special features (enter all that	apply): Chimney, Porch, Attached Garage, Carport

Resource Number: 5ME.14891
Temporary Resource Number: 1450.ESER

Architectural Inventory Form (page 2 of 5)

21. General architectural description: This is a complex wood frame house with	a low
pitched hipped roof. The house has a main ridge that runs northeast/southwe	est and the
principal façade faces northwest. The central section has a series of hipped	roof volumes
which extend off the main roof in various directions. The primary extension	runs to the
northwest and sits closest to the street. It has a large picture window on the	right corner,
with a large double hung on the left side of the picture window and a brick ba	se which
creates a planter the length of the window group. The brick base/planter turn	s the right
hand corner and runs back toward the main volume on the southwest facade	of the
projection. About half way along the wall a rectangular brick chimney interru	ipts the
planter, sharing the outside wall plane and the brick materials. The chimney	runs up
through the roof plane. A double hung sits on the corner of the wall to the lef	t of the
chimney and the main entry sits to the right of the chimney. A section of plan	nter also runs
along the wall on the right side of the chimney to the concrete entry walkway	that runs
along the wall of the main hipped volume. A pair of windows with a high sill	sit on the
main façade, near the right side. The main volume also extends to the left be	eyond the
above described projecting volume. Two large fixed windows are equally sp	aced on the
street facing wall. Another hipped roof projection extends off the southwest v	vall of the
main volume. This section has a lower ridge and continues the street facing	wall plane
adjacent to the entry door. This results in a deep overhang running to the en	try. The
corner of the main roof is supported by a trio of pipe columns that sit on the e	nd of the
concrete porch area. A flat roof projects from the front of the garage, creating	a carport
area. This roof is supported by simple wood posts on either side. The house	has a
variety of siding treatments, which vary from areas of contrasting brick to are	as of
vertical siding. The double hungs have a single horizontal muntin in each sa	<u>sh.</u>
22. Architectural style/building type: Ranch Type	
23. Landscaping or special setting features: The house has several shrubs and p	<u>lanting</u>
areas that front the house and run along the driveway to the southwest. Other	rwise the
vard is predominantly lawn.	
24. Associated buildings, features, or objects: none	
IV. Architectural History	
25. Date of Construction: Estimate: 1955 Actual:	
Source of information: Mesa County Assessors Office	
26. Architect: unknown	

Resource Number:	5ME.14891	
Temporary Resource Number:	1450.ESER	

Architectural Inventory Form (page 3 of 5)

		Source of information:	
	27.	. Builder/Contractor:	unknown
		Source of information:	3
	28.		Bernard A. Buescher
		Source of information:	1955 Polk Directory
	29.		e description and dates of major additions, alterations, or
		demolitions):	Siding alterations, addition of carport, dates unknown.
	30.	Original location X	_MovedDate of move(s):
V.	His	storical Associations	
			Domestic, Single Dwelling
			Something Switching
			Domestic, Single Dwelling
			Residential Neighborhood
			Bernard A, Buescher is shown as the owner in the 1955 and
			cher's owned the house until 1970 when the current owner
			ernie Buescher (son of the original owner) is now a State
			ing is part of Sherwood Addition on property owned in 1950 by
			The following individuals were party to the development: C. D.
			plumbine Co., and William and Dorothy Knoch, John F.
			a Kyle, Charles Bernal Howard, William and Belva Cross and
	36. Sources of information: Mesa County Assessors Office: Museum of Western Colorac		Mesa County Assessors Office; Museum of Western Colorado
Archives; Polk Directories 1955, 1956, 1957, Information also provided by Irene Learn.		955, 1956, 1957, Information also provided by Irene Learn,	
		current owner.	
VI.	Sig	gnificance	
	37.	Local landmark designation	: Yes No _X Date of designation:
		Designating authority:	
	38.	Applicable National Registe	er Criteria:
		X A. Associated with eve	nts that have made a significant contribution to the broad
		pattern of our histor	у;
			lives of persons significant in our past;
		X C. Embodies the distinct	ctive characteristics of a type, period, or method of
		·	resents the work of a master, or that possess high artistic
			ts a significant and distinguishable entity whose components
		may lack individual	distinction; or

Resource Number:	5ME.14891
Temporary Resource Number:	1450.ESER

Architectural Inventory Form (page 4 of 5)

	D. Has yielded, or may be likely to yield, information important	ortant in history or		
	prehistory.	8.6 11		
	Qualifies under Criteria Considerations A through G (see Manual)			
	Does not meet any of the above National Register criteri			
	Area(s) of significance: <u>Architecture</u> , <u>Community Developmen</u>	t_and_Planning		
	Period of significance: 1955; 1943 to 1957 Uranium Boom			
	Level of significance: National State Local X			
42.	Statement of significance: The development in this area is a c			
	involvement in WWII and the drive for the development of nuc	lear weapons. The		
	discovery of significant sources of Uranium in the region initia	ted development in Grand		
	Junction that supported both the mining of the materials and the	ne administration of		
	programs related to the development of weapons. The building	g types, materials and		
	neighborhood layout are all indicative of the national trends w	hich were driven by the		
	proliferation of the automobile and the enormous demand for	single family homes.		
	House designs departed from the romantic and revival styles t	hat were prevalent in the		
	earlier part of the 20th century and took on a California inspire	ed design that was		
	characterized by simple horizontally proportioned forms. House	ses were typically mass		
	produced on previously undeveloped tracts of land at the peri	phery of earlier		
	development. These groups of houses were typically based o	n one or two plan types		
	with a limited number of roof and exterior finish variations, fur	ther_reinforcing the		
	characteristics of mass production. This house is an example	of the more substantial and		
	individualized homes that skirt Sherwood Park.			
43.	Assessment of historic physical integrity related to significance	e: Alterations have added		
	design elements which are not original to the character of the	house. Along with the		
	addition of the carport the integrity has been moderately comp	promised.		
VII. Na	ational Register Eligibility Assessment			
44.	National Register eligibility field assessment:			
	Eligible Not EligibleX Need Data			
45.	Is there National Register district potential? Yes No _X	Discuss:		
	If there is National Register district potential, is this building:	Contributing		
		Noncontributing		
46.	If the building is in existing National Register district, is it:	Contributing		
		Noncontributing		

Resource Number:		_5ME.14891
Temporary Resource	Number:	1450.ESER


Architectural Inventory Form (page 5 of 5)

VIII. Recording Information

47. Photograph numbers: Roll # 13 Frame # 12		
Negatives filed at	: City of Grand Junction Planning Dept.	
48. Report title: Gran	nd Junction Phase 3 Survey 49. Date(s): March 2005	
50. Recorder(s):	Suzannah Reid, Patrick Duffield and Lydia Herron	
51. Organization:	Reid Architects, Inc.	
52. Address:	PO Box 1303 Aspen, Colorado 81612	
53. Phone number(s):	970 920 9225	

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1450 E. Sherwood Ave.



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14891 1450 E. Sherwood
Roll # 13 Frame # 12
Looking southeast
Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN- 1 5648 002911

013

share

54601