

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

Official eligibility determination (OAHP use only)

Date _____ Initials _____

- Determined Eligible- NR
- Determined Not Eligible- NR
- Determined Eligible- SR
- Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District
- Noncontributing to eligible NR District

I. Identification

1. Resource number: 5ME.14670
2. Temporary resource number: 1354.MES
3. County: Mesa
4. City: Grand Junction
5. Historic building name: n/a
6. Current building name: n/a
7. Building address: 1354 Mesa Ave.
8. Owner name and address: Kelly S Corn
2486 H CT Grand Junction, CO 81505-9613

II. Geographic Information

9. P.M. Ute Principal Meridian Township 1 South Range 1 West
SW 1/4 of NE 1/4 of NW 1/4 of SW 1/4 of section 12
10. UTM reference
Zone 1 2 ; 7 1 1 9 6 5 mE 4 3 2 8 8 4 6 mN
11. USGS quad name: Grand Junction Quadrangle
Year: 1962 rev.1973 Map scale: 7.5' X 15' *Attach photo copy of appropriate map section.*
12. Lot(s): 7 & 8 Block: 3
Addition: Eastholme in Grandview Year of Addition: 1950
13. Boundary Description and Justification: Legal description of the site is: W 35.5ft Of Lot 7
+ E 25.5ft Of Lot 8 Blk 3 Eastholme-In-Grandview Subdivision
Assessors Office Parcel ID # 2945-123-04-002
This description was chosen as the most specific and customary description of the site.

III. Architectural Description

14. Building plan (footprint, shape): Rectangular Plan
15. Dimensions in feet: Length 28' x Width 50'
16. Number of stories: 1
17. Primary external wall material(s) (enter no more than two): Brick
18. Roof configuration: (enter no more than one): Gable-on-Hip Roof
19. Primary external roof material (enter no more than one): Asphalt Roof
20. Special features (enter all that apply): Attached Garage

Resource Number: 5ME.14670
Temporary Resource Number: 1354.MES

Architectural Inventory Form
(page 2 of 4)

21. General architectural description: This is a simple rectangular house. The hipped roof has a large overhang on all sides and small gables revealed at the ends of the ridge. The ridge runs east/west and the principal façade faces south. A single car garage door is located on the west end of the façade with the main entry adjacent to the right. A picture window flanked by vertical units sits to the right of the door and a single window is centered on the remaining wall between the picture window and the pair of windows that sit near the east end. The windows have a single horizontal muntin. A shed roof porch extends off the rear.
22. Architectural style/building type: Ranch Type
23. Landscaping or special setting features: A large street tree sits at the corner of the lot with some shrubs along the side walk. The yard is otherwise predominantly lawn.
24. Associated buildings, features, or objects: _____

IV. Architectural History

25. Date of Construction: Estimate: 1951 Actual: _____
Source of information: Mesa County Assessors Office
26. Architect: unknown
Source of information: _____
27. Builder/Contractor: unknown
Source of information: _____
28. Original owner: unknown
Source of information: _____
29. Construction history (include description and dates of major additions, alterations, or demolitions): Window replacement, porch addition; dates unknown.
30. Original location Moved _____ Date of move(s): _____

V. Historical Associations

31. Original use(s): Domestic, Single Dwelling
32. Intermediate use(s): _____
33. Current use(s): Domestic, Single Dwelling
34. Site type(s): Residential Neighborhood
35. Historical background: Robert R. Carver is shown as owner in the 1955 and 1956 directories. This building is part of Eastholme-in-Grandview Subdivision. This part of the larger Grandview Subdivision was owned by Eugene and Annabelle Helms, Richard and Ella Mae Bouman, Coe Van Deren, and John and Ruth Dyer and developed in 1950.
36. Sources of information: Mesa County Assessors Office; Museum of Western Colorado Archives; Polk Directories 1951, 1955, 1956, 1957

Resource Number: 5ME.14670
Temporary Resource Number: 1354.MES

Architectural Inventory Form
(page 3 of 4)

VI. Significance

37. Local landmark designation: Yes No Date of designation: _____
Designating authority: _____

38. Applicable National Register Criteria:

- A. Associated with events that have made a significant contribution to the broad pattern of our history;
- B. Associated with the lives of persons significant in our past;
- C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
- D. Has yielded, or may be likely to yield, information important in history or prehistory.
- Qualifies under Criteria Considerations A through G (see Manual)
- Does not meet any of the above National Register criteria

39. Area(s) of significance: Architecture, Community Development and Planning

40. Period of significance: 1951; 1943 to 1957 Uranium Boom

41. Level of significance: National State Local

42. Statement of significance: The development in this area is a direct result of the nation's involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production.

43. Assessment of historic physical integrity related to significance: The alterations to the windows have moderately impacted the integrity.

Resource Number: 5ME.14670
Temporary Resource Number: 1354.MES

Architectural Inventory Form
(page 4 of 4)

VII. National Register Eligibility Assessment


44. National Register eligibility field assessment:
Eligible Not Eligible Need Data
45. Is there National Register district potential? Yes No Discuss: _____
If there is National Register district potential, is this building: Contributing _____
Noncontributing _____
46. If the building is in existing National Register district, is it: Contributing _____
Noncontributing _____

VIII. Recording Information

47. Photograph numbers: Roll # 2 Frame # 35
Negatives filed at: City of Grand Junction Planning Dept.
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron
51. Organization: Reid Architects, Inc.
52. Address: PO Box 1303 Aspen, Colorado 81612
53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation
1300 Broadway, Denver, CO 80203 (303) 866-3395




1354 Mesa Ave.



North

Grand Junction, Colorado
image from 2002 aerial map

City of Grand Junction • Phase Three Survey
2004



TN * MN
11 1/2"



Map created with TOPO! © 2003 National Geographic (www.nationalgeographic.com/topo)

GRAND JUNCTION, COLORADO

Phase Three Historic Survey
2004

5ME.14670 1354 Mesa Ave.
Roll # 2 Frame # 35
Looking north
Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN+ 2 5652 002915

036

sharp

54750

