OAHP1403 Rev. 9/98

1.61

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Official eligibility determination (OAHP use only) Date _______Initials _____

- Determined Eligible- NR Determined Not Eligible- NR Determined Eligible- SR
- Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District
 - Noncontributing to eligible NR District

I. Identification

- 1. Resource number: _____ 5ME.14918
- 2. Temporary resource number: 604.NOR
- 3. County: Mesa
- 4. City: Grand Junction
- 5. Historic building name: <u>Calso Service Station and Oil</u>
- 6. Current building name: Express Dry Cleaning and Laundry
- 7. Building address: _____ 604 North Ave.
- 8. Owner name and address: <u>Terrance I Boggs</u>
 - 604 North Ave Grand Junction, CO 81501-7544

II. Geographic Information

9. P.M. Ute Principal Meridian Township 1 South Range 1 West SE 1/4 of SE 1/4 of SE 1/4 of SW 1/4 of section 11

10. UTM reference

- Zone <u>1 2; 7 1 0 8 5 2 mE 4 3 2 8 2 2 2 mN</u>
- 11. USGS quad name: <u>Grand Junction Quadrangle</u> Year: <u>1962 rev.1973</u> Map scale: 7.5' X 15' *Attach photo copy of appropriate map section*.
- 12. Lot(s): _2_____ Block:_____ Addition: <u>Baby Boggs Subdivision</u>_____Year of Addition: <u>2002</u>_____

13. Boundary Description and Justification: Legal description of the site is: Lot 2 Baby Boggs Subdivision Sec 11 1s 1w - 0.25ac

Assessors Office Parcel ID # 2945-113-25-006

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape): Rectangular Plan
- 15. Dimensions in feet: Length 50' x Width 60'
- 16. Number of stories: 1
- 17. Primary external wall material(s) (enter no more than two): Stucco
- 18. Roof configuration: (enter no more than one): Flat Roof
- 19. Primary external roof material (enter no more than one): Synthetic Roof
- 20. Special features (enter all that apply): none_

Resource Number: 5ME.14918 Temporary Resource Number: 604.NOR

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: <u>This is a simple rectangular box, with no surface</u> detail. <u>The main façade faces south and is a simple rectangle Three horizontally</u> proportioned window openings are equally spaced across the main façade, the center one being slightly wider. <u>The center opening has a door in the center with a pair of fixed</u> windows on either side. <u>The east bay has three windows and the west has a door and store front windows that extend to the ground</u>. A large sign spans the width of the façade. <u>The sides have minimal openings and a flat roof addition is set on the rear</u>.
- 22. Architectural style/building type: <u>Commercial Type</u>
- 23. Landscaping or special setting features: <u>The building is surrounded by pavement on all</u> sides. It is set back slightly from the side walk line.
- 24. Associated buildings, features, or objects: <u>A large steel pipe column is set just off the</u> <u>corner and supports a tilted panel</u>. Possible an unused sign structure.

IV. Architectural History

- 25. Date of Construction: Estimate: 1937 Actual: _______ Actual: _______ Source of information: Mesa County Assessors Office
- 26. Architect: unknown
 Source of information:
- 27. Builder/Contractor: <u>unknown</u> Source of information: _____
- 28. Original owner: <u>unknown</u> Source of information: _____
- 29. Construction history (include description and dates of major additions, alterations, or demolitions): Addition off rear, possibly since 2002. Stucco and alterations to façade windows and doors; dates unknown.
- 30. Original location X Moved Date of move(s):

V. Historical Associations

- 31. Original use(s): <u>Commerce And Trade; Gas Station</u>
- 32. Intermediate use(s): Commerce And Trade; Gas Station
- 33. Current use(s): Commerce and Trade
- 34. Site type(s): Commercial Strip
- 35. Historical background: Between 1941 and 1946 Polk directories show this address as being Calso Service Station and Oil. By 1949 the listing was shown as Onan Super Service, Onan Ad-Ver-Tis-Er Signs. In 1951 it was Mike's Appliance Center, and by 1956 it was listed as Fleet Service Tires. This is located in the Baby Boggs Subdivision.

Resource Number:	5ME.14918
Temporary Resource Number:	604.NOR

Architectural Inventory Form (page 3 of 4)

36. Sources of information: <u>Mesa County Assessors Office; Museum of Western Colorado</u> <u>Archives; Polk Directories</u>

VI. Significance

- 37. Local landmark designation: Yes ____ No **X** Date of designation: _____ Designating authority:
- 38. Applicable National Register Criteria:
 - A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important in history or prehistory.
 - ____Qualifies under Criteria Considerations A through G (see Manual)
 - Does not meet any of the above National Register criteria
- 39. Area(s) of significance: Architecture
- 40. Period of significance: 1937
- 41. Level of significance: National ____ State ____ Local X
- 42. Statement of significance: <u>This building is significant for its position in the expansion of</u> <u>the commercial activities of the community.</u> <u>Development in this area was driven by the</u> proliferation of the automobile.
- 43. Assessment of historic physical integrity related to significance: <u>The alterations to the</u> <u>façade windows and the stucco finish have seriously compromised the integrity of this</u> <u>building.</u>

VII. National Register Eligibility Assessment

44. National Register eligibility field assessment:

Eligible Not Eligible _X Need Data	
------------------------------------	--

- 45. Is there National Register district potential? Yes No X Discuss:______ If there is National Register district potential, is this building: Contributing______ Noncontributing ______
- 46. If the building is in existing National Register district, is it:
- Contributing ______

Resource Number: 5ME.14918 Temporary Resource Number: 604.NOR

Architectural Inventory Form (page 4 of 4)

VIII. Recording information

47. Photograph numbers: Roll # 8 Frame # 34

Negatives filed at: <u>City of Grand Junction Planning Dept.</u>

48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005

50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron


51. Organization: Reid Architects, Inc.

52. Address: PO Box 1303 Aspen, Colorado 81612

53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




604 North Ave.



Grand Junction, Colorado *image from 2002 aerial map*

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004

