OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Official eligibility determination (OAHP use only) Date _______Initials ______ Determined Eligible- NR Determined Not Eligible- NR Determined Eligible- SR

- Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District
- Noncontributing to eligible NR District

I. Identification

- 1. Resource number: <u>5ME.14603</u>
- 2. Temporary resource number: 1240.SIXT
- 3. County: <u>Mesa</u>
- 4. City: Grand Junction
- 5. Historic building name: _____n/a ____
- 6. Current building name: _____n/a____
- 7. Building address: 1240 N. 16th Street
- 8. Owner name and address: Steven J Bethka

653 Grand View Dr Grand Junction, CO 81506-4901

II. Geographic Information

9. P.M. Ute Principal Meridian Township 1 South Range 1 West NE 1/4 of SW 1/4 of SE 1/4 of SW 1/4 of section 12

10. UTM reference

- Zone <u>1</u> <u>2</u>; <u>7</u> <u>1</u> <u>2</u> <u>2</u> <u>4</u> <u>8</u> mE <u>4</u> <u>3</u> <u>2</u> <u>8</u> <u>4</u> <u>1</u> <u>0</u> mN
- 11. USGS quad name: <u>Grand Junction Quadrangle</u> Year: <u>1962_rev.1973_</u> Map scale: 7.5'_X_ 15'__ Attach photo copy of appropriate map section.
- 12. Lot(s): <u>15</u> Block: <u>1</u> Addition: <u>Parkplace Heights</u> Year of Addition: <u>1950</u>
- 13. Boundary Description and Justification: Legal description of the site is: Lot 15 Blk 1 Parkplace Heights

Assessors Office Parcel ID # 2945-123-24-026

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape): Rectangular Plan
- 15. Dimensions in feet: Length 51' x Width 24'
- 16. Number of stories: 1
- 17. Primary external wall material(s) (enter no more than two): Aluminum
- 18. Roof configuration: (enter no more than one): Side Gabled Roof
- 19. Primary external roof material (enter no more than one): Asphalt Roof
- 20. Special features (enter all that apply): none

Resource Number: 5ME.14603 Temporary Resource Number: 1240.SIXT

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: <u>This is a moderate sized wood frame house with a medium pitched side gabled roof.</u> The ridge runs north/south and the principal façade faces west. The principal façade is an enclosed porch with the door in the center and a series of double hung windows to either side. The porch roof is a shed form that is a continuation of the main roof only it has a slightly lower pitch. A single double hung sits on the side walls of the porch area. A large pair of slider windows is located on the south side, generally centered on the roof peak. A shed roof addition is attached to the full width of the rear and extends beyond the south wall to the south. Another flatter roof addition extends off the back of that addition. The house sits on a concrete foundation.
- 22. Architectural style/building type: No Style
- 23. Landscaping or special setting features: The house sits on an open lot with a perimeter chain link fence, a gate to the rear of the house. Otherwise the yard is predominantly lawn.
- 24. Associated buildings, features, or objects: A gable shed sits at the rear.

IV. Architectural History

- 25. Date of Construction: Estimate: 1919 Actual: ______ Actual: ______ Source of information: _____ Mesa County Assessors Office
- 26. Architect: ______unknown
 Source of information: ______
- 27. Builder/Contractor: unknown
 Source of information:
- 28. Original owner: ______unknown Source of information: _____
- 29. Construction history (include description and dates of major additions, alterations, or demolitions): <u>All exterior materials replaced, windows replaced, porch</u>enclosure, several additions to the rear.
- 30. Original location X Moved Date of move(s): _____

V. Historical Associations

- 31. Original use(s): Domestic, Single Dwelling
- 32. Intermediate use(s):
- 33. Current use(s): Domestic, Single Dwelling
- 34. Site type(s): Residential Neighborhood

Resource Number: <u>5ME.14603</u> Temporary Resource Number: <u>1240.SIXT</u>

Architectural Inventory Form (page 3 of 4)

- 35. Historical background: <u>William H. Hardin is listed in the 1955 and 1956 directories</u> as well as on the Parkplace Heights plat map. The plat map includes his wife, Margaret M. Green. The 1955 listing is the first instance of this address in the available directories. This house is now part of Parkplace Heights Subdivision developed in 1951. This area was originally part of the larger Grandview Subdivision.
- 36. Sources of information: <u>Mesa County Assessors Office; Museum of Western Colorado</u> <u>Archives; Polk Directories</u>


VI. Significance

*e: -

- 37. Local landmark designation: Yes ____ No _X Date of designation: _____ Designating authority: _____
- 38. Applicable National Register Criteria:
 - A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important in history or prehistory.
 - Qualifies under Criteria Considerations A through G (see Manual)
 - _____Does not meet any of the above National Register criteria
- 39. Area(s) of significance: Architecture
- 40. Period of significance: 1919
- 41. Level of significance: National ____ State ____ Local __X__
- 42. Statement of significance: <u>This house is representative of the early suburban</u> <u>development that occurred adjacent to the original core of the city on previously</u> <u>agricultural lands</u>. <u>The town expanded first on the historic arterial streets and then</u> <u>infilled the interior of the grid</u>. <u>This area of town reflects the City's transition</u>, from early, <u>suburban development on a small scale to larger production style development during</u> <u>more rapid expansion</u>. <u>Though the automobile was a factor in the location of new</u> <u>development, the small modest houses that were built did not integrate the car into the</u> <u>design</u>.
- 43. Assessment of historic physical integrity related to significance: <u>Alterations and additions</u> <u>have removed all character defining features</u>. <u>Integrity is completely compromised</u>.

Architectural Inventory Form (page 4 of 4)	
II. National Register Eligibility Assessment	
44. National Register eligibility field assessment:	
Eligible Not Eligible _X Need Data	
45. Is there National Register district potential? Yes No X	Discuss:
If there is National Register district potential, is this building:	Contributing
	Noncontributing
46. If the building is in existing National Register district, is it:	Contributing
	Noncontributing
III. Recording Information	
47. Photograph numbers: Roll # 5 Frame # 22	
Negatives filed at: City of Grand Junction Planning Dept.	
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): M	larch 2005
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H	lerron
51. Organization: Reid Architects, Inc.	
52. Address: PO Box 1303 Aspen, Colorado 81612	
53. Phone number(s): 970 920 9225	

photographs. Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1240 N. 16th Street



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



