OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

l of 4

| | ial eligibility determination HP use only) |
|------|---|
| Date | Initials |
| | Determined Eligible- NR |
| | Determined Not Eligible- NR |
| | Determined Eligible- SR |
| | Determined Not Eligible- SR |
| | Need Data |
| | Contributes to eligible NR District |
| | Noncontributing to eligible NR District |

| I. I | den | tification | | | |
|---|--|------------------------------------|--|--|--|
| | 1. | Resource number: | 5ME.14604 | | |
| | 2. | Temporary resource number:_ | 1300.SIXT | | |
| | 3. | County: | Mesa | | |
| | 4. | City: | Grand Junction | | |
| | 5. | Historic building name: | n/a | | |
| | 6. | Current building name: | n/a | | |
| | 7. | Building address: | 1300 N. 16th Street | | |
| | 8. | Owner name and address: | Gale M James | | |
| | _ | | 1300 N 16th St Grand Junction, CO 81501-4310 | | |
| II. | Ged | ographic Information | | | |
| | 9. | P.M. <u>Ute Principal Meridian</u> | Township 1 South Range 1 West | | |
| | | SE 1/4 of NW 1/4 of SE 1/4 | of_SW_1/4 of section_12 | | |
| 10. UTM reference | | | | | |
| Zone 1 2; 7 1 2 2 4 6 mE 4 3 2 8 4 4 4 n | | | | | |
| 11. USGS quad name: <u>Grand Junction Quadrangle</u> Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map | | | | | |
| | | | | | |
| Addition: Parkplace Heights | | Addition: Parkplace Heights | Year of Addition: 1950 | | |
| | 13. Boundary Description and Justification: Legal description of the site is: Lot 17 Blk 1 | | | | |
| Parkplace Heights | | | | | |
| Assessors Office Parcel ID # 2945-123-24-021 This description was chosen as the most specific and customary description of the | | | | | |
| | | | | | |
| | 14. | Building plan (footprint, shape): | Irregular Plan | | |
| | 15. | Dimensions in feet: Length 30 | x Width_31' | | |
| | 16. | Number of stories: 1 | | | |
| | 17. | Primary external wall material(| s) (enter no more than two): Stucco | | |
| | 18. | Roof configuration: (enter no m | ore than one): Front Gabled Roof | | |
| 19. Primary external roof material (enter no more than one): Asphalt Roof | | | | | |
| | 20. | Special features (enter all that | apply): Car port. Chimney | | |

Resource Number: 5ME.14604
Temporary Resource Number: 1300.SIXT

Architectural Inventory Form (page 2 of 4)

| 21 | I. General architectural description: This is a simple rectangular wood frame house with a |
|-------|--|
| | medium pitched front gabled roof. The ridge runs east/west and the principal façade |
| | faces west. A small front gable roof is applied to the main wall in the center over the |
| | entry door. The roof is supported by pairs of square wood columns on either side of the |
| | corners. Pilaster supports the roof at the wall. The columns support a shallow |
| | entablature with an infilled pediment above. A wide double hung sits to each side of the |
| | entry, centered on the remaining wall. The double hungs are wood with a four over two |
| | muntin pattern. Similar double hungs are located on the sides. The stucco wall finish |
| | extends to the eave line and the large gable end is infilled with horizontal siding. The |
| | windows have, what appear to be brick sills under the stucco. A small cross gable |
| | extends off the main roof at the southeast corner of the house and a shed roof carport is |
| | attached to the south of that. The carport is very deep and open on both sides beyond the |
| | east side of the house. The back wall is an otherwise detached front gable garage. Small |
| | basement windows can be seen that correspond to the main level window locations. A |
| | brick chimney is located on the south slope of the roof. |
| 22 | 2. Architectural style/building type: No Style |
| 23 | . Landscaping or special setting features: The house sits on an open lot with little |
| | vegetation. |
| 24 | . Associated buildings, features, or objects: Front gable garage at rear of carport |
| | |
| IV. A | rchitectural History |
| 25 | . Date of Construction: Estimate: 1920s Actual: |
| | Source of information: Based on building style and other similar buildings in the |
| | neighborhood. (Mesa County Assessors Office lists 1945) |
| 26 | . Architect: unknown |
| | Source of information: |
| 27 | . Builder/Contractor:unknown |
| | Source of information: |
| 28 | Original owner: |
| | Source of information: Parkplace Heights Plat Map |
| 29 | . Construction history (include description and dates of major additions, alterations, or |
| | demolitions): Carport addition, cross gable addition, Stucco added, garage |
| | at rear; dates unknown. |
| 30 | . Original location X Moved Date of move(s): |

Resource Number: 5ME.14604
Temporary Resource Number: 1300.SIXT

Architectural Inventory Form (page 3 of 4)

| V. | Historical Associations | |
|-----|---------------------------------------|---|
| | 31. Original use(s): | Domestic, Single Dwelling |
| | 32. Intermediate use(s): | S. H. B. D. S. C. |
| | 33. Current use(s): | Domestic, Single Dwelling |
| | 34. Site type(s): | Residential Neighborhood |
| | 35. Historical background: | Thomas C. Houston and Josephine Houston are listed as the |
| | owners of the lot on the | 1951 Parkplace Heights Plat Map. Clair C. Dotts is listed in the |
| | 1955 and 56 directories, | the 1955 listing is the first instance of this address in the |
| | available directories. Th | is building is now part of Parkplace Heights Subdivision |
| | developed in 1951. This | s area was originally part of the larger Grandview Subdivision. |
| | 36. Sources of information:_ | Mesa County Assessors Office; Museum of Western Colorado |
| | Archives; Polk Directorie | s |
| | | |
| VI. | . Significance | |
| | 37. Local landmark designat | tion: Yes No _X Date of designation: |
| | Designating authority: | |
| | 38. Applicable National Reg | ister Criteria: |
| | A. Associated with e | vents that have made a significant contribution to the broad |
| | pattern of our his | tory; |
| | B. Associated with the | he lives of persons significant in our past; |
| | X C. Embodies the dis | tinctive characteristics of a type, period, or method of |
| | construction, or r | epresents the work of a master, or that possess high artistic |
| | values, or repres | ents a significant and distinguishable entity whose components |
| | may lack individu | ual distinction; or |
| | D. Has yielded, or m | ay be likely to yield, information important in history or |
| | prehistory. | |
| | | teria Considerations A through G (see Manual) |
| | | of the above National Register criteria |
| | _ | Architecture |
| | 40. Period of significance: | |
| | | ational State Local <u>X</u> |
| | | e: This house is representative of the early suburban |
| | | ed adjacent to the original core of the city on previously |
| | | own expanded first on the historic arterial streets and then |
| | | grid. This area of town reflects the City's transition, from early |
| | · · · · · · · · · · · · · · · · · · · | n a small scale to larger production style development during |
| | more rapid expansion. I | hough the automobile was a factor in the location of new |


| Resource Number: | 5ME,14604 |
|----------------------------|-----------|
| Temporary Resource Number: | 1300.SIXT |

Architectural Inventory Form (page 4 of 4)

| | development, the small modest houses that were built did not integrate the car into the | | | | | | |
|---|---|-----------------|--|--|--|--|--|
| | design. These early suburban examples were compact houses with simple forms and | | | | | | |
| | simple materials, based on traditional styles. | | | | | | |
| 43 | 43. Assessment of historic physical integrity related to significance: Alterations have | | | | | | |
| | seriously impacted the integrity. | | | | | | |
| | | | | | | | |
| VII. N | VII. National Register Eligibility Assessment | | | | | | |
| 44 | 44. National Register eligibility field assessment: | | | | | | |
| | Eligible Not Eligible X Need Data | | | | | | |
| 45 | i. Is there National Register district potential? Yes No _X | Discuss: | | | | | |
| | If there is National Register district potential, is this building: | Contributing | | | | | |
| | | Noncontributing | | | | | |
| 46. If the building is in existing National Register district, is it: | | Contributing | | | | | |
| | | Noncontributing | | | | | |
| VIII. Recording Information | | | | | | | |
| 47 | . Photograph numbers: Roll # 5 Frame # 24 | | | | | | |
| | Negatives filed at: City of Grand Junction Planning Dept. | | | | | | |
| 48 | 48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005 | | | | | | |
| 50 | . Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H | erron | | | | | |
| 51 | 51. Organization: Reid Architects, Inc. | | | | | | |
| 52 | . Address: PO Box 1303 Aspen, Colorado 81612 | | | | | | |
| 53 | . Phone number(s): <u>970 920 9225</u> | | | | | | |
| | | | | | | | |

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1300 N. 16th Street



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14604

1300 N. 16th Street

Roll #5 Frame #24

Looking northeast

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5882 002927

024

share

57921