OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

fficial eligibi AHP use onl	lity determination
ite	Initials
Determined	Eligible- NR
	Not Eligible- NR
	Eligible- SR
Determined	Not Eligible- SR
Need Data	
	to eligible NR District

		l of 4		Noncontributing to eligible NR District
I. I	den	tification		
	1.	Resource number:	5ME.14605	
	2.	Temporary resource number:_	1315.SIXT	
3. County: Mesa				
	4.	City:	Grand Junct	on
	5.	Historic building name:	n/a	
	6.	Current building name:	n/a	
	7.	Building address:	1315 N. 16th	Street
	8.	Owner name and address:	Edith Woodr	ing
	_	: ea	2862 Grand	Falls Dr Grand Junction, CO 81501-6888
II.	Ged	ographic Information		
	9.	P.M. <u>Ute Principal Meridian</u>	Township	0_1 South Range_1 West
		<u>NW</u> 1/4 of <u>NW</u> 1/4 of <u>SE</u> 1/	4 of <u>SW</u> 1/4	of section 12
10. UTM reference				
Zone 1 2; 7 1 2 2 0 5 mE 4 3 2 8 5 0 9 mN			E <u>4 3 2 8 5 0 9</u> mN	
11. USGS quad name: Grand Junction Quadrangle			angle	
Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map sec			15' Attach photo copy of appropriate map section.	
Addition: Parkplace Heights Year of Addition: 1950			Year of Addition: 1950	
	13. Boundary Description and Justification: Legal description of the site is: Lot 3 Blk 2			
Parkplace Heights				
Assessors Office Parcel ID # 2945-123-22-014			1	
This description was chosen as the most specific and customary description of the site.				cific and customary description of the site.
11:	Arc	chitectural Description		
		Building plan (footprint, shape):	: Rectangula	r Plan
			_	x Width 24'
		•		
				ore than two): Wood Horizontal Siding
		Roof configuration: (enter no m		
		-		e than one): Asphalt Roof
	20. Special features (enter all that apply): Porch. Chimney			

Resource Number:	5ME.14605
Temporary Resource	Number: 1315.SIXT

Architectural Inventory Form (page 2 of 4)

	21.	. General architectural descr	iption: <u>This is a s</u>	simple rectangular wood frame house with a		
				runs east/west and the principal façade		
		faces east. A small front ga	ble roof is applied	d to the main wall just off center to the south,		
		over the entry door. The ro	of is supported by	y single square wood columns on the		
		corners. Pilaster supports t	he roof at the wal	I. The columns support a shallow		
		entablature with an infilled	pediment above.	A low wall runs between the front column		
		and the main wall on each :	side. A wide dout	ole hung sits to each side of the entry,		
	centered on the remaining wall. The double hungs are wood with a four over two mun					
		pattern. Similar double_hur	ngs_are_located_or	the sides. The narrow clapboard siding		
	extends to the eave line and the large gable end is infilled with composition shingles.					
		Patches of composition shingles can also been seen on areas of the main walls. The				
		house sits on a concrete foundation and small basement windows can be seen that				
		correspond to the main level window locations. A brick chimney is located on the south				
		slope of the roof.				
	22.	22. Architectural style/building type: No Style				
	23.	23. Landscaping or special setting features: The house sits on an open lot with small trees				
		and little other vegetation.				
	24. Associated buildings, features, or objects: A prefabricated carport sits on the south side					
		of the house near the rear.				
IV.	Ar	chitectural History				
	25.	Date of Construction: Estima	ite:_1921	Actual:		
		Source of information:		sessors Office		
	26.	Architect:	unknown			
		Source of information:				
	27.	Builder/Contractor:	unknown			
		Source of information:				
	28.	Original owner:	unknown			
		Source of information:				
	29.	Construction history (include	e description and	dates of major additions, alterations, or		
		demolitions):	Siding alterations	s, alterations to the front porch; dates		
		unknown.				
	30.	Original location X	Moved	Date of move(s):		
v.	His	torical Associations				
	31.	Original use(s):	Domestic, Single	Dwelling		
	32	Intermediate use(s):	•			

Resource Number:		5ME.14605
Temporary Resource	Number:	1315.SIXT

Architectural Inventory Form (page 3 of 4)

	33.	Current use(s):	Domestic, Single Dwelling
	34.	Site type(s):	Residential Neighborhood
	35.	. Historical background:	Chester A. Hanchett is listed as the owner in the 1955 and 56
		directories. The 1955 listin	g is the first instance of this address in the available
		directories. Chester A. Han	chett and Eva M. Hanchett are also listed on the 1951
		Parkplace Heights Plat Map	. This building is part of Parkplace Heights Subdivision
		developed in 1951. This ar	ea was originally part of the larger Grandview Subdivision.
	36.	Sources of information:	Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories.	
VI.	Si	gnificance	
	37.	Local landmark designation	: Yes No _X Date of designation:
		Designating authority:	120
	38.	Applicable National Registe	er Criteria:
		A. Associated with eve	nts that have made a significant contribution to the broad
		pattern of our histor	у;
		B. Associated with the	lives of persons significant in our past;
		X C. Embodies the distin	ctive characteristics of a type, period, or method of
		construction, or rep	resents the work of a master, or that possess high artistic
		values, or represen	ts a significant and distinguishable entity whose components
		may lack individual	distinction; or
		D. Has yielded, or may	be likely to yield, information important in history or
		prehistory.	
		Qualifies under Criter	ia Considerations A through G (see Manual)
		Does not meet any of	the above National Register criteria
		Area(s) of significance: Arc	
		_	1
			onal State LocalX
	42.	_	his house is representative of the early suburban
			adjacent to the original core of the city on previously
			n expanded first on the historic arterial streets and then
			id. This area of town reflects the City's transition, from early
			small scale to larger production style development during
			rugh the automobile was a factor in the location of new
			dest houses that were built did not integrate the car into the
			pan examples were compact houses with simple forms and
		simple materials, based on	traditional styles.


Resource Number:	5ME.14605_	
Temporary Resource	Number:	1315.SIXT

Architectural Inventory Form (page 4 of 4)

43. Assessment of historic physical integrity related to significance is intact, though some of the original materials and details have				
been seriously compromised.				
VII. National Register Eligibility Assessment				
44. National Register eligibility field assessment:				
Eligible Not Eligible _X Need Data	1100 000 010 000			
45. Is there National Register district potential? Yes No _X	Discuss:			
If there is National Register district potential, is this building:	Contributing			
	Noncontributing			
46. If the building is in existing National Register district, is it:	Contributing			
	Noncontributing			
VIII. Recording Information				
47. Photograph numbers: Roll # 5 Frame # 25				
Negatives filed at: City of Grand Junction Planning Dept.				
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005				
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia F	Herron			
51. Organization: Reid Architects, Inc.				
52. Address: PO Box 1303 Aspen, Colorado 81612				
E2 Phana averbanda), 070 020 0225				

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.


Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395



1315 N. 16th Street



Grand Junction, Colorado image from 2002 aerial map



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14605

1315 N. 16th Street

Roll # 5 Frame # 25

Looking northwest

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5882 002927

025

share

57922