OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

	ial eligibility determination
	HP use only)
Date	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District

		1 01 4		Noncontributing to eligible NR District	
I. I	den	tification			
	1.	Resource number:	5ME.14613	puniterina e e e e	
	2.	Temporary resource number:_	1401.SEVT		
	3.	County:	Mesa		
	4.	City:	Grand Junct	ion	
	5.	Historic building name:	n/a		
	6.	Current building name:	n/a		
	7.	Building address:	1401 N. 17th	Street	
	8.	Owner name and address:	Dinah L McC	almont	
	_		1401 N 17th	St Grand Junction, CO 81501-4317	
II.	Ged	ographic Information			
	9.	P.M. <u>Ute Principal Meridian</u>	Townshi	2 1 South Range 1 West	
		<u>NE</u> 1/4 of <u>NW</u> 1/4 of <u>SE</u> 1/4	of <u>SW</u> 1/4 o	f section_12	
	10.	UTM reference			
	Zone 1 2; 7 1 2 2 9 9 mE 4 3 2 8 5 4 7 mN				
11. USGS quad name: Grand Junction Quadrangle				angle	
	Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map section				
12. Lot(s): _6 Block: _1					
		Addition: Parkplace Heights		Year of Addition: 1950	
	13. Boundary Description and Justification: Legal description of the site is: Lot 6 Blk 1				
	Parkplace Heights Exc S 11ft				
	Assessors Office Parcel ID # 2945-123-24-007				
This description was chosen as the most specific and customary description of the si				cific and customary description of the site.	
III.	-Arc	chitectural Description			
	14.	Building plan (footprint, shape):	:_Rectangula	r Plan	
	15.	Dimensions in feet: Length_30	,	x Width 24'	
	16.	Number of stories: 1.5			
	17.	Primary external wall material(s) (enter no m	ore than two): Synthetic Siding	
	18.	Roof configuration: (enter no m	ore than one)	Front Gabled Roof	
	19. Primary external roof material (enter no more than one): Asphalt Roof				
	20. Special features (enter all that apply): Dormer				

Resource Number: 5ME.14613
Temporary Resource Number: 1401.SEVT

Architectural Inventory Form (page 2 of 4)

	21.	General architectural descr	ription: This is a	rectangular wood frame house with a steep			
		front gable roof. The ridge runs east/west and the principal façade faces east. The front					
		gable has a large picture window on the south side, a double hung is located on the north					
		side under a small shed roof addition. A small window is located on the upper level, off					
		center from the peak. The	shed roof additio	n of the north side runs the length of the main			
		volume. The south side has a single entry door just off the corner with a piece of flat roo					
		cantilevering over the door. A series of windows are located on the remainder of the					
		wall. Two large shed dormers are located on the south roof plane. Another shed addition					
		is located on the rear of the house.					
	22.	2. Architectural style/building type: No Style					
	23.	Landscaping or special sett	ting features: Th	e house is close to the street and primarily			
		surrounded by lawn. A large street tree is in front of the house.					
	24.	Associated buildings, featu	res, or objects: <u> </u>	A shed is located at the rear of the site.			
IV.	Ar	chitectural History					
	25.	Date of Construction: Estima	ate: <u>1900</u>	Actual:			
		Source of information:	Mesa County As	ssessors Office			
	26.	Architect:	unknown				
		Source of information:					
	27.	Builder/Contractor:	unknown				
		Source of information:		_ h			
	28.	Original owner:	unknown				
		Source of information:					
	29.	9. Construction history (include description and dates of major additions, alterations, or					
		demolitions):	Additions and a	lterations to windows, addition of dormers,			
	additions to rear and north side; dates unknown.			own.			
	30.	Original location X	_Moved	_Date of move(s):			
V.	His	torical Associations					
	31.	. Original use(s): Domestic, Single Dwelling					
	32.	2. Intermediate use(s):					
	33.	Current use(s):	Domestic, Singl	e Dwelling			
	34.	Site type(s):	Residential Neighbor	hborhood			

Resource Number:	5ME.14613
Temporary Resource Number:	1401.SEVT

Architectural Inventory Form (page 3 of 4)

	35.	Historical background: G. C. Harbert is listed as the owner on the 1951 Parkplace
		Heights plat map. The name Harbert is also associated with a local lumber company that
		was located on North Avenue. James F. Maxwell is listed as the owner in the 1955 and
		56 directories. This building is part of Parkplace Heights Subdivision developed in 1951.
		This area was originally part of the larger Grandview Subdivision.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories 1955, 1956, 1957
VI.	Sid	gnificance
• • •		Local landmark designation: Yes No _X_ Date of designation:
	071	Designating authority:
	38.	Applicable National Register Criteria:
		A. Associated with events that have made a significant contribution to the broad
		pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
		Area(s) of significance: Architecture
		Period of significance: 1900
		Level of significance: National State Local _ X
	42.	Statement of significance: This house is representative of the development that occurred
		adjacent to the original core of the city on agricultural lands. Presently, this area of town
		reflects the City's transition, from agricultural development on a small scale to larger
	42	production style development during more rapid expansion.
	43.	Assessment of historic physical integrity related to significance: Major alterations have
		seriously impacted the original character. Little or no integrity remains.
VII.	Na	ational Register Eligibility Assessment
	44.	National Register eligibility field assessment:
		Eligible Not Eligible X Need Data


Resource Number:		5ME.14613
Temporary Resource	Number:	1401.SEVT

Architectural Inventory Form (page 4 of 4)

45. Is there National Register district potential? Yes No _X	Discuss:			
If there is National Register district potential, is this building:	Contributing			
	Noncontributing			
46. If the building is in existing National Register district, is it:	Contributing			
	Noncontributing			
VIII. Recording Information				
47. Photograph numbers: Roll # 5 Frame # 17				
Negatives filed at: City of Grand Junction Planning Dept.				
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): M	arch 2005			
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H	erron			
51. Organization: Reid Architects, Inc.				
52. Address: PO Box 1303 Aspen, Colorado 81612				
53. Phone number(s): 970 920 9225				

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1401 N. 17th Street



North

Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14613

1401 N. 17th Street

Roll # 5 Frame # 17

Looking southwest

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5882 002927

017

share

57914