OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Official eligibility determination (OAHP use only)

- Date ______Initials _ Determined Eligible- NR Determined Not Eligible- NR Determined Eligible- SR Determined Not Eligible- SR Need Data
- Contributes to eligible NR District
- Noncontributing to eligible NR District

I. Identification

- 1. Resource number: <u>5ME.14789</u>
- 2. Temporary resource number: 540.WAL
- 3. County: <u>Mesa</u>
- 4. City: Grand Junction
- Historic building name: _____n/a___
- Current building name: _____n/a___
- 7. Building address: _____ 540 Walnut Ave.
- 8. Owner name and address: <u>Robert T Crowell</u>

540 Walnut Ave Grand Junction, CO 81501-7438

II. Geographic Information

- 9. P.M. <u>Ute Principal Meridian</u> Township <u>1 South</u> Range <u>1 West</u> <u>SW</u> 1/4 of <u>NE</u> 1/4 of <u>SE</u> 1/4 of <u>NW</u> 1/4 of section <u>11</u>
- 10. UTM reference Zone 1 2; 7 1 0 7 2 7 mE 4 3 2 9 2 3 3 mN
- 11. USGS quad name: <u>Grand Junction Quadrangle</u> Year: <u>1962</u> rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map section.
- 12. Lot(s): <u>16 & 17</u> Block: <u>5</u> Addition: Bookcliff Park _____Year of Addition: <u>1946</u>
- 13. Boundary Description and Justification: Legal description of the site is: W 2ft Of Lot 16 + All Lot 17 Blk 5 Bookcliff Park

Assessors Office Parcel ID # 2945-112-03-017

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape): <u>Irregular Plan</u>
- 15. Dimensions in feet: Length <u>52'</u> x Width <u>61'</u>
- 16. Number of stories: 1
- 17. Primary external wall material(s) (enter no more than two): Aluminum
- 18. Roof configuration: (enter no more than one): Hipped Roof
- 19. Primary external roof material (enter no more than one): Asphalt Roof
- 20. Special features (enter all that apply): Chimney, Carport

22

Resource Number:	5ME.14789
Temporary Resource Number:	540.WAL

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: <u>This is a horizontally proportioned, wood frame house</u> with a moderately pitched hipped roof. The main ridge runs generally east/west and the principal façade faces south. The principal façade is divided by a central hipped roof projection. A single slider window is located on the face of the projection, on the left corner and a vertical row of three small square windows is located on the right. To the left of the projection, another slider window is located on the far corner. On the right side of the projecting volume is a large picture window, flanked by casements on each side. The main entry door is located on the east wall of the projection and a concrete walkway runs along the main volume wall to the east. A thin metal rail runs along the top of a low wall at the edge of the walkway. A shed roof carport is attached to the east side of the main façade. The roof is supported by several pipe columns. A large rectangular chimney is applied to the east façade and appear on the wall surface under the carport roof. A series of additions extend off the rear of the house.
- 22. Architectural style/building type: <u>Ranch Type</u>
- 23. Landscaping or special setting features: <u>The house has several trees and shrubs to each</u> side and the driveway runs up to the carport on the east side. Otherwise the yard is predominantly lawn.
- 24. Associated buildings, features, or objects: none

IV. Architectural History

- 29. Construction history (include description and dates of major additions, alterations, or demolitions): <u>Siding replacement, all windows replaced and openings</u> <u>altered, chimney added; dates unknown.</u>
- 30. Original location___X___Moved____Date of move(s):

V. Historical Associations

- 31. Original use(s): Domestic, Single Dwelling
- 32. Intermediate use(s): ____
- 33. Current use(s): _____ Domestic, Single Dwelling
- 34. Site type(s): Residential Neighborhood

Resource Number:		5ME.14789
Temporary Resource	Number:	540.WAL

Architectural Inventory Form (page 3 of 4)

- 35. Historical background: <u>Harry W. Thornton is shown as owner in the 1955 directory.</u> <u>This is the first instance of this address in the available directories.</u> Tom E. Elder is <u>shown as owner in the 1956 and 1957 directories.</u> This building is part of Bookcliff Park <u>developed in 1946.</u> The owners were Gertrude B. Smith, Claude D. Smith later the U. S. <u>Bank of Grand Junction, and Thomas L. Brownson, Mabel L. Brownson, Bruce Brownson</u> <u>and Mary F. Brownson.</u>
- 36. Sources of information: <u>Mesa County Assessors Office; Museum of Western Colorado</u> <u>Archives; Polk Directories 1955, 1956, 1957</u>

VI. Significance

- 38. Applicable National Register Criteria:
 - **X** A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important in history or prehistory.
 - _____Qualifies under Criteria Considerations A through G (see Manual)
 - _____Does not meet any of the above National Register criteria
- 39. Area(s) of significance: Architecture, Community Development and Planning
- 40. Period of significance: 1950; 1943 to 1957 Uranium Boom
- 41. Level of significance: National _____ State ____ Local X
- 42. Statement of significance: <u>The development in this area is a direct result of the nation's involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier.</u>

Architectural Inventory Form (page 4 of 4)

development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production. In this particular subdivision there are examples of both repetitive house types and more high style individualized houses. The curvilinear street layout is characteristic of national planning trends and is unusual in this community, where new development tended to extend the existing street grid.

43. Assessment of historic physical integrity related to significance: <u>The window replacement</u> has altered original opening proportions and window types. Along with other alterations, the integrity has been seriously compromised. The building no longer contributes to the character of the neighborhood.

VII. National Register Eligibility Assessment

- 44. National Register eligibility field assessment:
 - Eligible ____ Not Eligible _X__ Need Data ___
- 45. Is there National Register district potential? Yes X No

Discuss: The Bookcliff Park Subdivision lies on the periphery of the historic city center and was originally established by single group of investors. The sites were built out to accommodate the rapid growth associated with the Uranium Boom over a short period of time. The architectural styles present in the area represent a significant concentration and continuity of dwellings and a subtle transition of styles over the building period. Few intrusions have been made into the original neighborhood and it retains a high level of integrity.

If there is National Register district potential, is this building:	Contributing
	Noncontributing X
46. If the building is in existing National Register district, is it:	Contributing
	Noncontributing

VIII. Recording Information

47. Photograph numbers: Roll # 7 Frame # 12 & 13

Negatives filed at: City of Grand Junction Planning Dept.

48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005


50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron

- 51. Organization: Reid Architects, Inc.
- 52. Address: PO Box 1303 Aspen, Colorado 81612
- 53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation

1300 Broadway, Denver, CO 80203 (303) 866-3395




540 Walnut Ave.



Grand Junction, Colorado *image from 2002 aerial map*

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004

