OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

Official eligibility determination (OAHP use only) Date Initials . **Determined Eligible- NR** Determined Not Eligible- NR **Determined Eligible- SR Determined Not Eligible- SR** Need Data

- Contributes to eligible NR District
 - Noncontributing to eligible NR District

I. Identification

1. Resource number: ____ 5ME.14608 2. Temporary resource number: 1731.SIXT 3. County: _____ Mesa 4. City: Grand Junction 5. Historic building name: _____ n/a 6. Current building name: _____n/a 7. Building address: 1731 N. 16th Street 8. Owner name and address: Geneva V Hicks 1731 N 16th St Grand Junction, CO 81501-6311

II. Geographic Information

9. P.M.___Ute Principal Meridian ___Township 1 South _____ Range 1 West _____ <u>SW 1/4 of NW 1/4 of NE 1/4 of SW 1/4 of section 12</u>

10. UTM reference Zone <u>1 2; 7 1 2 1 9 0 mE 4 3 2 8 8 9 0 mN</u>

11. USGS quad name: Grand Junction Quadrangle Year: 1962 rev. 1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map section.

12. Lot(s): _7_____ Block: _2___

Addition: Sunnyvale Acres Subdivision Year of Addition: 1946

13. Boundary Description and Justification: Legal description of the site is: Lot 7 Blk 2 Sunnyvale Acres

Assessors Office Parcel ID # 2945-123-06-004

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape): Irregular Plan
- 15. Dimensions in feet: Length_43'_____x Width_48'____
- 16. Number of stories: 1
- 17. Primary external wall material(s) (enter no more than two): Wood Shingle
- 18. Roof configuration: (enter no more than one): Cross Gabled Roof
- 19. Primary external roof material (enter no more than one): Asphalt Roof
- 20. Special features (enter all that apply): Porch, Car port, Chimney

Resource Number:		5ME.14608
Temporary Resource	Number:	1731.SIXT

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: <u>This is a wood frame, primarily side gabled house.</u> <u>The main ridge runs north/south and the principal façade faces east. The main façade is generally divided into three sections. The right side has a front gable projection whose ridge is lower than the main ridge. The center section has a recessed porch which runs the width of the center from the side of the front gable to the drop in the ridge height that defines the third section. A low pitched shed roofed carport is attached to the south side of the building. A large multi-paned picture window is centered on the front gable. The entry door is located on the south wall of the recess and a series of double hungs are on the main wall of the recess. A single double hung is located on the face of the third section, where the wall returns to the line of the main wall. Several concrete steps access the recessed porch in the center and a rail runs up the steps and across each side. The carport is open on three sides. The house sits on a concrete foundation and has a brick chimney on the rear slope of the main roof.</u>
- 22. Architectural style/building type: Minimal Traditional
- 23. Landscaping or special setting features: Lot has large area of concrete paving as well as several shrubs. Otherwise yard is predominantly lawn.
- 24. Associated buildings, features, or objects: none

IV. Architectural History

- 25. Date of Construction: Estimate: <u>1948</u> Actual: _______ Actual: _______ Source of information: <u>Mesa County Assessors Office</u>
- 26. Architect: unknown
 Source of information:
- 27. Builder/Contractor: <u>unknown</u> Source of information:
- 28. Original owner: <u>unknown</u> Source of information: _____
- 29. Construction history (include description and dates of major additions, alterations, or demolitions): ______ Possible window and siding replacement, possible addition to rear, carport added; dates unknown.
- 30. Original location X Moved Date of move(s):

V. Historical Associations

- 31. Original use(s): Domestic, Single Dwelling
- 32. Intermediate use(s): ____
- 33. Current use(s): Domestic, Single Dwelling

Architectural Inventory Form (page 3 of 4)

34. Site type(s): Residential Neighborhood

- 35. Historical background: <u>E. Eugene Hicks is shown as the owner in the 1951, 1955 and 1956 directories. The 1951 listing is the first instance of this address in the available directories. Mother Goose Playschool is listed also in the 1956 directory. This building is part of Sunnyvale Acres and previously part of Grandview Subdivision. In 1946 A. M. Vale was the owner and developer of the 5 acres in the subdivision.</u>
- 36. Sources of information: <u>Mesa County Assessors Office; Museum of Western Colorado</u> Archives; Polk Directories 1951, 1955, 1956, 1957

VI. Significance

- 37. Local landmark designation: Yes ____ No <u>X</u> Date of designation: _____ Designating authority: _____
- 38. Applicable National Register Criteria:
 - X A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important in history or prehistory.
 - Qualifies under Criteria Considerations A through G (see Manual)
 - _____Does not meet any of the above National Register criteria

39. Area(s) of significance: Architecture, Community Development and Planning

- 40. Period of significance: <u>1948; 1943 to 1957 Uranium Boom</u>
- 41. Level of significance: National ____ State ____ Local X___
- 42. Statement of significance: <u>The development in this area is a direct result of the nation's</u> involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass

Architectural Inventory Form (page 4 of 4)

produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production.

43. Assessment of historic physical integrity related to significance: <u>Additions have altered</u> the original scale and material replacement has obscured the original detailing. Integrity is seriously compromised.

VII. National Register Eligibility Assessment

- 44. National Register eligibility field assessment:
 - Eligible ____ Not Eligible _X Need Data _____
- 45. Is there National Register district potential? Yes No X Discuss:
 If there is National Register district potential, is this building: Contributing
 46. If the building is in existing National Register district, is it: Contributing
 Noncontributing
 Noncontributing

VIII. Recording Information

47. Photograph numbers: <u>Roll # 6 Frame # 14</u> Negatives filed at: <u>City of Grand Junction Planning Dept.</u>

48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005

50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron


51. Organization: Reid Architects, Inc.

52. Address: PO Box 1303 Aspen, Colorado 81612

53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs. Colorado Historical Society - Office of Archaeology & Historic Preservation

1300 Broadway, Denver, CO 80203 (303) 866-3395




1731 N. 16th Street



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



