OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

	rial eligibility determination HP use only)
ate	Initials
	Determined Eligible- NR
- 13	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
- 5	Contributes to eligible NR District
	Noncontributing to eligible NR District

			Workcontributing to engine the district
I. I	den	tification	
	1.	Resource number:	5ME.14893
	2.	Temporary resource number:_	1502.ESER
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	1502 E. Sherwood
	8.	Owner name and address:	R G Packard
			1502 E Sherwood Dr Grand Junction, CO 81501-7550
II.	Ged	graphic Information	
	9.	P.M. <u>Ute Principal Meridian</u>	Township 1 South Range 1 West
		_SW_1/4 of_SW_1/4 of_NE_1/	4 of_SW_1/4 of section_11
	10.	UTM reference	
		Zone 1 2; 7 1 0 !	5 2 9 mE 4 3 2 8 5 9 3 mN
	11.	USGS quad name: Grand Ji	unction Quadrangle
		Year: 1962 rev.1973 Map sc	ale: 7.5'_X 15' Attach photo copy of appropriate map section.
	12.	Lot(s): 7 Block: 9	9
		Addition: Sherwood Addition	Year of Addition: 1950
	13.	Boundary Description and Just	ification: Legal description of the site is: Lot 7 Blk 9
		Sherwood Addition	
		Assessors Office Parcel ID # 29	45-113-13-007
		This description was chosen as	the most specific and customary description of the site.
111	Arc	chitectural Description	
		Building plan (footprint, shape)	· Rectangular Plan
			5'x Width54'
			X WidthX
			s) (enter no more than two):_Brick, Aluminum
		Roof configuration: (enter no m	
		_	(enter no more than one): Wood Shake
			apply):_Attached Garage, Porch
	0		

Resource Number: 5ME.14893
Temporary Resource Number: 1502,ESER

Architectural Inventory Form (page 2 of 4)

	21.	. General architectural desc	ription:	<u>This is a basi</u>	cally rectangular wood frame house with
		a moderately pitched hipp	ed_roof7	<u>[he_ridge_run:</u>	s northeast/southwest and the principal
		façade faces northwest. Ti	he main e	ntry is genera	ally centered on the length of the main
		façade and sits at the back	of a deep	recess. A se	ection of hipped roof projects forward on
		the left side of the recess.	A double	hung sits in t	he center of the wall plane on the entry
		side of the projection. The	street fac	ing wall of th	e projection has two sets of three double
		hungs on either end of the	façade ar	nd the northe	ast corner of the wall sets back slightly
		under the roof overhang, a	way from	the street. A	All the windows sit on a brick sill which is
		continuous around the wal	<u>l planes o</u>	f_the_house	The area below the sill is brick and the
		area above is horizontal si	ding. The	<u>main_volum</u>	e wall has three casements centered on
		the remaining wall plane.	The brick	wainscoting	continues across this wall to the wall of
		the garage section. A two	car garag	<u>e door sits in</u>	a field of horizontal siding which
		projects slightly from the n	nain wall	plane. The h	ipped roof in this section has a lower
		ridge and the eave extend	s lower o	ver the garag	e door area. A concrete landing infills
		the recess at the door and	several s	teps run to th	e grade.
	22.	Architectural style/building	type: <u> </u>	lanch Type	
	23.	Landscaping or special set	ting featu	res: <u>A_single</u>	large tree sits directly in front of the
		house. Several shrubs and	d_vines_fro	ont the house	and the wide driveway runs to the
		garage on the southwest s	ide. Othe	rwise the yar	d is predominantly lawn.
	24.	Associated buildings, featu	ires, or ob	jects: none	
IV.	Ar	chitectural History			
	25.	Date of Construction: Estim	ate: <u>1955</u>		Actual:
		Source of information:	Mesa Co	ounty Assesso	ors Office
	26.	Architect:	unknow	n	
		Source of information:			
	27.	Builder/Contractor:	unknow	n	
		Source of information:			No.
	-28.	Original owner:	Harry E.	Williams	
		Source of information:	1956 Po	lk Directory	900
	29.	Construction history (included)	de descrip	tion and date	s of major additions, alterations, or
		demolitions):	Some w	indow replac	ement, siding replacement; dates
		unknown			and All Markets and Baselli state or water conductions.
	30.	Original location X	_Moved_	Date	of move(s):
V.	His	torical Associations			
	31.	Original use(s):	Domesti	c. Single Dwe	elling

Resource Number:	5ME.14893
Temporary Resource Number:	1502.ESER

Architectural Inventory Form (page 3 of 4)

	32.	Intermediate use(s):	
	33.	Current use(s):	Domestic, Single Dwelling
	34.	Site type(s):	Residential Neighborhood
	35.	Historical background:	Harry E. Williams is shown as owner in the 1956 directory.
		This building is part of She	rwood Addition on property owned in 1950 by the Columbine
		Company. The following in	ndividuals were party to the development: C. D. Smith, Jr.,
			o., and William and Dorothy Knoch, John F. Thompson, Robert rnal Howard, William and Belva Cross and E. D. Parmiter.
	36.	Sources of information:	Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories	1955, 1956, 1957
VI.	Sig	gnificance	
	37.	Local landmark designation	n: Yes No _X Date of designation:
		Designating authority:	1000
	38.	Applicable National Regist	er Criteria:
		X A. Associated with eve	ents that have made a significant contribution to the broad
		pattern of our histor	ry;
		B. Associated with the	lives of persons significant in our past;
		X C. Embodies the distin	ctive characteristics of a type, period, or method of
		construction, or rep	resents the work of a master, or that possess high artistic
		values, or represen	ts a significant and distinguishable entity whose components
		may lack individual	distinction; or
		D. Has yielded, or may	be likely to yield, information important in history or
		prehistory.	
		Qualifies under Criter	ria Considerations A through G (see Manual)
		Does not meet any of	the above National Register criteria
	39.	Area(s) of significance: Are	hitecture, Community Development and Planning
	40.	Period of significance: 195	55; 1943 to 1957 Uranium Boom
	41.	Level of significance: Nation	onal State Local X_
	42.	Statement of significance:_	The development in this area is a direct result of the nation's
		involvement in WWII and to	he drive for the development of nuclear weapons. The
		discovery of significant sou	rces of Uranium in the region initiated development in Grand
		Junction that supported bot	th the mining of the materials and the administration of
		programs related to the dev	velopment of weapons. The building types, materials and
		neighborhood layout are al	I indicative of the national trends which were driven by the
		proliferation of the automol	bile and the enormous demand for single family homes.
		House designs departed from	om the romantic and revival styles that were prevalent in the


Resource Number:		5ME.14893
Temporary Resource	Number:	1502.ESER

Architectural Inventory Form (page 4 of 4)

	earlier part of the 20th century and took on a California inspire	<u>a design that was</u>
	characterized by simple horizontally proportioned forms. House	es were typically mass
	produced on previously undeveloped tracts of land at the peri	ohery of earlier
	development. These groups of houses were typically based o	n one or two plan types
	with a limited number of roof and exterior finish variations, fur	ther reinforcing the
	characteristics of mass production. This house is an example	of the more substantial and
	individualized homes that skirt Sherwood Park.	
43	3. Assessment of historic physical integrity related to significance	: Material alterations have
	had a moderate impact on the integrity of the house.	
VII. N	lational Register Eligibility Assessment	
44	. National Register eligibility field assessment:	
	Eligible Not Eligible _X Need Data	
45	. Is there National Register district potential? Yes No _X	Discuss:
	If there is National Register district potential, is this building:	Contributing
		Noncontributing
46	i. If the building is in existing National Register district, is it:	Contributing
		Noncontributing
VIII. I	Recording Information	Noncontributing
	_	Noncontributing
	_	
47	. Photograph numbers: Roll # 13 Frame # 10	
47 48	. Photograph numbers: Roll # 13 Frame # 10 Negatives filed at: City of Grand Junction Planning Dept.	arch 2005
47 48 50	. Photograph numbers: Roll # 13 Frame # 10 Negatives filed at: City of Grand Junction Planning Dept. Report title: Grand Junction Phase 3 Survey 49. Date(s): M	arch 2005 erron
47 48 50 51	. Photograph numbers: Roll # 13 Frame # 10 Negatives filed at: City of Grand Junction Planning Dept. Report title: Grand Junction Phase 3 Survey 49. Date(s): M Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H	arch 2005 erron


Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395

photographs.




1502 E. Sherwood Ave.





GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14893 1502 E. Sherwood Roll # 13 Frame # 10 Looking southeast

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN- 1 5648 002911

011

share

54599