

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

Official eligibility determination (OAHP use only)

Date _____ Initials _____

- Determined Eligible- NR
- Determined Not Eligible- NR
- Determined Eligible- SR
- Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District
- Noncontributing to eligible NR District

I. Identification

1. Resource number: 5ME.14901
2. Temporary resource number: 461.NSER
3. County: Mesa
4. City: Grand Junction
5. Historic building name: n/a
6. Current building name: n/a
7. Building address: 461 N. Sherwood Ave.
8. Owner name and address: Evelyn Willis
461 N Sherwood Dr Grand Junction, CO 81501-2174

II. Geographic Information

9. P.M. Ute Principal Meridian Township 1 South Range 1 West
SE 1/4 of SW 1/4 of NE 1/4 of SW 1/4 of section 11
10. UTM reference
Zone 1 2 ; 7 1 0 5 9 7 mE 4 3 2 8 6 4 2 mN
11. USGS quad name: Grand Junction Quadrangle
Year: 1962 rev. 1973 Map scale: 7.5' X 15' *Attach photo copy of appropriate map section.*
12. Lot(s): 11 Block: 9
Addition: Sherwood Addition Year of Addition: 1950
13. Boundary Description and Justification: Legal description of the site is: Lot 11 Blk 9
Sherwood Addition
Assessors Office Parcel ID # 2945-113-13-011
This description was chosen as the most specific and customary description of the site.

III. Architectural Description

14. Building plan (footprint, shape): Rectangular Plan
15. Dimensions in feet: Length 31' x Width 60'
16. Number of stories: 1
17. Primary external wall material(s) (enter no more than two): Brick
18. Roof configuration: (enter no more than one): Cross Gabled Roof
19. Primary external roof material (enter no more than one): Asphalt Roof
20. Special features (enter all that apply): Chimney, Carport, Porch

Architectural Inventory Form
(page 2 of 4)

21. General architectural description: This is a long masonry house with a low pitched gable roof. The main ridge runs generally east/west and the principal façade faces generally north. The main side gable roof has a front gable off center to the right along its length. The face of the front gable maintains the wall plane of the main side wing. A picture window, flanked by double hungs sits in the center of the front gable. A pair of double hungs sit on the far right corner of the side wing. The main side wing wall is recessed under the side gable roof, beginning at the east end of the front gable. The main entry sits on the street facing wall at the right side of the recess and a picture window, flanked by double hungs, is centered on the remaining wall to the left of the door. A tall rectangular brick chimney penetrates the side gable roof plane just off the right side of the entry door. The side gable roof continues to the east covering the carport area on the east end of the house. Four pipe columns support the end of the roof. A concrete landing infills the recess under the main roof and a single post sits on the right side of the carport along the main eave. Diagonal siding infills the gable ends above the eave line, the diagonals mimic the roof shape and have scalloped ends where they overlap the brick wall. Single double hungs are located on the corners of the west façade. All the double hungs have a single horizontal muntin in each sash.
22. Architectural style/building type: Ranch Type
23. Landscaping or special setting features: Several shrubs front the house and a couple of trees are located in the yard, in addition to the street trees. The driveway runs to the carport on the east and a diagonal walk runs from the drive to the entry steps. Otherwise the yard is predominantly lawn.
24. Associated buildings, features, or objects: none

IV. Architectural History

25. Date of Construction: Estimate: 1954 Actual: _____
Source of information: Mesa County Assessors Office
26. Architect: unknown
Source of information: _____
27. Builder/Contractor: unknown
Source of information: _____
28. Original owner: Robert V. Smith
Source of information: 1955 Polk Directory
29. Construction history (include description and dates of major additions, alterations, or demolitions): No major alterations are apparent.
30. Original location Moved _____ Date of move(s): _____

Resource Number: 5ME.14901
Temporary Resource Number: 461.NSER

Architectural Inventory Form
(page 3 of 4)

V. Historical Associations

31. Original use(s): Domestic, Single Dwelling
32. Intermediate use(s): _____
33. Current use(s): Domestic, Single Dwelling
34. Site type(s): Residential Neighborhood
35. Historical background: Robert V. Smith is shown as owner in the directories of 1955, 1956 and 1957. This building is part of Sherwood Addition on property owned in 1950 by the Columbine Company. The following individuals were party to the development: C. D. Smith, Jr., Frank Hall for Columbine Co., and William and Dorothy Knoch, John F. Thompson, Robert and Nora Kyle, Charles Bernal Howard, William and Belva Cross and E. D. Parmiter.
36. Sources of information: Mesa County Assessors Office; Museum of Western Colorado Archives; Polk Directories 1955, 1956, 1957

VI. Significance

37. Local landmark designation: Yes No Date of designation: _____
Designating authority: _____
38. Applicable National Register Criteria:
- A. Associated with events that have made a significant contribution to the broad pattern of our history;
- B. Associated with the lives of persons significant in our past;
- C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
- D. Has yielded, or may be likely to yield, information important in history or prehistory.
- Qualifies under Criteria Considerations A through G (see Manual)
- Does not meet any of the above National Register criteria
39. Area(s) of significance: Architecture, Community Development and Planning
40. Period of significance: 1954; 1943 to 1957 Uranium Boom
41. Level of significance: National State Local
42. Statement of significance: The development in this area is a direct result of the nation's involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and

Resource Number: 5ME.14901
Temporary Resource Number: 461.NSER

Architectural Inventory Form
(page 4 of 4)

neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production. This house is an example of the more substantial and individualized homes that skirt Sherwood Park.

43. Assessment of historic physical integrity related to significance: The house is apparently intact in original condition.

VII. National Register Eligibility Assessment

44. National Register eligibility field assessment:

Eligible Not Eligible Need Data

45. Is there National Register district potential? Yes No Discuss: _____

If there is National Register district potential, is this building: Contributing _____

Noncontributing _____

46. If the building is in existing National Register district, is it: Contributing _____

Noncontributing _____

VIII. Recording Information

47. Photograph numbers: Roll # 13 Frame # 7

Negatives filed at: City of Grand Junction Planning Dept.

48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005

50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron


51. Organization: Reid Architects, Inc.

52. Address: PO Box 1303 Aspen, Colorado 81612

53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation
1300 Broadway, Denver, CO 80203 (303) 866-3395



Mesa Court

North Sherwood

5ME.14901

Elm Court

East Sherwood


461 N. Sherwood Ave.




North

Grand Junction, Colorado
image from 2002 aerial map

City of Grand Junction • Phase Three Survey
2004



TN MN
11 1/2°



Map created with TOPO!® ©2003 National Geographic (www.nationalgeographic.com/topo)

GRAND JUNCTION, COLORADO

Phase Three Historic Survey
2004

5ME.14901

461 N. Sherwood

Roll # 13 Frame # 7

Looking south

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN- 1 5648 002911

008

sharp

54596

