OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

	ial eligibility determination
	HP use only)
)ate	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
-07	Contributes to eligible NR District
	Name and discretions an alimible ND District

1. 1	den	tification	
	1.	Resource number:	5ME.8870
	2.	Temporary resource number:_	1325.SEV
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	1325 N. 7th Street
	8.	Owner name and address:	Lee Ann Blaney
	_		1635 Maple Ct Grand Junction, CO 81505-1582
11.	Ged	ographic Information	
			Township_1 South Range_1 West
SW 1/4 of NW 1/4 of SW 1/4 of SE 1/4 of section 11			
	10.	UTM reference	
		Zone 1 2; 7 1 0	9 4 0 mE 4 3 2 8 4 9 5 mN
	11.		unction Quadrangle
			cale: 7.5'_X_ 15' Attach photo copy of appropriate map section
	12.	Lot(s): 19 Block:	
			Year of Addition: 1898
	13.		ification: Legal description of the site is: S 39ft Of N 125ft
		Of Lot 19 Capitol Hill Sub Sec	11_1s_1w
Assessors Office Parcel ID # 2945-114-00-042			45-114-00-042
		This description was chosen as	the most specific and customary description of the site.
111.	Arc	chitectural Description	
	14.	Building plan (footprint, shape)	: Rectangular Plan
	15.	Dimensions in feet: Length 38'	x Width 24'
	16.	Number of stories: 1	
	17.	Primary external wall material	s) (enter no more than two): Wood Horizontal Siding
	18.	Roof configuration: (enter no m	ore than one): Hipped Roof
	19.	Primary external roof material	(enter no more than one): Asphalt Roof
	20.	Special features (enter all that	apply): Porch, Dormer

Resource Number:		5ME.8870
Temporary Resource	Number:	1325.SEV

Architectural Inventory Form (page 2 of 4)

	21.	. General architectural desci	ription: This is a simple symmetrical wood frame house with a
		steeply pitched hipped roo	f. The ridge runs east/west and the principal façade faces east.
		A single hipped roof dorme	er is centered on the main roof plane with a pair of casement
		windows in the center of th	e dormer wall. A hipped roof porch is applied to the face of
		the main wall. The entry d	oor is generally centered on the main wall and two vertically
		proportioned double hung	windows are located to either side. The porch roof is
		supported by four equally s	spaced square posts and two pilaster at the main wall plane. A
		low wall runs between the	posts with small sections on either side of the walkway to the
		door. A door frame is locat	ted in the central column bay. A pair of double hungs is
		centered on the south wall	and similar single units are located to each side. The north
		side has smaller double hu	ng units. A single concrete step fronts the entry way.
	22.	Architectural style/building	type: Hipped Box
	23.	Landscaping or special sett	ting features: Driveways run to each side of the house and the
		lawn is sporadic.	
	24.	Associated buildings, featu	res, or objects: A shed sits at the rear of the site.
IV.	Ar	chitectural History	¥E
	25.	Date of Construction: Estimate	ate: 1909 Actual:
		Source of information:	Mesa County Assessors Office
	26.	Architect:	unknown
		Source of information:	
	27.	Builder/Contractor:	unknown
		Source of information:	
	28.	Original owner:	unknown
		Source of information:	
	29.	Construction history (includ	e description and dates of major additions, alterations, or
		demolitions):	Alterations to the porch posts and details, some possible
		window alterations; dates u	nknown.
	30.	Original location X	_MovedDate of move(s):
V.	His	torical Associations	
	31.	Original use(s):	Domestic, Single Dwelling
	32.	Intermediate use(s):	
		Intermediate use(s): Current use(s):	Domestic, Single Dwelling

Resource Number:	5ME.8870
Temporary Resource Number:	1325.SEV

Architectural Inventory Form (page 3 of 4)

	35.	Historical background: Newton E. Joy is listed as the owner in the 1926 Polk
		Directory. The Joy name is associated with a number of properties in this section of
		North 7th Street over the years. Frank Robberson is listed as the owner in 1931
		directory. Herbert P. Lambert is listed as the occupant in 1941. Verna M. Nugent is listed
		as the owner in 1951 and Harry E. Wall is listed as the occupant in 1955, and 1956. This
		building is part of the Capitol Hill Subdivision. In October 1898 the subdivision was
		developed by Charles B. Rich and Monroe L. Allison, trustees of the estate of town
		founder, George Crawford. They laid out a very large property that encompassed the
		majority of the acreage from today's 7th Street to 12th Street between North Avenue and
		Patterson Avenue.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories 1926, 1931, 1941, 1951, 1955, 1956, 1957
VI.	Sig	gnificance
	37.	Local landmark designation: Yes No _X Date of designation:
		Designating authority:
	38.	Applicable National Register Criteria:
		A. Associated with events that have made a significant contribution to the broad
		pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
		Area(s) of significance: Architecture
		Period of significance: 1909
		Level of significance: National State LocalX
	42.	Statement of significance: This house is representative of the development that occurred
		adjacent to the original core of the city on agricultural lands. This house sits on a
		historically arterial street. Presently, this area of town reflects the City's transition, from
		agricultural development on a small scale to larger production style development during
		more rapid expansion.


Resource Number:	_5ME.8870
Temporary Resource Number:	1325.SEV

Architectural Inventory Form (page 4 of 4)

	storic physical integrity related to significance			
moderate impact	on the integrity.			
VII. National Register	Eligibility Assessment			
44. National Register	r eligibility field assessment:			
Eligible N	ot Eligible <u>X</u> Need Data			
45. Is there National	Register district potential? Yes No _X	Discuss:		
If there is Nationa	al Register district potential, is this building:	Contributing		
		Noncontributing		
46. If the building is i	n existing National Register district, is it:	Contributing		
		Noncontributing		
VIII. Recording Inform	ation			
47. Photograph numb	pers: Roll # 9 Frame # 35			
Negatives filed at: City of Grand Junction Planning Dept.				
48. Report title: Gra	48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005			
50. Recorder(s):	Suzannah Reid, Patrick Duffield and Lydia H	lerron		
51. Organization:	Reid Architects, Inc.			
52. Address:	PO Box 1303 Aspen, Colorado 81612			
53. Phone number(s)	970 920 9225			

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1325 N. 7th Street



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.8870

1325 N. 7th Street

Roll # 9 Frame # 35 Looking northwest Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN+ 1 5883 002928

036

share

57970