OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

# Architectural Inventory Form I of 4

	rial eligibility determination HP use only)
Date	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District
	Noncontributing to eligible NR District

ı.	lder	ntification		
	1.	Resource number:	5ME.8878	
	2.		1337.SEV	
	3.		Mesa	
	4.		Grand Junction	
	5.		n/a	
	6.	Current building name:	n/a	
	7.	Building address:	1337 N. 7th Street	
	8.	Owner name and address:	Pamela S Noonan	
	_			
II.	Ged	ographic Information		
9. P.M. <u>Ute Principal Meridian</u> Township 1 South R		P.M. <u>Ute Principal Meridian</u>	Township_1 SouthRange_1 West	
			/4 of_SE_1/4 of section_11	
10. UTM reference  Zone 1 2; 7 1 0 9 4 0 mE 4 3 2 8 5  11. USGS quad name: Grand Junction Quadrangle  Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of a				
			9 4 0 mE 4 3 2 8 5 1 6 mN	
			unction Quadrangle	
	12.	Lot(s): 19 Block:		
			Year of Addition: 1898	
13. Boundary Description and Justification: Legal description of the site is: N				
			<del>15-114-00-026</del>	
			the most specific and customary description of the site.	
.111	Arc	chitectural Description		
14. Building plan (footprint, shape): T-Shaped Plan			T-Shaped Plan	
15. Dimensions in feet: Length 38' x Width 33'  16. Number of stories: 1		x Width_33'		
		Number of stories: 1		
			s) (enter no more than two): Wood Horizontal Siding	
	18.	3. Roof configuration: (enter no more than one): Cross Gabled Roof		
	19.	Primary external roof material (	enter no more than one): Asphalt Roof	
		Special features (enter all that a		

Resource Number:	5ME.8878	
Temporary Resource	Number:	1337.SEV

## Architectural Inventory Form (page 2 of 4)

	21.	. General architectural descr	ription: This is a simple wood frame house with a moderately		
		pitched gable roof. The house consists of a main front gable form, running east/west, with			
		a side gable wing projectin	g off the north wall. The principal façade faces east and is		
		symmetrical over the gable	end. The entry door is centered on the peak, three casement		
		windows fill the width of the	e wall to either side of the door. Similar windows wrap the		
	corners on the north and south sides. A low wall runs under all the windows with vert				
		siding. A small gable sits above the door at the entry. Two vertically proportioned			
		double hung windows sit on the south wall. The side gable has a pair of double hungs o			
		the east wall. The roof has a moderate overhang and the rafters are exposed behind a			
		continuous fascia board. A brick chimney sits on the ridge about halfway back.			
	22.	2. Architectural style/building type: No Style			
	23.	3. Landscaping or special setting features: A driveway runs along the south side and a long			
		hedge runs across the sidewalk. The front and side yard have several shrubs, otherwise			
		the yard is predominantly lawn.			
	24.	4. Associated buildings, features, or objects: small shed. Per owner this was originally a			
		coal shed.			
IV.	Ar	chitectural History			
		•	ate: 1924 Actual:		
	25.	Date of Construction: Estimation:	Mesa County Assessors Office		
	25.	Date of Construction: Estimation:			
	25.	Date of Construction: Estime Source of information:  Architect:	Mesa County Assessors Office		
	25. 26.	Date of Construction: Estime Source of information: Architect: Source of information:	Mesa County Assessors Office unknown		
	25. 26.	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor:	Mesa County Assessors Office unknown		
	<ul><li>25.</li><li>26.</li><li>27.</li></ul>	Date of Construction: Estimation: Source of information: Architect: Source of information: Builder/Contractor: Source of information:	Mesa County Assessors Office unknown unknown		
	<ul><li>25.</li><li>26.</li><li>27.</li><li>28.</li></ul>	Date of Construction: Estimation: Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information:	Mesa County Assessors Office unknown unknown		
	<ul><li>25.</li><li>26.</li><li>27.</li><li>28.</li></ul>	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (include	Mesa County Assessors Office unknown unknown unknown e description and dates of major additions, alterations, or		
	<ul><li>25.</li><li>26.</li><li>27.</li><li>28.</li></ul>	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions):	Mesa County Assessors Office unknown  unknown  unknown  e description and dates of major additions, alterations, or Original porch enclosed; date unknown. Additions to the rear		
	<ul><li>25.</li><li>26.</li><li>27.</li><li>28.</li><li>29.</li></ul>	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): in two stages; one possibly	Mesa County Assessors Office unknown  unknown  unknown  e description and dates of major additions, alterations, or Original porch enclosed; date unknown. Additions to the rear early, the second in the 50's		
	<ul><li>25.</li><li>26.</li><li>27.</li><li>28.</li><li>29.</li></ul>	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): in two stages; one possibly	Mesa County Assessors Office unknown  unknown  unknown  e description and dates of major additions, alterations, or Original porch enclosed; date unknown. Additions to the rear		
	<ul><li>25.</li><li>26.</li><li>27.</li><li>28.</li><li>29.</li><li>30.</li></ul>	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): in two stages; one possibly Original location X	Mesa County Assessors Office unknown  unknown  unknown  e description and dates of major additions, alterations, or Original porch enclosed; date unknown. Additions to the rear early, the second in the 50's		
	<ul><li>25.</li><li>26.</li><li>27.</li><li>28.</li><li>29.</li><li>30.</li><li>His</li></ul>	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): in two stages; one possibly Original location X	Mesa County Assessors Office unknown  unknown  e description and dates of major additions, alterations, or Original porch enclosed; date unknown. Additions to the rear early, the second in the 50's  MovedDate of move(s):		
	25. 26. 27. 28. 29. 30. His	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): in two stages; one possibly Original location X  storical Associations Original use(s):	Mesa County Assessors Office unknown  unknown  unknown  e description and dates of major additions, alterations, or Original porch enclosed; date unknown. Additions to the rear early, the second in the 50's		
	25. 26. 27. 28. 29. 30. His 31. 32.	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): in two stages; one possibly Original location X  Storical Associations Original use(s): Intermediate use(s):	Mesa County Assessors Office unknown  unknown  e description and dates of major additions, alterations, or Original porch enclosed; date unknown. Additions to the rear early, the second in the 50's  Moved Date of move(s):  Domestic, Single Dwelling		
	25. 26. 27. 28. 29. 30. His 31. 32. 33.	Date of Construction: Estime Source of information: Architect: Source of information: Builder/Contractor: Source of information: Original owner: Source of information: Construction history (included demolitions): in two stages; one possibly Original location X  storical Associations Original use(s):	Mesa County Assessors Office unknown  unknown  e description and dates of major additions, alterations, or Original porch enclosed; date unknown. Additions to the rear early, the second in the 50's  MovedDate of move(s):		

Resource Number:	5ME.8878
Temporary Resource Number:	1337.SEV

## Architectural Inventory Form (page 3 of 4)

	35.	Historical background: Robert E. Smith is listed as the owner in 1926. Charles M.
		Porter is listed as the owner in 1931. Homer E. Tippet is listed as the occupant in 1941.
		Charles K. Rockwood is listed as the occupant in 1951, 1955, and 1956. This building is
		part of the Capitol Hill Subdivision. In October 1898 the subdivision was developed by
		Charles B. Rich and Monroe L. Allison, trustees of the estate of town founder, George
		Crawford. They laid out a very large property that encompassed the majority of the
		acreage from today's 7th Street to 12th Street between North Avenue and Patterson
		Avenue.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories 1926, 1931, 1941, 1951, 1955, 1956, and 1957
VI.	Sic	gnificance
		Local landmark designation: Yes No _X Date of designation:
		Designating authority:
	38.	Applicable National Register Criteria:
		A. Associated with events that have made a significant contribution to the broad
		pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		·
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
	20	Does not meet any of the above National Register criteria
		Area(s) of significance: Architecture
		Period of significance: 1924
		Level of significance: National State Local X
	42.	Statement of significance: This house is representative of the development that occurred
		adjacent to the original core of the city on agricultural lands. This house sits on a
		historically arterial street. Presently, this area of town reflects the City's transition, from
		agricultural development on a small scale to larger production style development during
	5	more rapid expansion.
	43.	Assessment of historic physical integrity related to significance: Alterations have
		removed or obscured original character defining features. Integrity is seriously
		compromised.

Resource Number:		5ME.8878
Temporary Resource	Number:	1337.SEV


53. Phone number(s): 970 920 9225

#### Architectural Inventory Form (page 4 of 4)

VII. National Register Eligibility Assessment				
VII. IVATIONAL REGISTER ELIGIDINITY ASSESSMENT				
44. National Register eligibility field assessment:				
Eligible Not EligibleX Need Data				
45. Is there National Register district potential? Yes No _X_	Discuss:			
If there is National Register district potential, is this building:	Contributing			
	Noncontributing			
46. If the building is in existing National Register district, is it:	Contributing			
	Noncontributing			
VIII. Recording Information				
47. Photograph numbers: Roll # 9 Frame # 33				
Negatives filed at: City of Grand Junction Planning Dept.				
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005				
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H	lerron			
51. Organization: Reid Architects, Inc.				
E2 Address: PO Poy 1202 Aspen Colorado 91612				

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




# 1337 N. 7th Street



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



#### GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.8878

1337 N. 7th Street

**Roll #9** Frame #33

Looking west

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN+ 1 5883 002928

034

share

57968