OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Official eligibility determination (OAHP use only) Date ______ Initials

- Date _____ Init ____ Determined Eligible- NR ____ Determined Not Eligible- NR
- Determined Eligible- SR Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District
- Noncontributing to eligible NR District

I. Identification

- 1. Resource number: _____ 5ME.14910
- 2. Temporary resource number: 120.TEX
- 3. County: <u>Mesa</u>
- 4. City: Grand Junction
- 5. Historic building name: ______n/a___
- Current building name: <u>n/a</u>
- 7. Building address: <u>120 Texas Ave.</u>
- 8. Owner name and address: <u>Thomas John Ziola</u>

120 Texas Ave Grand Junction, CO 81501-2170

II. Geographic Information

9. P.M. <u>Ute Principal Meridian</u> Township_<u>1_South</u> Range_<u>1 West</u> _<u>NW_</u>1/4 of_<u>SW_</u>1/4 of_<u>NW_</u>1/4 of_<u>SW_</u>1/4 of section_<u>11</u>_____

10. UTM reference Zone <u>1 2 ; 7 1 0 1 7 6 mE 4 3 2 8 6 9 9 mN</u>

- 11. USGS quad name: <u>Grand Junction Quadrangle</u> Year: <u>1962_rev.1973</u> Map scale: 7.5'_X_ 15'__ Attach photo copy of appropriate map section.
- 12. Lot(s): _____ Block: __6_____

 Addition: __Sherwood Addition

 Year of Addition: __1950 ______

13. Boundary Description and Justification: Legal description of the site is: Lot 21 Blk 6 Sherwood Addition

Assessors Office Parcel ID # 2945-113-03-019

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape): Rectangular Plan
- 15. Dimensions in feet: Length 33' x Width 57'
- 16. Number of stories:__1_____
- 17. Primary external wall material(s) (enter no more than two): Brick
- 18. Roof configuration: (enter no more than one): Hipped Roof
- 19. Primary external roof material (enter no more than one): Metal Roof
- 20. Special features (enter all that apply): Porch

Resource Number: <u>5ME.14910</u> Temporary Resource Number: <u>120.TEX</u>

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: <u>This is a simple horizontally proportioned wood frame house with a moderately pitched hipped roof.</u> The main ridge runs east/west and the principal façade faces south. A shallow projecting volume sits on the west side of the main façade and is covered with a hipped roof. The projection shares the west wall and roof plane with the main roof and covers over half the length of the principal façade. The southeast corner of the projection is recessed back to the main wall, creating a deep overhang at the main entry. The south wall of the projection has a picture window, flanked by sliders, near the right side and a set of three equal slider windows on the left. The main entry door is centered on the recess and a large three over two picture window sits on the eastern corner of the main façade. A concrete landing infills the area of the recess and four steps run to grade off the face of the projecting volume. A small shed roof addition extends off the rear of the west façade. The addition has a central picture window, flanked by sliders, in a field of board and batten siding. The brick wall surface of the main house has contrasting brick quoins on the corners of the volumes.
- 22. Architectural style/building type: <u>Ranch Type</u>
- 23. Landscaping or special setting features: <u>Several planting areas are scattered around the</u> site and in front of the house. A driveway runs to the addition on the west. The remainder of the yard is red sand.
- 24. Associated buildings, features, or objects: none

IV. Architectural History

- 25. Date of Construction: Estimate: <u>1955</u> Actual: _______ Source of information: _____ Mesa County Assessors Office
- 26. Architect: _____unknown _____ Source of information: _____
- 27. Builder/Contractor: _____unknown _____ Source of information: _____
- 28. Original owner: Frank M. Byers
 Source of information: 1956 Polk directory
- 29. Construction history (include description and dates of major additions, alterations, or demolitions): Addition to side (may have replaced or altered original carport), metal roof: dates unknown
- 30. Original location X Moved Date of move(s):

V. Historical Associations

- 31. Original use(s): Domestic, Single Dwelling
- 32. Intermediate use(s):

Resource Number: <u>5ME.14910</u> Temporary Resource Number: <u>120.TEX</u>

Architectural Inventory Form (page 3 of 4)

- 33. Current use(s): Domestic, Single Dwelling
- 34. Site type(s): _____ Residential Neighborhood
- 35. Historical background: <u>Frank M, Byers is shown as owner in the directories of 1956</u> and 1957. This building is part of Sherwood Addition on property owned in 1950 by the <u>Columbine Company</u>. The following individuals were party to the development: C. D. <u>Smith, Jr., Frank Hall for Columbine Co., and William and Dorothy Knoch, John F.</u> <u>Thompson, Robert and Nora Kyle, Charles Bernal Howard, William and Belva Cross and E. D. Parmiter.</u>
- 36. Sources of information: <u>Mesa County Assessors Office; Museum of Western</u> <u>Colorado Archives; Polk Directories 1955, 1956, 1957</u>

VI. Significance

- 37. Local landmark designation: Yes ____ No _X ___ Date of designation: ______ Designating authority: _____
- 38. Applicable National Register Criteria:
 - X A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important in history or prehistory.
 - Qualifies under Criteria Considerations A through G (see Manual)
 - Does not meet any of the above National Register criteria
- 39. Area(s) of significance: Architecture, Community Development and Planning
- 40. Period of significance: 1955; 1943 to 1957 Uranium Boom
- 41. Level of significance: National _____ State ____ Local X
- 42. Statement of significance: <u>The development in this area is a direct result of the nation's</u> <u>involvement in WWII and the drive for the development of nuclear weapons. The</u> <u>discovery of significant sources of Uranium in the region initiated development in Grand</u> <u>Junction that supported both the mining of the materials and the administration of</u> <u>programs related to the development of weapons. The building types, materials and</u> <u>neighborhood layout are all indicative of the national trends which were driven by the</u> <u>proliferation of the automobile and the enormous demand for single family homes.</u> <u>House designs departed from the romantic and revival styles that were prevalent in the</u>

Architectural Inventory Form (page 4 of 4)

earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production.

43. Assessment of historic physical integrity related to significance: <u>Alterations have had a</u> <u>moderate impact on the integrity.</u>

VII. National Register Eligibility Assessment

44. National Register eligibility field assessment: Eligible _____ Not Eligible _X___ Need Data _____

:uss:
tributing
contributing
tributing
contributing

VIII. Recording Information

47. Photograph numbers: Roll # 12 Frame # 13

Negatives filed at: <u>City of Grand Junction Planning Dept.</u>

48. Report title: <u>Grand Junction Phase 3 Survey</u> 49. Date(s): <u>March 2005</u>

50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron


51. Organization: Reid Architects, Inc.

52. Address: PO Box 1303 Aspen, Colorado 81612

53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395



120 Texas Ave.



Grand Junction, Colorado *image from 2002 aerial map*

City of Grand Junction • Phase Three Survey 2004



Map created with TOPOI® @2003 National Geographic (www.nationalgeographic.comAopo)

GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



