OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

# Architectural Inventory Form

l of 4

λH ₃	P use only)
_	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
ı	Contributes to eligible NR District
	Noncontributing to eligible NR District

<b>I.</b>	lden	tification				
	1.	Resource number:	5ME.2838			
	2.	Temporary resource number:	3095.DHR			
	3.	County:	Mesa			
	4.	City:	Grand Junction			
	5.	Historic building name:	n/a			
	6.	Current building name:	n/a			
	7.	Building address:	3095 D.5 Road			
	8.	Owner name and address:	Steven W Miller			
	-		3095 D 1/2 Rd Grand Junction, CO 81504-2590			
II.		ographic Information				
	9.	P.M. <u>Ute Principal Meridian</u>	Township <u>1 South</u> Range <u>1 East</u>			
		NE_1/4 of_NE_1/4 of_NE_1/4	of_SE_1/4 of section_16			
	10.	. UTM reference				
		Zone 1 2; 7 1 8	0 5 8 mE 4 3 2 7 5 5 1 mN			
	11.	11. USGS quad name: Grand Junction Quadrangle				
		Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map section				
	12.	12. Lot(s): Block:				
		Addition:Year of	Addition:			
	13.	13. Boundary Description and Justification: Legal description of the site is: N 16a E2 NE4				
		SE4 Sec 16 1S 1E				
		Assessors Office Parcel ID # 29	943-164-00-056			
		This description was chosen as	the most specific and customary description of the site.			
101.	Ar	chitectural Description				
		4. Building plan (footprint, shape): <u>Irregular Plan</u>				
			x Width 28'			
		16. Number of stories: 1.5				
			(s) (enter no more than two): Wood Horizontal Siding;			
		Plywood/Particle Board				
	18		ore than one): Side Gabled Roof			
		-	(enter no more than one): Metal Roof			
		Special features (enter all that				
	20.	Special features (enter all that	apply): Porch, Chimney			

Resource Number:	5ME.2838
Temporary Resource Number:	3095.DHR

### Architectural Inventory Form (page 2 of 4)

	21.	General architectural description: This is a narrow one and one half story wood frame
		side gable house. The main ridge runs east/west and the principal façade faces north. A
		small gable dormer sits in the center of the principal façade on the main roof. The main
		wall continues into the dormer and a single vertically proportioned door is centered on
		the dormer gable on the upper level. A smaller vertically proportioned double hung
		window is located on either side of the dormer and equally spaced along the wall. A
		hipped roof porch is applied to the main wall on the lower level. The porch roof stops
		short of the corners of the building and is depressed under the dormer door. The porch
		roof is supported by four equally spaced Tuscan columns. The columns have simple
		bases and capitals which support a shallow entablature. There are four equally spaced
		openings along the length of the wall under the porch roof. The center left opening is the
		entry door, which is balanced on the right by a single similarly sized double hung window
		on the right. A single wider double hung window sits on the wall to the right and left of
		these openings. The double hung windows all have unequal sashes with a narrow panel
		on the top. Each side of the main form has two vertically proportioned double hung
		windows, one on each level, centered on the gable end. The main roof has a moderate
		overhand with small eave returns on the gable ends. A brick chimney sits just off the
		main ridge on the south side of the roof. A one story, lower pitched gable form is
		attached to the rear of the house. The east side has an additional shed roof addition
		which extends beyond the east wall of the house. The addition has fixed glass windows
		on the southeast corner.
	22.	Architectural style/building type: No Style
	23.	Landscaping or special setting features: The house sits on a large open lot with several
		large trees surrounding the house.
	24.	Associated buildings, features, or objects: Several sheds and a garage are located on the
		site.
IV.	Ar	chitectural History
	25.	Date of Construction: Estimate: 1895 Actual:
		Source of information: Mesa County Assessors Office
	26.	Architect:unknown
		Source of information:
	27.	Builder/Contractor:unknown
		Source of information:
	28.	Original owner: unknown
		Source of information:

Resource Number:	5ME.2838
Temporary Resource	Number: 3095.DHR

### Architectural Inventory Form (page 3 of 4)


	29. Construction history (include	de description	and dates of major additions, alterations, or
	demolitions):	Siding repla	acement, addition at rear; dates unknown
	30. Original location X	Moved	Date of move(s):
	Historia I Associations		
W.	Historical Associations	Damantia 6	Single Develling
	-		Single Dwelling
	32. Intermediate use(s):		Market Brown III and
			Single Dwelling
			s combined with adjacent areas of recent
	suburban development		
			associations were found
			ty Assessors Office; Museum of Western Colorado
	Archives; Polk Directories		
VI.	. Significance		
			No X Date of designation:
	Designating authority:		
	38. Applicable National Regist		
	X A. Associated with ev pattern of our histo		e made a significant contribution to the broad
	B. Associated with the	e lives of pers	sons significant in our past;
	X C. Embodies the distir	nctive charact	teristics of a type, period, or method of
	construction, or rep	resents the w	vork of a master, or that possess high artistic
	values, or represer	nts a significa	nt and distinguishable entity whose components
	may lack individua	I distinction;	or
	D. Has yielded, or may	y be likely to	yield, information important in history or
	prehistory.		
	Qualifies under Crite	ria Considera	tions A through G (see Manual)
	Does not meet any of	f the above N	ational Register criteria
	39. Area(s) of significance: Ar	rchitecture; A	griculture
	40. Period of significance: 18	395	
	41 Level of significance: Nati	ional St	rate Local X

Resource Number:	5ME.2838
Temporary Resource Number:	3095.DHR

#### Architectural Inventory Form (page 4 of 4)

42. Statement of significance: The development in this area is a r	esult of early land		
speculation. Developers bought large areas of land outside th	e city center, subdivided		
them and sold off ten acre tracts for the purpose of fruit orchar	d development. Future frui		
growers were enticed by the promoter's promises of high quality land and success			
industry. The houses that were built on these orchard tracts reflect the modest tradition			
styles of the period combined with the success of the individual farmer.			
43. Assessment of historic physical integrity related to significance	e: Alterations have had a		
moderate impact on the integrity of the house.			
VII. National Register Eligibility Assessment			
44. National Register eligibility field assessment:			
Eligible Not Eligible _X Need Data			
45. Is there National Register district potential? Yes No _X_	Discuss:		
If there is National Register district potential, is this building:	Contributing		
	Noncontributing		
46. If the building is in existing National Register district, is it:	Contributing		
	Noncontributing		
VIII. Recording Information			
47. Photograph numbers: Roll # 15 Frame # 9			
Negatives filed at: City of Grand Junction Planning Dept.			
48. Report title: Grand Junction Phase 3 Survey 49. Date(s):	October 2005		
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia F	lerron		
51. Organization: Reid Architects, Inc.			
52. Address: PO Box 1303 Aspen, Colorado 81612			
53. Phone number(s): 970 920 9225			
NOTE: Please attach a sketch map, a photocopy of the USGS quad. map ind	icating resource location, and		
photographs			

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395



detail map

# 3095 D.5 Road




Grand Junction, Colorado image from 2002 aerial map

area map



City of Grand Junction • Phase Three Survey 2004



#### GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



SME.2838
Roll # 15 Frame # 9
Looking southwest
Grand Junction, Mesa County, CO

PANYSHAR NINH 1 2219 8822991