OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

20. Special features (enter all that apply): Chimney

	cial eligibility determination HP use only)
Date	Initials
	Determined Eligible- NR
8 1	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District

		l of 4		Noncontributing to eligible NR District
l. I	den	tification		is the second se
	1.	Resource number:	5ME.14672	
	2.	Temporary resource number:_	1320.ORC	
	3.	County:	Mesa	
	4.	City:	Grand Junct	ion
	5.	Historic building name:	n/a	
	6.	Current building name:	n/a	11/2/2023
	7.	Building address:	1320 Orchar	d Ave.
	8.	Owner name and address:	J & M Enterp	prises LLC
			320 Mcfarlar	nd Ct Grand Junction, Co 81501
I.	Ged	ographic Information		
	9.	P.M. <u>Ute Principal Meridian</u>	Township	2_1_South Range_1 West
SW 1/4 of SE 1/4 of SW 1/4 of NW 1/4 of section 12			of section_12	
	10.	UTM reference		
		Zone 1 2 ; 7 1 1 !	<u>9 5 9 m</u>	E <u>4 3 2 9 0 5 6</u> mN
11. USGS quad name: Grand Junction Quadrangle			angle	
Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map secti				
12. Lot(s):8 Block: _1				
		Addition: N W Smith Subdivisi	on	Year of Addition: 1946
	13.	Boundary Description and Just	ification: <u>Lega</u>	I description of the site is: Lot 8 Blk 1 N W
		Smith Addition Sec 12 1s 1w		
Assessors Office Parcel ID # 2945-122-04-019)	
		This description was chosen as	the most spec	cific and customary description of the site.
	Λ	chitectural Description		
		Building plan (footprint, shape):	Rectangula	r Dian
		Dimensions in feet: Length 36		
		Number of stories: 1		X VVIdtiiZ i
			el lenter no m	ore than two): Wood Horizontal Siding
		Roof configuration: (enter no ma		
		Primary external roof material		
	15.	Timary external 1001 material	feurar un mou	e than one). Asphalt noor

Resource Number:	5ME.14672
Temporary Resource Numb	er: 1320.ORC

Architectural Inventory Form (page 2 of 4)

	21.	1. General architectural description: This is a simple wood frame, front gable house. The main ridge runs north/south and the principal façade faces south. The entry door sits on the south wall slightly off center to the right. A vertically proportioned double hung		
			hungs. A long set of steps with a landing front the entry door.	
			tical muntins in the upper sash. The east side wall has a	
			s at the rear corner, a single double hung near the front and a	
			the two. A brick chimney is located on the east roof slope.	
	22.		type: No Style	
			ting features: A couple of street trees are located at the front of	
	the lot, and a dirt drive runs along the east side. Otherwise the yard is predominantly			
	lawn.			
	24.	Associated buildings, featu	res, or objects: A front gable garage sits at the rear.	
IV.	Ar	chitectural History		
	25.	Date of Construction: Estimate	ate: 1920 Actual:	
			Mesa County Assessors Office	
	26.		unknown	
		Source of information:	2. 19992	
	27.		unknown	
	28.		unknown	
	29.		e description and dates of major additions, alterations, or	
			Possible addition of basement; dates unknown	
	30.	Original location X	_MovedDate of move(s):	
v.		torical Associations		
			Domestic, Single Dwelling	
		Intermediate use(s):	Developed Cities D. Cities B. Cities C.	
		Current use(s):		
		Site type(s):		
			Eugene G. Helms is listed as the occupant in 1955. This is the	
			in the available directories. Harry Pangborn is listed as the	
	26	Sources of information:	Maca County Assessors Office: Museum of Western Calanda	
	30.		Mesa County Assessors Office; Museum of Western Colorado	
		Archives: Polk Directories		

Resource Number:		5ME.14672
Temporary Resource	Number:	1320.ORC_

Architectural Inventory Form (page 3 of 4)

VI. Significance					
37. Local landmark designation: Yes No _X Date of	designation:				
Designating authority:					
38. Applicable National Register Criteria:					
 A. Associated with events that have made a significant co pattern of our history; 	ntribution to the broad				
B. Associated with the lives of persons significant in our past;					
X C. Embodies the distinctive characteristics of a type, perio	od, or method of				
construction, or represents the work of a master, or tha	nt possess high artistic				
values, or represents a significant and distinguishable may lack individual distinction; or	entity whose components				
D. Has yielded, or may be likely to yield, information impo	ortant in history or				
prehistory.					
Qualifies under Criteria Considerations A through G (see Manual)					
Does not meet any of the above National Register criteria					
 39. Area(s) of significance: Architecture 40. Period of significance: 1920 41. Level of significance: National State LocalX 42. Statement of significance: This house is representative of the early suburban 					
			development that occurred adjacent to the original core of the	city on previously	
			agricultural lands. The town expanded first on the historic arterial streets and then infilled the interior of the grid. This area of town reflects the City's transition, from each		
more rapid expansion. Though the automobile was a factor in the location of n					
development, the small modest houses that were built did not	integrate the car into the				
design.					
43. Assessment of historic physical integrity related to significance	e: Possible addition of				
basement has had a moderate impact on the integrity.					
VII. National Register Eligibility Assessment					
44. National Register eligibility field assessment:					
Eligible Not Eligible _X_ Need Data					
45. Is there National Register district potential? Yes No _X	Discuss:				
If there is National Register district potential, is this building:	Contributing				
	Noncontributing				


Resource Number:		_5ME.14672
Temporary Resource	Number:	1320,ORC

Architectural Inventory Form (page 4 of 4)

46. If the building is in existing National Register district, is it:	Contributing
	Noncontributing
VIII. Recording Information	
47. Photograph numbers: Roll # 6 Frame # 25	
Negatives filed at: City of Grand Junction Planning Dept.	
48. Report title: Grand Junction Phase 3 Survey 49. Date(s):	March 2005
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia	Herron
51. Organization: Reid Architects, Inc.	
52. Address: PO Box 1303 Aspen, Colorado 81612	<u></u>
53. Phone number(s): 970 920 9225	

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1320 Orchard Ave.



North

Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14672

1320 Orchard Ave.

Roll # 6 **Frame #** 25

Looking northwest

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5651 002914

926

share

United that but strong the contract of the con

54702