OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form 1 of 4

AC	-IP use only)
ate	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District
0.00	Managassibusing to plinible MD District

		1014		Noncontributing to eligible NR District
1. 1	den	tification		
	1.	Resource number:	5ME.14677	- 333
	2.	Temporary resource number:_	1502.ORC	AAATT NOT TO THE
	3.	County:	Mesa	
	4.	City:	Grand Junct	ion
	5.	Historic building name:	n/a	
	6.	Current building name:	n/a	
	7.	Building address:	1502 Orchar	d Ave.
	8.	Owner name and address:	Sean P Dola	n
			893 S Coron	ado Dr Sedalia, CO 80135-8304
II.		ographic Information		
	9.	P.M. <u>Ute Principal Meridian</u>	Township	2 1 South Range 1 West
		SW 1/4 of SW 1/4 of SE 1/4	4 of_ <u>NW_</u> 1/4	of section_12
	10.	UTM reference		
Zone <u>1 2; 7 1 2 1 2 2 mE 4 3 2 9 0 5 5 mN</u>				
11. USGS quad name: Grand Junction Quadrangle				angle
		· ·		15' Attach photo copy of appropriate map section.
	12.			
				Year of Addition: 1956
	13.	•		description of the site is: Lot 1 Blk 1
)
		This description was chosen as	the most spe	cific and customary description of the site.
III.	_Are	chitectural Description		
	14.	Building plan (footprint, shape)	: Irregular Pl	an
	15.	Dimensions in feet: Length_27	,	x Width47'
	16.	Number of stories: 1.5		
	17.	Primary external wall material	(s) (enter no m	ore than two): Wood Horizontal Siding
	18.	Roof configuration: (enter no m	ore than one):	Gable on Hip Roof
	19.	Primary external roof material	(enter no mor	e than one):Asphalt Roof
	20.	Special features (enter all that	apply): Porch	, Car port

Resource Number:		5ME.14677
Temporary Resource	Number:	1502.ORC

Architectural Inventory Form (page 2 of 4)

2	1. General architectural desc	ription: This is a large wood frame house with a series of
	additive volumes. The ma	ain section is a steeply pitched pyramidal roof. A lower cross
	gable extends to the west	and meets the main volume wall plane. The gable shares the
	same south roof plane as t	the pyramid section. Another gable extends off the south roof
	plane, creating a long fron	t gable, facing the main street. The long front gable faces
	south and the entry is in th	ne ell created by the two gables. A shed roof extends to the
	south over the entry door.	The roof is supported by a group of thin metal supports and
	several concrete steps run	off the west side to the entry walk. The west facing gable has
	a bay in the center with ve	ertically proportioned double hung windows on each face. A
	single square window sits	in the upper level near the peak. A horizontally proportioned
	window sits to the north of	the west gable on the main volume wall. A pair of window
	units sit on the west side o	f the south front gable at the corner and are mirrored on the
	south wall corner. A single	e double hung sits in the peak of the south gable. The house is
	predominantly horizontal v	wood siding with corner boards a band of contrasting material
	infills the gable ends above	e the window heads. Vertical board and batten siding fills the
	inside corner of the entry a	area
2	Architectural style/building	type:type:
2	Landscaping or special set	tting features: Dense vegetation surrounds the house and a
	patch of lawn sits between	the bushes and the sidewalk.
2	4. Associated buildings, featu	res, or objects: A gable garage sits at the rear, connected to
	the house by a trellis, with	a carport on the side.
	Architectural History	
2		nate: 1898 Actual:
		Mesa County Assessors Office
20	6. Architect:	
		Transport Western
27	7. Builder/Contractor:	
		- 1410
28	_	unknown
		(viiii AX Labora III a
29	•	de description and dates of major additions, alterations, or
		Some window and siding alterations, addition of trellis and
		/ porch; dates unknown Noved Date of move(s):
- 41	I LICIO DEL LOCATION E	MONDO 11510 OL MONO(C).

Resource Number:		5ME.14677
Temporary Resource	Number:	1502.ORC

Architectural Inventory Form (page 3 of 4)

V.	His	storical Associations					
	31.	. Original use(s):	Domestic, Single Dwelling				
	32.	. Intermediate use(s):					
	33.	. Current use(s):	Domestic, Single Dwelling				
	34.	. Site type(s):	Residential Neighborhood				
	35.	. Historical background:	Herman R. Ogle is listed as the occupant in 1955. This is the				
		first instance of this address	s in the available directories. The property is listed as vacant				
		in 1956.					
	36.	. Sources of information:	Mesa County Assessors Office; Museum of Western Colorado				
		Archives; Polk Directories	the same transmission of the same of the s				
VI.	Sig	gnificance					
	37.	. Local landmark designatior	n: Yes No X Date of designation:				
		Designating authority:					
	38.	. Applicable National Registe	er Criteria:				
		A. Associated with eve	nts that have made a significant contribution to the broad				
		pattern of our histor	у;				
	B. Associated with the lives of persons significant in our past;						
	X C. Embodies the distinctive characteristics of a type, period, or method of						
		construction, or rep	resents the work of a master, or that possess high artistic				
		values, or represen	ts a significant and distinguishable entity whose components				
		may lack individual	distinction; or				
	D. Has yielded, or may be likely to yield, information important in history						
		prehistory.					
		Qualifies under Criter	ia Considerations A through G (see Manual)				
		Does not meet any of	the above National Register criteria				
	39.	Area(s) of significance: Arc	hitecture				
	40.	Period of significance: 189	8				
	41.	Level of significance: Nation	nal State Local X				
	42.	Statement of significance:	his house is representative of the development that occurred				
		adjacent to the original core	of the city on agricultural lands. This house sits on a				
		historically arterial street.	Presently, this area of town reflects the City's transition, from				
		agricultural development or	n a small scale to larger production style development during				
		more rapid expansion. This	s is a particularly large house, of which few remain in the				
		area.					
	43.	Assessment of historic phys	ical integrity related to significance: Alterations have had a				
		serious impact on integrity.					

Resource Number:		5ME.14	677
Temporary Resource	Number:	1502.0	RC


53. Phone number(s): 970 920 9225

Architectural Inventory Form (page 4 of 4)

VII. National Register Eligibility Assessment					
44. National Register	44. National Register eligibility field assessment:				
Eligible N	ot Eligible X Need Data				
45. Is there National	Register district potential? Yes No _X	Discuss:			
If there is Nationa	al Register district potential, is this building:	Contributing			
	Noncontributing				
46. If the building is i	Contributing				
	Noncontributing				
VIII. Recording Information					
47. Photograph numbers: Roll # 6 Frame # 22 and Roll # 16 Frame # 18					
Negatives filed at: City of Grand Junction Planning Dept.					
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005					
50. Recorder(s):	Suzannah Reid, Patrick Duffield and Lydia H	erron			
51. Organization:	Reid Architects, Inc.				
52. Address:	PO Box 1303 Aspen, Colorado 81612				

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1502 Orchard Ave.



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004





5ME.14677 1502 Orchard Ave. Roll # 16 Frame # 18 Z Looking north Grand Junction, Mesa County, CO 8ANX8N8 NNN+ 1 2218 862998 Ø 5651 ØØ2914 WHF BAG18A1XBN NNN 1502 Orchard Ave. Grand Junction, Mesa County, CO Roll #6 Frame #22 **8**23 Looking east 5ME.14678