OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 1

HP use only)	
	Initials
Determined Eligib	le- NR
Determined Not E	ligible- NR
Determined Eligib	le- SR
Determined Not E	ligible- SR
Need Data	
Contributes to elig	aible NR District
Noncontributing	to eligible NR District

l. I	den	tification	
	1.	Resource number:	5ME.14627
	2.	Temporary resource number:_	1343.NINT
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	1343 N. 19th Street
	8.	Owner name and address:	Lysle D Wilson
			1343 N 19th St Grand Junction, CO 81501-6509
II.	Ged	ographic Information	
	9.	P.M. <u>Ute Principal Meridian</u>	Township 1 South Range 1 West
		SE 1/4 of NE 1/4 of SE 1/4	of_SW_1/4 of section_12
	10.	UTM reference	
		Zone <u>1 2; 7 1 2 5</u>	5 <u>0 2 mE 4 3 2 8 4 8 6 mN</u>
	11.	USGS quad name: Grand Ju	unction Quadrangle
		Year: 1962 rev.1973 Map sca	ale: 7.5'_X 15' Attach photo copy of appropriate map section.
	12.	Lot(s): 11 Block: 5	
		Addition: Elmwood Plaza Amer	Year of Addition: 1946
13. Boundary Description and Justification: Legal description of the site is: Lot 1		fication: Legal description of the site is: Lot 11 Blk 5	
Elmwood Plaza Refile Sec 12 1s 1w			s 1w
Assessors Office Parcel ID # 2945-123-27-017		45-123-27-017	
		This description was chosen as	the most specific and customary description of the site.
	_		
		chitectural Description	
		Building plan (footprint, shape):	
		7.50	x Width34'
		Number of stories: 1	
		•	s) (enter no more than two): Aluminum
		Roof configuration: (enter no me	
			enter no more than one): Asphalt Roof
	20.	Special features (enter all that a	apply): Porch, Chimney

Resource Number:		5ME.14627
Temporary Resource	Number:	1343.NINT

V.

Architectural Inventory Form (page 2 of 4)

	21.	General architectural desc	ription: This is a simple wood frame house. The hipped roof
		has a large overhang and	a short ridge which runs north/south. The principal façade
		faces east and has a centra	al volume which projects forward. This volume has a hipped
		roof and is slightly off cent	er to the north. The main entry is located under the projecting
		hipped roof in an area rece	essed to be flush with the main wall. The overhanging roof is
		supported by one square p	ost on the corner. A concrete landing fronts the door and a
series of four steps run to the grade. Adjacent to the front door, to the left is a large picture window with a single double hung on the right side. A large picture window is also located on the façade of the projecting volume. Two pairs of double hungs are located on the south wall. The house sits on a concrete foundation with several base window openings. The siding is horizontal aluminum on all walls, except the area of			he grade. Adjacent to the front door, to the left is a large
			le double hung on the right side. A large picture window is
			of the projecting volume. Two pairs of double hungs are
			The house sits on a concrete foundation with several basement
			ing is horizontal aluminum on all walls, except the area of the
		entry under the roof overha	ang.
	22.	Architectural style/building	type: Ranch Type
23. Landscaping or special setting features: The lot is predominantly lawn, with a single			ting features: The lot is predominantly lawn, with a single
street tree. The edge of the lawn has a series of stones along the sidewalk. 24. Associated buildings, features, or objects: A front gable garage at the rear of the site			e lawn has a series of stones along the sidewalk.
			res, or objects: A front gable garage at the rear of the site.
IV.	Ar	chitectural History	
	25.	Date of Construction: Estim	ate: 1951 Actual:
			Mesa County Assessors Office
	26.	Architect:	unknown
		Source of information:	5 (0) - 3
	27.	Builder/Contractor:	
		Source of information:	
	28.	Original owner:	William R. Bray
		Source of information:	1951 Polk Directory
	29.	Construction history (include	le description and dates of major additions, alterations, or
		demolitions):	Addition of metal flues, summer 2004. Siding replaced; dates
		unknown.	
	30.	Original locationX	_MovedDate of move(s):
V.	His	torical Associations	
		Original use(s):	Domestic, Single Dwelling
		Intermediate use(s):	
		Current use(s):	Domestic, Single Dwelling
	34.	Site type(s):	Residential Neighborhood

Resource Number:		5ME.14627
Temporary Resource	Number:	1343.NINT

Architectural Inventory Form (page 3 of 4)

	35.	Historical background: William R. Bray is shown as owner in the 1951 and 1955
		directories. "Four generations of the Bray family have lived and loved the real estate
		business. Today, Bray Real Estate is the oldest and one of the largest real estate
		companies in Grand Junction" "Bray Real Estate was founded in 1946 by Sherman
		and Roxie Brayand continued to prosper though the 1960s and 1970s, when Roxie and
		Sherman's son, W.R. (Bob) Bray led the company"* Samuel Sedalnick is shown in the
		1956 directory. This building is part of Elmwood Plaza. The subdivision was created in
		1946 from the larger Grandview Subdivision, whose owners are shown as Ira G. and
		Thelma L. Carpenter, Forrest M. and Mary J. Cochran, George M. and Thelma E.
		Saunders, and Adie Russell Maynard.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories 1951, 1955, 1956, 1957; *Business Biographies, page 7, The
		Daily Sentinel, Sunday, March 26, 2006
VI.	Sig	gnificance
	37.	Local landmark designation: Yes No _X Date of designation:
		Designating authority:
38. Applicable National Register Criteria:		Applicable National Register Criteria:
		X A. Associated with events that have made a significant contribution to the broad
pattern of our history;		
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
	39.	Area(s) of significance: Architecture, Community Development and Planning
	40.	Period of significance: 1951; 1943 to 1957 Uranium Boom
	41.	Level of significance: National State LocalX_
	42.	Statement of significance: The development in this area is a direct result of the nation's
		involvement in WWII and the drive for the development of nuclear weapons. The
		discovery of significant sources of Uranium in the region initiated development in Grand
		Junction that supported both the mining of the materials and the administration of
		programs related to the development of weapons. The building types, materials and

Resource Number:	5ME.14627
Temporary Resource Number:	1343.NINT

Architectural Inventory Form (page 4 of 4)

neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production. This house is associated with the members of a prominent local family. 43. Assessment of historic physical integrity related to significance: The material replacement has somewhat impacted the integrity. VII. National Register Eligibility Assessment 44. National Register eligibility field assessment: Eligible ____ Not Eligible X Need Data __ 45. Is there National Register district potential? Yes ___ No X Discuss:___ Contributing___ If there is National Register district potential, is this building: Noncontributing ___ 46. If the building is in existing National Register district, is it: Contributing _ Noncontributing ___

VIII. Recording Information

47. Photograph numbers: Roll # 4 Frame # 31

Negatives filed at: City of Grand Junction Planning Dept.

48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005

50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron


51. Organization: Reid Architects, Inc.

52. Address: PO Box 1303 Aspen, Colorado 81612

53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1343 N. 19th Street



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14627

1343 N. 19th Street

Roll #4 Frame #31

Looking south

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN+ 1 5653 002916

032

share

54784