OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

Al	-iP use only)
te	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
100	Determined Not Eligible- SR
_	Need Data
	Contributes to eligible NR District
_	Noncontributing to eligible NR District

1. 1	den	tification	
	1.	Resource number:	5ME.14681
	2.	Temporary resource number:_	1745.ORC
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	1745 Orchard Ave.
	8.	Owner name and address:	Virginia G Blount
			4620 Careyback Ave Elk Grove, CA 95758-5107
II.	Ged	ographic Information	
	9. P.M. <u>Ute Principal Meridian</u> Township 1 South Range 1 West		
		NW_1/4 of_NE_1/4 of_NE_1/4	of <u>SW</u> 1/4 of section <u>12</u>
	10. UTM reference		
	Zone 1 2; 7 1 2 3 9 6 mE 4 3 2 9 0 1 2 mN		
	11. USGS quad name: Grand Junction Quadrangle		
	Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map secti		
	12. Lot(s): <u>5</u> Block: <u>1</u>		
	Addition: Elmwood Plaza Amendment Year of Addition: 1946		
	13.	· · ·	ification: Legal description of the site is: Lot 5 Blk 1
	Elmwood Plaza Refile Sec 12 1s 1w		
	Assessors Office Parcel ID # 2945-123-01-001		
		This description was chosen as	the most specific and customary description of the site.
m.	Arc	chitectural Description	
.,		Building plan (footprint, shape):	Rectangular Plan
			x Width_19'
		_	
	17. Primary external wall material(s) (enter no more than two): Wood Shingle		
	18. Roof configuration: (enter no more than one): Front Gable		
	19. Primary external roof material (enter no more than one): Asphalt Roof		

20. Special features (enter all that apply): Porch, Dormer

Resource Number:		5ME.14681
Temporary Resource	Number:	1745,ORC

Architectural Inventory Form (page 2 of 4)

	21.	. General architectural desc	ription: This is a relatively large, generally rectangular, wood
		frame front gable house.	The ridge runs north/south and the principal façade faces north.
		A shed roof porch is applied	ed to the front façade; the porch roof is supported by three
		equally spaced square wo	od posts. The entry door sits off center to the west and a large
		double hung sits off center	to the east. A pair of vertically proportioned double hung
		windows sits in the upper l	evel on the gable end. The east side has a large gable dorme
		in the center of the roof pla	ane, with two vertically proportioned double hungs. Two
		double hungs are located	on the rear of the main form. At the rear, the wall and eave
		line step back and the mai	n roof ends in a hipped form. This step occurs on both sides. A
		single story shed roof addi	tion sits on the west side in the space created by the main
		building stepping in. Anot	her small shed is added to the main wall on the west. A few
		windows are located on th	e west side of the main volume. Several windows with
		aluminum awnings are loc	ated on the west side of the addition.
	22.	Architectural style/building	type: Late Victorian
	23.	Landscaping or special set	ting features: The lot is heavily treed with a wood fence
		surrounding the lot.	
	24.	Associated buildings, featu	res, or objects: <u>none seen</u>
IV.	Ar	chitectural History	
	25.	Date of Construction: Estim	ate: 1910 Actual:
		Source of information:	Mesa County Assessors Office
	26.	Architect:	unknown
		Source of information:	
	27.	Builder/Contractor:	unknown
		Source of information:	
	28.	Original owner:	unknown
		Source of information:	
	29.	Construction history (include	de description and dates of major additions, alterations, or
		demolitions):	Some window replacement, siding replacement, additions on
		rear, possible alterations to	porch details; dates unknown.
	30.	Original location X	_MovedDate of move(s):
V.	His	torical Associations	
	31.	Original use(s):	Domestic, Single Dwelling
	32.	Intermediate use(s):	
	33.	Current use(s):	Domestic, Single Dwelling
	34.	Site type(s):	Residential Neighborhood

Resource Number:	5ME.14681
Temporary Resource Number:	1745.ORC

Architectural Inventory Form (page 3 of 4)

	35.	Historical background: Lewis Pantuso is listed as owner in the 1951 and 1956
		directories. The 1951 listing is the first instance of this address in the available
		directories. The site is now part of the Elmwood Plaza Subdivision established in 1946.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories
VI.	Si	gnificance
	37.	Local landmark designation: Yes No _X Date of designation:
		Designating authority:
	38.	Applicable National Register Criteria:
		A. Associated with events that have made a significant contribution to the broad
		pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
	39.	Area(s) of significance: Architecture
		Period of significance: 1910
		Level of significance: National State LocalX
	42.	Statement of significance: This house is representative of the development that occurred
		adjacent to the original core of the city on agricultural lands. This house sits on a
		historically arterial street. Presently, this area of town reflects the City's transition, from
		agricultural development on a small scale to larger production style development during
		more rapid expansion.
	43.	Assessment of historic physical integrity related to significance: Alterations have
		moderately impacted the integrity of the building.
VII.		ational Register Eligibility Assessment
	44.	National Register eligibility field assessment:
		Eligible Not Eligible X Need Data


Resource Number:	5ME.14681
Temporary Resource Number:	1745.ORC

Architectural Inventory Form (page 4 of 4)

American Anna American Indiana Anna Atlanta Anna Anna Anna Anna Anna Anna Anna	D:	
45. Is there National Register district potential? Yes No _X	Discuss:	
If there is National Register district potential, is this building:	Contributing	
	Noncontributing	
46. If the building is in existing National Register district, is it:	Contributing	
40. If the building is in existing National Register district, is it.		
	Noncontributing	
VIII. Recording Information		
47. Photograph numbers: Roll # 6 Frame # 16 & 17		
Negatives filed at: City of Grand Junction Planning Dept.		
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005		
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron		
51. Organization: Reid Architects, Inc.		
52. Address: PO Box 1303 Aspen, Colorado 81612		
53. Phone number(s): 970 920 9225		

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1745 Orchard Ave.



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004





5ME.14681 1745 Orchard Ave. Roll #6 Frame #17 Looking south Grand Junction, Mesa County, CO WHF BA010A1X0N NNN+ 1 5651 002914 018 54694 WHF BAB18A1X8N NNN+ 1 5651 882914 Grand Junction, Mesa County, CO

1745 Orchard Ave.

Roll # 6 Frame # 16 Looking southwest