OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

OAH	P use only)	
Date _	Initials	
80000	Determined Eligible- NR	
	Determined Not Eligible- NR	
3337	Determined Eligible- SR	
	Determined Not Eligible- SR	
	Need Data	
2016	Contributes to eligible NR District	
	Noncontributing to eligible NR District	t

1. 1	den	tification				
	1.	Resource number:	5ME.14764			
	2.	Temporary resource number:_	132.ORC			
	3.	County:	Mesa			
	4.	City:	Grand Juncti	on		
	5.	Historic building name:	n/a			
	6.	Current building name:	n/a			
	7.	Building address:	132 Orchard	Ave.		
	8.	Owner name and address:	Joseph Jame	s Rodriguez		
	_		132 Orchard	Ave Grand Junction, CO 81501-2154		
H.		ographic Information				
	9.		•	1 South Range 1 West		
			/4 of <u>NW</u> 1/4	of section_11		
	10.	UTM reference				
				4 3 2 8 7 9 2 mN		
	11.	11. USGS quad name: Grand Junction Quadrangle				
		Year: 1962 rev.1973 Map scale: 7.5' X 15' Attach photo copy of appropriate map section.				
	12.					
				Year of Addition:		
	13.	3. Boundary Description and Justification: Legal description of the site is: Beg 30ft N + 350f				
				236ft S 64deg 40min W 76ft S 202.2ft To		
				Fr W4 Cor Sd Sec 11e 80ft S 82ft S 69deg09		
				Beg		
		This description was chosen as	the most spec	ific and customary description of the site.		
III.	Arc	chitectural Description				
	14.	Building plan (footprint, shape)	:_L-Shaped P	an		
				x Width _24'		
	16.	Number of stories: 1				
				ore than two): Wood Shingle		
				Side Gabled Roof		
				than one): Asphalt Roof		

Resource Number:	5ME.14764
Temporary Resource Numb	er: 132.ORC

Architectural Inventory Form (page 2 of 4)

	20.	. Special features (enter all	that apply):_Porch		
	21.	. General architectural desc	ription: This is a simple wood frame house with a moderately		
		pitched side gable roof. T	he ridge runs east/west and the principal façade faces south.		
		The façade is generally sy	mmetrical with a small central gable roof over the entry door.		
		The front gable is supported	ed by three posts on each corner; two facing front and one		
		equally spaced around the	corner. A pair of casement style windows is centered on the		
wall to the left and a similar window group is located off center to the east on the					
	Two tall double hungs and a smaller one occupy the east wall and a shed roof addition				
		extends off the rear. The	gable ends are infilled with vertical siding above the eave line.		
	22.	Architectural style/building	type: _Minimal Traditional		
	23.	Landscaping or special set	ting features: A large shrub is located on the side of the		
		driveway, which runs alon	g the side of the house to the east. A curving stone curb		
			ntry and bound the lawn. Smaller shrubs front the house and a		
		split rail fence runs along t	the sidewalk.		
	24.	Associated buildings, featu	res, or objects: A gabled garage is located at the rear of the		
	site.				
		HESSAW			
IV.	Ar	chitectural History			
25. Date of Construction: Estimate: 1949 Actual:			ate: 1949 Actual:		
		Source of information:	Mesa County Assessors Office		
	26.	Architect:	unknown		
	27.		unknown		
		Source of information:			
	28.	Original owner:	unknown		
			W2C24.00		
	29.		de description and dates of major additions, alterations, or		
		demolitions):	Window alterations, possible siding replacement, shed roof		
		addition at rear; dates unki			
	30.	Original location X	_MovedDate of move(s):		
V.	His	torical Associations			
	31.	Original use(s):	Domestic, Single Dwelling		
	33.	Current use(s):	Domestic, Single Dwelling		
	0.4	O14 - 4 1-1:	Provide a contract to the contract of the cont		

Resource Number:		5ME.14764
Temporary Resource	Number:	132.ORC

Architectural Inventory Form (page 3 of 4)

	35.	Historical background: Lester O. Dillard is listed as the owner in the 1955 and 56			
		directories. This is the first instance of this address in the available directories.			
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado			
		Archives; Polk Directories.			
VI.	Sic	gnificance			
		Local landmark designation: Yes No _X Date of designation:			
		Designating authority:			
	38.	Applicable National Register Criteria:			
		X A. Associated with events that have made a significant contribution to the broad			
	pattern of our history;				
		B. Associated with the lives of persons significant in our past;			
		X C. Embodies the distinctive characteristics of a type, period, or method of			
		construction, or represents the work of a master, or that possess high artistic			
		values, or represents a significant and distinguishable entity whose components			
		may lack individual distinction; or			
		D. Has yielded, or may be likely to yield, information important in history or			
		prehistory.			
		Qualifies under Criteria Considerations A through G (see Manual)			
		Does not meet any of the above National Register criteria			
	39.	Area(s) of significance: <u>Architecture, Community Development and Planning</u>			
	40.	Period of significance: 1949; 1943 to 1957 Uranium Boom			
	41.	Level of significance: National State LocalX			
	42.	Statement of significance: The development in this area is a direct result of the nation's			
		involvement in WWII and the drive for the development of nuclear weapons. The			
		discovery of significant sources of Uranium in the region initiated development in Grand			
		Junction that supported both the mining of the materials and the administration of			
		programs related to the development of weapons. The building types, materials and			
		neighborhood layout are all indicative of the national trends which were driven by the			
		proliferation of the automobile and the enormous demand for single family homes.			
		House designs departed from the romantic and revival styles that were prevalent in the			
		earlier part of the 20th century and took on a California inspired design that was			
		characterized by simple horizontally proportioned forms. Houses were typically mass			
		produced on previously undeveloped tracts of land at the periphery of earlier			
		development. These groups of houses were typically based on one or two plan types			
		with a limited number of roof and exterior finish variations, further reinforcing the			
		characteristics of mass production.			


Resource N	lumber:		5ME.14764
Temporary	Resource	Number:	132.ORC

Architectural Inventory Form (page 4 of 4)

43. Assessment of historic physical integrity related to significance: Alterations have				
somewhat impacted the integrity of the building.	· · · · · · · · · · · · · · · · · · ·			
VII. National Register Eligibility Assessment				
44. National Register eligibility field assessment:				
Eligible Not Eligible X Need Data				
45. Is there National Register district potential? Yes No _X	Discuss:			
If there is National Register district potential, is this building:	Contributing			
	Noncontributing			
46. If the building is in existing National Register district, is it:	Contributing			
	Noncontributing			
VIII. Recording Information				
47. Photograph numbers: Roll # 10 Frame # 11				
Negatives filed at: City of Grand Junction Planning Dept.				
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005				
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H	lerron			
51. Organization: Reid Architects, Inc.				
52. Address: PO Box 1303 Aspen, Colorado 81612				
53. Phone number(s): 970 920 9225				

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




132 Orchard Ave.



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14764

132 Orchard Ave.

Roll # 10 Frame # 11 Looking northwest Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5649 002912,

012

share

54626