OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form 1 of 4

Offic	ial eligibility determination
	HP use only)
Date	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
- 3	Determined Not Eligible- SR
	Need Data
380	Contributes to eligible NR District
-	Noncontributing to eligible NR District

I. I	den	tification	
	1.	Resource number:	5ME.8914
	2.	Temporary resource number:_	649.SIXT
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	649 N. 16th Street
	8.	Owner name and address:	Elizabeth Cannedy
	_		649 N 16th St Grand Junction, CO 81501
H.		ographic Information	
	9.	P.M. <u>Ute Principal Meridian</u>	Township 1 South Range 1 West
		<u>NW</u> 1/4 of <u>NW</u> 1/4 of <u>SE</u> 1/	4 of <u>NW</u> 1/4 of section 13
10. UTM reference Zone 1 2; 7 1 2 2 1 3 mE 4 3 2 7 7 6 11. USGS quad name: Grand Junction Quadrangle			
			2 <u>1 3 mE 4 3 2 7 7 6 9 mN</u>
			unction Quadrangle
		Year: 1962 rev. 1973 Map sc	ale: 7.5'_X 15' Attach photo copy of appropriate map section.
	12.	Lot(s): <u>25 & 26</u> Block: <u>9</u>	9
		Addition: Slocomb's Addition	Year of Addition: 1906
	13.	Boundary Description and Just	ification: Legal description of the site is: Lot 25 & 26 Blk 9
		Slocomb Addition Sec 13 1s 1w	V
Assessors Office Parcel ID # 2945-132-05-012			45-132-05-012
		This description was chosen as	the most specific and customary description of the site.
III.	_Arc	chitectural Description	
		Building plan (footprint, shape):	Rectangular Plan
			x Width 40'
17. Primary external wall material(s) (enter no more than two): Vinyl			
			ore than one): Front Gabled Roof
		•	(enter no more than one): Asphalt Roof
20. Special features (enter all that apply): Porch. Chimney			

Resource Number:	5ME.8914
Temporary Resource Number:	649.SIXT

Architectural Inventory Form (page 2 of 4)

	21.	. General architectural desci	ription: This is a simple rectangular wood frame house, with a	
	front gabled roof. The main ridge runs east/west and the front of the house faces east.			
lower gabled volume projects forward from the main façade, creating a screened p			cts forward from the main façade, creating a screened porch.	
		The porch roof is supported	by two square posts in the corners, which sit on a low wall	
		encircling the porch. Seve	ral wood steps lead up to the door which is off center on the	
		main wall of the porch gab	e. Screen window panels infill the perimeter of the porch,	
		above the low wall and to the head of the door. Adjacent to the porch volume on the		
		south side of the main wall is a group of three double hung windows which appear to		
		have three over three muntins in the upper sash.		
	22.	2. Architectural style/building type:Bungalow		
	23.	3. Landscaping or special setting features: The house sits on a corner lot with a significant		
		tree to the south, otherwise predominantly lawn.		
	24.	Associated buildings, featu	res, or objects: none	
IV.	Ar	chitectural History		
	25.	Date of Construction: Estima	ate: 1925 Actual:	
			Mesa County Assessors Office	
	26.	Architect:	unknown	
		Source of information:		
	27.		unknown	
		Source of information:		
	28.	Original owner:	unknown	
		Source of information:		
	29. Construction history (include description and dates of major additions, alterations, or			
		demolitions):	Porch enclosure, vinyl siding, alterations to eave and rake	
		details, dates unknown.		
	30.	Original location X	_MovedDate of move(s):	
V.,	His	torical Associations		
	31.	Original use(s):	Domestic, Single Dwelling	
	32.	Intermediate use(s):		
	33.	Current use(s):	Domestic, Single Dwelling	
	34	Site type(s):	Residential Neighborhood	

Resource Number:	5ME.8914
Temporary Resource Number:	649.SIXT

Architectural Inventory Form (page 3 of 4)

	35.	Historical background: No specific early information was found on this building, but
		in the 1941 directory it is shown as vacant. In the directories of 1955 and 1956 Joseph
		W. Peart is shown as owner. Then in 1957 directory it is occupied by William A. Watson
		The building is part of Slocomb's Addition created in 1906. Originally consisting of 28
		blocks, the subdivision was named for Edwin M. Slocomb who was one of the first
		residents of the area and had numerous real estate holdings in Colorado and Idaho.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorade
		Archives; Polk Directories 1955, 1956, 1957
./1	e:	gnificance
VI.		
	37.	Local landmark designation: Yes No _X Date of designation:
	20	Designating authority:
	30.	Applicable National Register Criteria:
		A. Associated with events that have made a significant contribution to the broad
		pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
		Area(s) of significance: Architecture
		Period of significance: 1925
		Level of significance: National State Local X
	42.	Statement of significance: This house is representative of the early suburban
		development that occurred adjacent to the original core of the city on previously
		agricultural lands. Development occurred first on the historic arterial streets and then
		infilled the interior of the grid. This area of town reflects the City's transition, from early
		suburban development on a small scale to larger production style development during
		more rapid expansion. Though the automobile was a factor in the location of new
		development, the small modest houses that were built did not integrate the car into the
		design. These early suburban examples were compact houses with simple forms and
		simple materials.

Resource Number:	5ME.8914
Temporary Resource Number:	649.SIXT


Architectural Inventory Form (page 4 of 4)

43. Assessment of historic physical integrity related to significance seriously impacted the integrity.			
VII. National Register Eligibility Assessment			
44. National Register eligibility field assessment:			
Eligible Not Eligible _X_ Need Data			
45. Is there National Register district potential? Yes No X	Discuss:		
If there is National Register district potential, is this building:	Contributing		
	Noncontributing		
46. If the building is in existing National Register district, is it:	Contributing		
	Noncontributing		
VIII. Recording Information			
47. Photograph numbers: Roll # 16 Frame # 13			
Negatives filed at: City of Grand Junction Planning Dept.			
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005			
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron			
51. Organization: Reid Architects, Inc.			
52. Address: PO Box 1303 Aspen, Colorado 81612			
53. Phone number(s): 970 920 9225			

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395








Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.8914

649 N. 16th Street

Roll # 16 Frame # 13

Looking southwest

Grand Junction, Mesa County, CO

CHARGE CARREST

7.01.1