OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

	ial eligibility determination IP use only)
e	Initials
	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District
	Noncontributing to eligible NR District

1. 1	den	tification	
	1.	Resource number:	5ME.8912
	2.	Temporary resource number:_	620.SEVT
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	Moyer House
	6.	Current building name:	n/a
	7.	Building address:	620 N. 17th Street
	8.	Owner name and address:	Dean Allen Humphrey
		<u> </u>	620 N 17th St Grand Junction, CO 81501-4434
II.	Ged	ographic Information	
	9.	P.M. <u>Ute Principal Meridian</u>	Township_1 South Range_1 West
		NW_1/4 of_NE_1/4 of_SE_1/4	of_NW_1/4 of Section_13
	10.	UTM reference (NAD 83 Datum	n)
		Zone 1 2; 7 1 2	<u>3 6 7 mE 4 3 2 7 7 2 1 mN</u>
	11.	USGS quad name: Grand J	unction Quadrangle
			ale: 7.5'_X_ 15' Attach photo copy of appropriate map section.
	12.	Lot(s): 8 & 9 Block:	11
		Addition: Slocomb's Addition	Year of Addition: 1940
	13.	Boundary Description and Just	ification: Legal description of the site is Lots 8 + 9 Blk 11
		Slocomb's Addition	
		Assessors Office Parcel ID # 29	45-132-03-007
		This description was chosen as	the most specific and customary description of the site.
111.	Arc	chitectural Description	
	14.	Building plan (footprint, shape):	: Rectangular Plan
	15.	Dimensions in feet: Length 38	<u>'x Width_32'</u>
	16.	Number of stories: One Story	
			s) (enter no more than two): Wood Shingles
	18.	Roof configuration: (enter no m	ore than one): Cross Gabled Roof
		_	(enter no more than one): Asphalt Roof
	20.	Special features (enter all that	apply): none

Resource Number:		5ME.14543
Temporary Resource	Number:	620.SEVT

V.

Architectural Inventory Form (page 2 of 4)

31. Original use(s):		21.	. General architectural desc	ription: This is a modest single story, wood frame house. The
side but does not alter the wall plane of the primary form. The entry is a single door located just past the spring line of the front gable form, generally centered on the façade. A small gable roof is applied to the face of the main wall, but shares the roof plane with the front gable. It is supported by thin metal supports which rest on the bottom step of the concrete steps that access the entry. Four steps and a small landing fill the space in front of the door. A horizontally proportioned window is located on the right side of the door with a low aluminum awning. A similar single double hung is located to the left of the door just off center on the front gable. Two similar double hungs are located symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type: Minimal Traditional 23. Landscaping or special setting features: The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate: 1947 Actual: Source of information: Mesa County Assessors Office 26. Architect: unknown Source of information: 1996 Phase Two survey form 27. Builder/Contractor: unknown Source of information: 1996 Phase Two survey form 29. Construction history (include description and dates of major additions, alterations, or demolitions): Awnings added, dates unknown. 30. Original location X Moved Date of move(s): V. Historical Associations 31. Original use(s): Domestic, Single Dwelling 32. Intermediate use(s):			primary volume has a med	dium to low pitched side gable roof with minimal overhangs
located just past the spring line of the front gable form, generally centered on the façade, A small gable roof is applied to the face of the main wall, but shares the roof plane with the front gable. It is supported by thin metal supports which rest on the bottom step of the concrete steps that access the entry. Four steps and a small landing fill the space in front of the door, A horizontally proportioned window is located on the right side of the door with a low aluminum awning. A similar single double hung is located to the left of the door just off center on the front gable. Two similar double hungs are located symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type: Minimal Traditional 23. Landscaping or special setting features: The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate: 1947 Actual: Source of information: Mesa County Assessors Office 26. Architect: unknown Source of information: Unknown Source of information: 1996 Phase Two survey form 29. Construction history (include description and dates of major additions, alterations, or demolitions): Awnings added, dates unknown. 30. Original location X Moved Date of move(s): V. Historical Associations 31. Original use(s): Domestic, Single Dwelling 32. Intermediate use(s):			and is a deep rectangle clo	ose to square in plan. A front gable form rises on the left (north)
A small gable roof is applied to the face of the main wall, but shares the roof plane with the front gable. It is supported by thin metal supports which rest on the bottom step of the concrete steps that access the entry. Four steps and a small landing fill the space in from of the door. A horizontally proportioned window is located on the right side of the door with a low aluminum awning. A similar single double hung is located to the left of the door just off center on the front gable. Two similar double hungs are located symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type:Minimal Traditional 23. Landscaping or special setting features: _The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate:1947			side but does not alter the	wall plane of the primary form. The entry is a single door
the front gable. It is supported by thin metal supports which rest on the bottom step of the concrete steps that access the entry. Four steps and a small landing fill the space in front of the door. A horizontally proportioned window is located on the right side of the door with a low aluminum awning. A similar single double hung is located to the left of the door just off center on the front gable. Two similar double hungs are located symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type:Minimal Traditional 23. Landscaping or special setting features: _The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: _A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. 17. Architectural History 25. Date of Construction: Estimate:1947			located just past the spring	line of the front gable form, generally centered on the façade.
concrete steps that access the entry. Four steps and a small landing fill the space in from of the door. A horizontally proportioned window is located on the right side of the door with a low aluminum awning. A similar single double hung is located to the left of the door just off center on the front gable. Two similar double hungs are located symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type: Minimal Traditional 23. Landscaping or special setting features: The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate: 1947			A small gable roof is appli-	ed to the face of the main wall, but shares the roof plane with
of the door. A horizontally proportioned window is located on the right side of the door with a low aluminum awning. A similar single double hung is located to the left of the door just off center on the front gable. Two similar double hungs are located symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type: Minimal Traditional 23. Landscaping or special setting features: The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate: 1947 Actual: Source of information: Mesa County Assessors Office 26. Architect: unknown			the front gable. It is suppo	orted by thin metal supports which rest on the bottom step of the
with a low aluminum awning. A similar single double hung is located to the left of the door just off center on the front gable. Two similar double hungs are located symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type:Minimal Traditional 23. Landscaping or special setting features: _The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: _A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate: _1947			concrete steps that access	the entry. Four steps and a small landing fill the space in front
door just off center on the front gable. Two similar double hungs are located symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type:Minimal Traditional 23. Landscaping or special setting features: _The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: _A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate:1947			of the door. A horizontally	proportioned window is located on the right side of the door
symmetrically on each side. A small addition projects off the rear. 22. Architectural style/building type: _Minimal Traditional 23. Landscaping or special setting features: _The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: _A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate: _1947			with a low aluminum awni	ng. A similar single double hung is located to the left of the
22. Architectural style/building type:Minimal Traditional 23. Landscaping or special setting features: _The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: _A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate:1947			door just off center on the f	front gable. Two similar double hungs are located
23. Landscaping or special setting features: The landscape is primarily lawn with mature street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate: 1947			symmetrically on each side	e. A small addition projects off the rear.
street trees and evergreen shrubs wrap the corner of the house. 24. Associated buildings, features, or objects: A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate: 1947 Actual: Source of information: Mesa County Assessors Office 26. Architect: unknown Source of information: 27. Builder/Contractor: unknown Source of information: 28. Original owner: Moyer Source of information: 1996 Phase Two survey form 29. Construction history (include description and dates of major additions, alterations, or demolitions): _Awnings added, dates unknown. 30. Original location X Moved Date of move(s): V. Historical Associations 31. Original use(s): Domestic, Single Dwelling 32. Intermediate use(s): Date of move(s): 29 Domestic, Single Dwelling 33. Intermediate use(s): Date of move(s):		22.	Architectural style/building	type: Minimal Traditional
24. Associated buildings, features, or objects: A front gable single car garage is set toward the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate:1947 Actual: Source of information: Mesa County Assessors Office 26. Architect: unknown		23.	Landscaping or special set	ting features: The landscape is primarily lawn with mature
the rear of the site and has similar roof pitch and materials. IV. Architectural History 25. Date of Construction: Estimate:1947 Actual: Source of information: Mesa County Assessors Office 26. Architect: unknown Source of information: Unknown Source of information: Moyer Source of information: Moyer Source of information: 1996 Phase Two survey form 29. Construction history (include description and dates of major additions, alterations, or demolitions): _Awnings added, dates unknown. 30. Original location X Moved Date of move(s):			street trees and evergreen	shrubs wrap the corner of the house.
IV. Architectural History 25. Date of Construction: Estimate:		24.	Associated buildings, featu	res, or objects: A front gable single car garage is set toward
25. Date of Construction: Estimate: 1947			the rear of the site and has	s similar roof pitch and materials.
25. Date of Construction: Estimate: 1947				
Source of information:	IV.		-	
26. Architect:		25.		
Source of information: 27. Builder/Contractor:unknown				
27. Builder/Contractor:		26.		
Source of information: 28. Original owner:				
28. Original owner:		27.		
Source of information:1996 Phase Two survey form 29. Construction history (include description and dates of major additions, alterations, or demolitions): _Awnings added, dates unknown. 30. Original location X Moved Date of move(s): V. Historical Associations 31. Original use(s): Domestic, Single Dwelling 32. Intermediate use(s):				
29. Construction history (include description and dates of major additions, alterations, or demolitions): Awnings added, dates unknown. 30. Original location X Moved Date of move(s): V. Historical Associations 31. Original use(s): Domestic, Single Dwelling 32. Intermediate use(s):		28.		
demolitions): Awnings added, dates unknown. 30. Original location X Moved Date of move(s): V. Historical Associations 31. Original use(s): Domestic, Single Dwelling 32. Intermediate use(s):				
30. Original location X Moved Date of move(s): V. Historical Associations 31. Original use(s): Domestic, Single Dwelling 32. Intermediate use(s):		29.	*	
V. Historical Associations 31. Original use(s):		20	-	
31. Original use(s):		30.	Original locationX	WovedDate of move(s):
31. Original use(s):	.,		4il Ai-ti	
32. Intermediate use(s):	_			Demostic Single Devalling
		5 1	Original use(s):	Domestic, Single Dwelling
23 Current yeals): Domastic Single Dwelling			Intermediate see/els	
33. Current use(s): Domestic, Single Dwelling		32.		

Resource Number: 5ME.14543
Temporary Resource Number: 620.SEVT


Architectural Inventory Form (page 3 of 4)


	35.	. Historical background: The 1996 Phase 2 Survey shows a Moyer as the original
		owner. The 1951 directory shows the occupant to be Max F. Welch; this is the first
		instance of this address in the available directories. The 1955 and 1956 directories show
		Roy f. Hollis as occupant and in the 1957 directory Guy Winslow is the occupant. This
		building is part of Slocomb's Addition created in 1906. Originally consisting of 28 blocks,
		the subdivision was named for Edwin M. Slocomb who was one of the first residents of
		the area and had numerous real estate holdings in Colorado and Idaho.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories 1951, 1955, 1956, 1957; 1996 Phase 2 survey form
VI.	Sig	gnificance
	37.	Local landmark designation: Yes No _X Date of designation:
		Designating authority:
	38.	Applicable National Register Criteria:
		X A. Associated with events that have made a significant contribution to the broad
		pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
	39.	Area(s) of significance: Architecture, Community Development and Planning
		Period of significance: 1947; 1943 to 1957 Uranium Boom
	41.	Level of significance: National State LocalX
	42.	Statement of significance: The development in this area is a direct result of the nation's
		involvement in WWII and the drive for the development of nuclear weapons. The
		discovery of significant sources of Uranium in the region initiated development in Grand
		Junction that supported both the mining of the materials and the administration of
		programs related to the development of weapons. The building types, materials and
		neighborhood layout are all indicative of the national trends which were driven by the
		proliferation of the automobile and the enormous demand for single family homes. This
		house is representative of the early suburban development that occurred adjacent to the
		original core of the city on previously agricultural lands. The town expanded first on the

Resource Number:	_5ME.14543
Temporary Resource Number:	620.SEVT

Architectural Inventory Form (page 4 of 4)

historic arterial streets and then infilled the interior of the gr	id. This area of town reflects
the City's transition, from early suburban development on a	
production style development during more rapid expansion.	
a factor in the location of new development, the small mode	-
not integrate the car into the design. These early suburban	
houses with simple forms and simple materials, based on tra	•
43. Assessment of historic physical integrity related to significan	•
intact in its original form.	
VII. National Register Eligibility Assessment	
44. National Register eligibility field assessment:	
Eligible Not EligibleX Need Data	
45. Is there National Register district potential? Yes No _X	Discuss:
If there is National Register district potential, is this building:	Contributing
	Noncontributing
46. If the building is in existing National Register district, is it:	Contributing
	Noncontributing
VIII. Recording Information	
47. Photograph numbers: Roll #2 Frame #19	
Negatives filed at: City of Grand Junction Planning Dept.	
48. Report title: Grand Junction Phase 3 Survey 49. Date(s):	October, 2004
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herro	n
51. Organization: Reid Architects, Inc.	
52. Address: PO Box 1303 Aspen, Colorado 81612	
53. Phone number(s): 970 920 9225	
NOTE: Please attach a sketch map, a photocopy of the USGS quad. map in photographs.	ndicating resource location, and
Colorado Historical Society - Office of Archaeology & His	toric Preservation
1300 Broadway, Denver, CO 80203 (303) 86	








Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME,8912

620 N. 17th Street

Roll #2 Frame #19

Looking east

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5652 002915

020

share

CENTERED CONTROL FOR THE LESS CONTROL OF THE CONTRO

54734