OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

4	(P use only)
3 _	Initials
_	Determined Eligible- NR
	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District
	Noncontributing to eligible NR District

1. 1	den	tification	
	1.	Resource number:	5ME.8966
	2.	Temporary resource number:_	430.FIFT
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	430 N. 15th Street
	8.	Owner name and address:	Meredith Ann Miller
	,=		225 Park Dr Grand Junction, CO 81501-2062
	_		
II.		ographic Information	T 11 40 11 5 411 1
	9.	•	Township_1 South Range_1 West
	4.0	HIP AND SEE	4 of <u>NW</u> 1/4 of section <u>13</u>
	10.	UTM reference	
			1 7 6 mE 4 3 2 7 5 2 7 mN
	11.		unction Quadrangle
	4.0	·	cale: 7.5' <u>X</u> 15' Attach photo copy of appropriate map section
	12.		1 (4.15)
	40		Year of Addition: 1906
	13.	·	ification: Legal description of the site is: Lots 3 + 4 Blk 1
			WE 120 10 002
			45-132-19-003
		This description was chosen as	the most specific and customary description of the site.
III.	Arc	chitectural Description	
	14.	Building plan (footprint, shape)	: Rectangular Plan
	15.	Dimensions in feet: Length 16'	x Width32'
	16.	Number of stories: 1	
	17.	Primary external wall material	s) (enter no more than two): Wood Horizontal Siding
	18.	Roof configuration: (enter no m	ore than one): Hip on Gable Roof
	19.	Primary external roof material	(enter no more than one): Asphalt Roof
	20.	Special features (enter all that	apply): Chimney

Resource Number:		5ME.8966
Temporary Resource	Number:	430.FIFT

٧.

Architectural Inventory Form (page 2 of 4)

	21.	General architectural desc	ription: This is a simple wood frame building with a clipped
		side gable roof. The main	façade is asymmetrical with the entry door located on the far
		left side with a narrow vert	ical window on the right and a square-ish window of the same
		height on the left. Both win	ndows have multiple panes. The remainder of the façade has
		two vertically proportioned	double hungs distributed relatively evenly along the wall.
		The south side has a pair of	of vertically proportioned double hungs near the front corner
		and a horizontally proportion	oned slider window near the rear. The north side has a
		window on the corner simi	ar to the entry window with a slider window near the center
		and another horizontal ven	t window in the peak of the roof. The roof has exposed rafters
		with a decorative ogee cut	on the barge boards. Brackets support the overhangs on the
		north and south at the eave	e and at the corners of the clipped gables. A small shed roof
		addition extends off the rea	ar of the house, with a flat roofed patio area on the south
		corner. The wood siding is	narrow clapboards which are mitered at the corners. The
		brick chimney sits near the	ridge off center to the north.
	22.	Architectural style/building	type: Bungalow
	23.	Landscaping or special set	ting features: The lot is open with a couple of large trees and
		some shrubs. Most of the a	area is lawn.
	24.	Associated buildings, featu	res, or objects:_none seen
IV.	Ar	chitectural History	
	25.	Date of Construction: Estim	ate: 1922 Actual:
		Source of information:	Mesa County Assessors Office
	26.	Architect:	unknown
		Source of information:	
	27.	Builder/Contractor:	unknown
		Source of information:	
	28.	Original owner:	unknown
		Source of information:	
	29.	Construction history (include	le description and dates of major additions, alterations, or
		demolitions):	Some non-original windows have been added (or partially
		replacing originals), addition	on at rear, Dates Unknown.
	30.	Original location X	_MovedDate of move(s):
V.	His	torical Associations	
			Domestic, Single Dwelling
			Domestic Single Dwelling

Resource Number:		5ME.8966
Temporary Resource	Number:	430.FIFT

Architectural Inventory Form (page 3 of 4)

	34.	Site type(s): Residential Neighborhood
	35.	Historical background: No specific early information was found on this building. In
		the directories of 1941, 1951, 1955, 1956 and 1957 Ralph W. Safford is shown as owner.
		The building is part of Slocomb's Addition created in 1906. Originally consisting of 28
		blocks, the subdivision was named for Edwin M. Slocomb who was one of the first
		residents of the area and had numerous real estate holdings in Colorado and Idaho.
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado
		Archives; Polk Directories 1941, 1951, 1955, 1956, 1957
/1.	Sig	gnificance
	37.	Local landmark designation: Yes No _X Date of designation:
		Designating authority:
	38.	Applicable National Register Criteria:
		A. Associated with events that have made a significant contribution to the broad
		pattern of our history;
		B. Associated with the lives of persons significant in our past;
		X C. Embodies the distinctive characteristics of a type, period, or method of
		construction, or represents the work of a master, or that possess high artistic
		values, or represents a significant and distinguishable entity whose components
		may lack individual distinction; or
		D. Has yielded, or may be likely to yield, information important in history or
		prehistory.
		Qualifies under Criteria Considerations A through G (see Manual)
		Does not meet any of the above National Register criteria
	39.	Area(s) of significance: Architecture
	40.	Period of significance: 1922
	41.	Level of significance: National State Local X
	42.	Statement of significance: This house is representative of the early suburban
		development that occurred adjacent to the original core of the city on previously
		agricultural lands. Development occurred first on the historic arterial streets and then
		infilled the interior of the grid. This area of town reflects the City's transition, from early
		suburban development on a small scale to larger production style development during
		more rapid expansion. Though the automobile was a factor in the location of new
		development, the small modest houses that were built did not integrate the car into the
		design. These early suburban examples were compact houses with simple forms and
		simple materials.


Resource Number:		5ME.8966	
Temporary Resource	Number:	430.FIFT	

Architectural Inventory Form (page 4 of 4)

43. Assessment of historic physical integrity related to significance	
intact. Provided that the entry configuration is original, the ho	
integrity.	
VII. National Register Eligibility Assessment	
44. National Register eligibility field assessment:	
Eligible Not Eligible _X Need Data	
45. Is there National Register district potential? Yes No _X_	Discuss:
If there is National Register district potential, is this building:	Contributing
	Noncontributing
46. If the building is in existing National Register district, is it:	Contributing
	Noncontributing
VIII. Recording Information	
47. Photograph numbers: Roll # 2 Frame # 27	
Negatives filed at: City of Grand Junction Planning Dept.	-
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): M	larch 2005
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia F	lerron
51. Organization: Reid Architects, Inc.	
52. Address: PO Box 1303 Aspen, Colorado 81612	
53. Phone number(s): 970 920 9225	

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395








Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.8966

430 N. 15th Street

Roll #2 Frame #27 Looking northeast

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5652 002915

028

share

54742