OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

# Architectural Inventory Form 1 of 4

A۱	IP use only)
e	Initials
_	Determined Eligible- NR
7.23	Determined Not Eligible- NR
	Determined Eligible- SR
	Determined Not Eligible- SR
	Need Data
	Contributes to eligible NR District
_	Non-consideration and eligible NID District

		<u> </u>	
<b>I.</b> I	den	tification	
	1.	Resource number:	5ME.14635
	2.	Temporary resource number:	1333.ELM
	3.	County:	Mesa
	4.	City:	Grand Junction
	5.	Historic building name:	n/a
	6.	Current building name:	n/a
	7.	Building address:	1333 Elm Ave.
	8.	Owner name and address:	Ann Marie Lamphere
			1333 Elm Ave Grand Junction, CO 81501-7653
II.	Ged	ographic Information	
	9.	P.M. <u>Ute Principal Meridian</u>	Township_1_South Range_1_West
		NW_1/4 of_NE_1/4 of_SW_1/4	of <u>SW</u> 1/4 of section <u>12</u>
	10.	. UTM reference	
		Zone 1 2; 7 1 1 9	<u>4 3 mE 4 3 2 8 6 0 5 mN</u>
	11.	. USGS quad name: <u>Grand Ju</u>	nction Quadrangle
		Year: 1962 rev.1973 Map sca	le: 7.5'_X 15' Attach photo copy of appropriate map section.
	12.	. Lot(s): _7 Block:	
		Addition: Grandview Subdivision	on Year of Addition: 1905
	13.	. Boundary Description and Justif	fication: Legal description of the site is: Beg 60ft E Of Nw
Cor Lot 7 Grandview Subdivision S 145.2ft E50ft N 145.2ft W To Beg exc Aly on Assessors Office Parcel ID # 2945-123-00-012			n S 145.2ft E50ft N 145.2ft W To Beg exc Aly on S
			5-123-00-012
		This description was chosen as t	the most specific and customary description of the site.
m.	-Arc	chitectural Description	
14. Building plan (footprint, shape): Rectangular Plan			Rectangular Plan
	15.	Dimensions in feet: Length_38'	x Width_ 27'
	16.	Number of stories: 1	14/9/2-10-0000
	17.	Primary external wall material(s	s) (enter no more than two):_Stucco
	18.	Roof configuration: (enter no mo	ore than one): Hip-on-Gable Roof
	19.	Primary external roof material (	enter no more than one): Asphalt Roof
	20.	Special features (enter all that a	pply): none

Resource Number:		5ME.14635
Temporary Resource	Number:	1333.ELM

## Architectural Inventory Form (page 2 of 4)

	21.	General architectural descr	iption: This is a rectangular wood frame house with a front
		gabled roof. The ridge runs	s north/south and the principal façade faces north. The house
		is comprised of a larger pri	mary volume with a smaller additive volume on the main
		façade. Both roofs have a	small clipped gable at the peak. The roof has large overhangs
		supported by triangular bra	ckets. The entry door is centered on the façade and is flanked
		by a series of vertically pro	portioned windows running across the front and wrapping the
		corners of the front volume	. The sides of the main volume have three vertically
proportioned double hung windows distributed along the wall. A shed roof p			windows distributed along the wall. A shed roof porch extends
		off the rear of the house	
	22.	Architectural style/building	type: Craftsman
	23.	Landscaping or special sett	ting features: Several trees and shrubs fill the yard.
	24.	Associated buildings, featur	res, or objects: <u>none seen</u>
IV.	Ar	chitectural History	
	25.	Date of Construction: Estima	ate:_1924Actual:
		Source of information:	Mesa County Assessors Office
	26.	Architect:	unknown
		Source of information:	11/21/04/2012
	27.		unknown
		Source of information:	
	28.	Original owner:	unknown
		Source of information:	
	29.	Construction history (includ	e description and dates of major additions, alterations, or
		demolitions):	Stucco added, porch enclosure, addition off rear, dates
		unknown.	
	30.	Original location X	Date of move(s):
V.	His	torical Associations	
	31.	Original use(s):	Domestic, Single Dwelling
	32.	Intermediate use(s):	
	33.	Current use(s):	Domestic, Single Dwelling
	34.	Site type(s):	Residential Neighborhood
	35.	Historical background:	No specific early information was found on this building, but
			ock is shown as owner. In the 1955 and 1956 directories the
		building is shown as vacant	t. In the 1957 directory the owner shown is Fred C. Muto. The
		building is now part of Pros	pect Park subdivision of about 1947 developed by a group of

Resource Number:	5ME.14635
Temporary Resource Number:	1333.ELM

### Architectural Inventory Form (page 3 of 4)

thirty-one owners for the 81 lots and included a park. This area was originally			
		larger Grandview Subdivision.	
	36.	Sources of information: Mesa County Assessors Office; Museum of Western Colorado	
		Archives; Polk Directories	
VI.	Sig	gnificance	
	37.	Local landmark designation: Yes No _X_ Date of designation:	
		Designating authority:	
	38.	Applicable National Register Criteria:	
		A. Associated with events that have made a significant contribution to the broad pattern of our history;	
		B. Associated with the lives of persons significant in our past;	
		X C. Embodies the distinctive characteristics of a type, period, or method of	
		construction, or represents the work of a master, or that possess high artistic	
		values, or represents a significant and distinguishable entity whose components	
		may lack individual distinction; or	
		D. Has yielded, or may be likely to yield, information important in history or	
		prehistory.	
		Qualifies under Criteria Considerations A through G (see Manual)	
		Does not meet any of the above National Register criteria	
	39.	Area(s) of significance: Architecture	
	40.	Period of significance: 1924	
		Level of significance: National State LocalX_	
	42.	Statement of significance: This house is representative of the early suburban	
		development that occurred adjacent to the original core of the city on previously	
		agricultural lands. The town expanded first on the historic arterial streets and then	
		infilled the interior of the grid. This area of town reflects the City's transition, from early	
		suburban development on a small scale to larger production style development during	
		more rapid expansion. Though the automobile was a factor in the location of new	
		development, the small modest houses that were built did not integrate the car into the	
		design. The craftsman style was particularly popular during this period of time.	
	43.	Assessment of historic physical integrity related to significance: <u>Material alterations have</u>	
		seriously compromised the integrity.	
VII.	. Na	ational Register Eligibility Assessment	
	44.	National Register eligibility field assessment:	
		Eligible Not Eligible _X Need Data	


Resource Number:		5ME.14635
Temporary Resource	Number:	1333.ELM

#### Architectural Inventory Form (page 4 of 4)

45. Is there National	45. Is there National Register district potential? Yes No _X If there is National Register district potential, is this building:		
If there is Nationa			
		Noncontributing	
46. If the building is i	Contributing		
		Noncontributing	
VIII. Recording Inform	ation		
47. Photograph numbers: Roll # 4 Frame # 6			
Negatives filed at: City of Grand Junction Planning Dept.			
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005			
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron			
51. Organization:	Reid Architects, Inc.		
52. Address:	PO Box 1303 Aspen, Colorado 81612		
53. Phone number(s):	:_ 970 920 9225		

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1333 Elm Ave.



Grand Junction, Colorado image from 2002 aerial map

City of Grand Junction • Phase Three Survey 2004



#### GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14635

1333 Elm Ave.

Roll #4 Frame #6

Looking southeast

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN 0 5653 002916

007

share

Transfer tester between the more than the contract of the cont

54759