OAHP1403 Rev. 9/98

12.

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Official eligibility determination (OAHP use only)

- Date ______Initials _ Determined Eligible- NR Determined Not Eligible- NR Determined Eligible- SR Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District Noncontributing to eligible NR District

I. Identification

- 1. Resource number: _____ 5ME.14652
- 2. Temporary resource number: 1343.HAL
- 3. County: <u>Mesa</u>
- 4. City: Grand Junction
- 5. Historic building name: ______n/a___
- Current building name: <u>n/a</u>
- 7. Building address: <u>1343 Hall Ave.</u>
- 8. Owner name and address: Ellen M Kiesler

1343 Hall Ave Grand Junction, CO 81501-6321

II. Geographic Information

9. P.M. <u>Ute Principal Meridian</u> Township <u>1 South</u> Range <u>1 West</u> <u>SW 1/4 of NE 1/4 of NW 1/4 of SW 1/4 of section 12</u>

10. UTM reference

- Zone <u>1 2; 7 1 1 9 4 7 mE 4 3 2 8 9 0 2 mN</u>
- 11. USGS quad name: Grand Junction Quadrangle
- Year:
 1962
 rev.1973
 Map scale:
 7.5' X
 15' Attach photo copy of appropriate map section.

 12. Lot(s):
 2 & 3
 Block:
 3

Addition: Eastholme-in-Grandview Year of Addition: 1950

13. Boundary Description and Justification: Legal description of the site is: E 35.5ft Of Lot 2 + W 25.5ft Of Lot 3 Blk 3 Eastholme-In-Grandview Subdivision

Assessors Office Parcel ID # 2945-123-04-006

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape): <u>Rectangular Plan</u>
- 15. Dimensions in feet: Length 28' x Width 50'
- 16. Number of stories: _ 1_____
- 17. Primary external wall material(s) (enter no more than two): Brick
- 18. Roof configuration: (enter no more than one): Side Gable Roof
- 19. Primary external roof material (enter no more than one): Asphalt Roof
- 20. Special features (enter all that apply): Attached Garage

Resource Number: 5ME.14652 Temporary Resource Number: 1343.HAL

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: <u>The building is a simple rectangular, masonry house</u> with a side gable roof that runs east/west. The principal façade faces north. A low pitched front gable sits on the right end of the principal façade, covering a shallow projection in the wall plane. A single car garage door is centered on the projection. The main entry door is located to the left of the projection, a large picture window, flanked by double hungs, sits further to the left. Two concrete steps and a landing front the entry door. Two double hungs are located on the remainder of the principal façade. The side gable roof has a deep overhang which runs into the line of the front gable face. The front gable is infilled with vertical siding.
- 22. Architectural style/building type: Ranch type
- 23. Landscaping or special setting features: <u>The house sits in a lawn back from the street</u> with a few street trees and large evergreens as well as some low evergreens at the front of the house and along the driveway.
- 24. Associated buildings, features, or objects: None

IV. Architectural History

- 25. Date of Construction: Estimate: <u>1951</u> Actual: _______ Source of information: Mesa County Assessors Office
- 26. Architect: _____unknown _____ Source of information: _____
- 27. Builder/Contractor: _____unknown Source of information: _____
- 28. Original owner: <u>unknown</u> Source of information:
- 29. Construction history (include description and dates of major additions, alterations, or demolitions): <u>No major alterations are apparent.</u>
- 30. Original location X Moved Date of move(s): _____

V. Historical Associations

- 31. Original use(s): _____ Domestic, Single Dwelling
- 32. Intermediate use(s): _____
- 33. Current use(s): Domestic, Single Dwelling
- 34. Site type(s): Residential Neighborhood

Architectural Inventory Form (page 3 of 4)

- 35. Historical background: <u>Fredrick B. Dunn is listed as owner in the 1955 and 1956</u> <u>directories. The 1955 listing is the first instance of this address in the available</u> <u>directories. This building is part of Eastholme-in-Grandview Subdivision. This part of the</u> <u>larger Grandview Subdivision was owned by Eugene and Annabelle Helms, Richard and</u> <u>Ella Mae Bouman, Coe Van Deren, and John and Ruth Dyer and developed in 1950.</u>
- 36. Sources of information: <u>Mesa County Assessors Office; Museum of Western Colorado</u> <u>Archives; Polk Directories 1951, 1955, 1956, 1957</u>

VI. Significance

- 37. Local landmark designation: Yes ____ No _X ___ Date of designation: _____
 Designating authority: ______
- 38. Applicable National Register Criteria:
 - X A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important in history or prehistory.
 - Qualifies under Criteria Considerations A through G (see Manual)
 - Does not meet any of the above National Register criteria
- 39. Area(s) of significance: Architecture, Community Development and Planning
- 40. Period of significance: 1951; 1943 to 1957 Uranium Boom
- 41. Level of significance: National _____ State ____ Local X
- 42. Statement of significance: <u>The development in this area is a direct result of the nation's involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier.</u>

Architectural Inventory Form (page 4 of 4)

development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production.

43. Assessment of historic physical integrity related to significance: <u>The house appears intact</u> in its original condition.


VII. National Register Eligibility Assessment

v

44. National Register eligibility field assessment:	
Eligible Not Eligible 🗶 Need Data	
45. Is there National Register district potential? Yes No X	Discuss:
If there is National Register district potential, is this building:	Contributing
	Noncontributing
46. If the building is in existing National Register district, is it:	Contributing
	Noncontributing
III. Recording Information	
47. Photograph numbers: Roll # 3 Frame # 4	
Negatives filed at: City of Grand Junction Planning Dept.	
48. Report title: <u>Grand Junction Phase 3 Survey</u> 49. Date(s): <u>N</u>	larch 2005
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H	lerron
51. Organization: Reid Architects, Inc.	
52. Address: PO Box 1303 Aspen, Colorado 81612	
53. Phone number(s): 970 920 9225	

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.


Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395



1343 Hall Ave.



Grand Junction, Colorado image from 2002 aerial map



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



