OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Official eligibility determination (OAHP use only) Date Initials

- Date _____Ini _____ Determined Eligible- NR
- Determined Not Eligible- NR
- Determined Eligible- SR Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District
- Noncontributing to eligible NR District

I. Identification

- 1. Resource number: _____5ME.14824
- 2. Temporary resource number: 2411.BUN
- 3. County: <u>Mesa</u>
- 4. City: Grand Junction
- Historic building name: <u>n/a</u>
- Current building name: <u>n/a</u>
- 7. Building address: 2411 Bunting Ave.
- 8. Owner name and address: Scott C Mueller

2411 Bunting Ave_Grand Junction, CO 81501-6221

II. Geographic Information

9. P.M. <u>Ute Principal Meridian</u> Township <u>1 South</u> Range <u>1 West</u> <u>NE 1/4 of SW 1/4 of SE 1/4 of SE 1/4 of section 12</u>

10. UTM reference

- Zone <u>1 2; 7 1 3 0 6 5 mE 4 3 2 8 3 8 1 mN</u>
- 11. USGS quad name: Grand Junction Quadrangle
- Year:
 1962
 rev.1973
 Map scale:
 7.5'
 X
 15'
 Attach photo copy of appropriate map section.

 12. Lot(s):
 8
 Block:
 3

Addition: Teller Acres Year of Addition: 1947

13. Boundary Description and Justification: Legal description of the site is: Lot 8 Blk 3 Teller Acres

Assessors Office Parcel ID # 2945-124-24-008

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape): Irregular Plan
- 15. Dimensions in feet: Length <u>38'</u>x Width <u>43'</u>
- 16. Number of stories: 1
- 17. Primary external wall material(s) (enter no more than two): Brick
- 18. Roof configuration: (enter no more than one): Side Gabled Roof
- 19. Primary external roof material (enter no more than one): Asphalt Roof
- 20. Special features (enter all that apply): ___Porch____

Resource Number:	5ME.14824
Temporary Resource Number:	2411.BUN

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: <u>This is a small masonry side gabled house with a series of additive volumes.</u> The main ridge runs east/west and the principal façade faces north. The entry door is located off center to the right and is recessed back under the primary roof form about 2'. A picture window is located to the right and is flanked by one vertically proportioned window on the left. A wood mullion sits at the corner and a similar window is located on the west side. The entry has a concrete slab which fills the entire recessed area, a low wall extends forward from the side wall of the recess and locates the single concrete step up to the porch area. The roof overhang is supported by a decorative metal support. On the left side of the façade a pair of double hung windows. sit on the corner with a wood corner mullion. The head and sill match the principal window. The window wraps the corner on this side as well. On the west side a low pitched shed roof addition extends to the west. It has a sliding glass door in the corner and a brick veneer wall. The addition wraps the southwest corner of the building. The façade has an all over brick veneer, the side walls have brick up to the eave and vertical siding in the gable ends.
- 22. Architectural style/building type: Ranch Type
- 23. Landscaping or special setting features: <u>The house sits on a small lot, fairly close to the</u> street. <u>The yard is predominantly lawn, and the area has a very nice group of street</u> trees.

24. Associated buildings, features, or objects: none seen

IV. Architectural History

- 25. Date of Construction: Estimate: 1950
 Actual:

 Source of information:
 Mesa County Assessors Office

 26. Architect:
 unknown

 Source of information:
 27. Builder/Contractor:

 27. Builder/Contractor:
 unknown

 Source of information:
 28. Original owner:

 28. Original owner:
 Roy L. Garner or Gardner

 Source of information:
 1951 Polk Directory

 29. Construction history (include description and dates of major additions, alterations, or demolitions):
 Additions to the rear; dates unknown
- 30. Original location X Moved Date of move(s):

V. Historical Associations

- 31. Original use(s): _____ Domestic, Single Dwelling
- 32. Intermediate use(s):

Architectural Inventory Form (page 3 of 4)

- 33. Current use(s): Domestic, Single Dwelling
- 34. Site type(s): _____ Residential Neighborhood
- 35. Historical background: <u>Roy L. Garner is shown as owner in the directory of 1950.</u> <u>Roy L. Gardner is shown in the directories of 1955 and 56. This building is part of Teller</u> <u>Acres, developed about 1947 by V. A. Green and Ivah Green, A. E. Borschell, Oscar and</u> <u>Ruth Redd, George H. Weldon and J. W. Miller. Virgil Green was a building contractor.</u>
- 36. Sources of information: <u>Mesa County Assessors Office; Museum of Western Colorado</u> <u>Archives; Polk Directories 1951, 1955, 1956, 1957</u>

VI. Significance

- 37. Local landmark designation: Yes _____ No _X ___ Date of designation: ______
 Designating authority: ______
- 38. Applicable National Register Criteria:
 - X A. Associated with events that have made a significant contribution to the broad pattern of our history;

B. Associated with the lives of persons significant in our past;

- X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
- D. Has yielded, or may be likely to yield, information important in history or prehistory.
- ____Qualifies under Criteria Considerations A through G (see Manual)
 - ____Does not meet any of the above National Register criteria

39. Area(s) of significance: Architecture, Community Development and Planning

- 40. Period of significance: 1950; 1943 to 1957 Uranium Boom
- 41. Level of significance: National _____ State ____ Local__X___
- 42. Statement of significance: The development in this area is a direct result of the nation's involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass

Architectural Inventory Form (page 4 of 4)

produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production.

43. Assessment of historic physical integrity related to significance: <u>The additions alter the</u> <u>original scale and formality of the structure, somewhat compromising the integrity.</u>

VII. National Register Eligibility Assessment

- 44. National Register eligibility field assessment:
 - Eligible ____ Not Eligible _X__ Need Data ___
- 45. Is there National Register district potential? Yes No X Discuss:
 If there is National Register district potential, is this building:
 Contributing Noncontributing Noncontributi

VIII. Recording Information

- 47. Photograph numbers: Roll # 2 Frame # 10 Negatives filed at: City of Grand Junction Planning Dept.
- 48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005

50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron


51. Organization: Reid Architects, Inc.

52. Address: PO Box 1303 Aspen, Colorado 81612

53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




2411 Bunting Ave.



Grand Junction, Colorado *image from 2002 aerial map*

City of Grand Junction • Phase Three Survey 2004



GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14824 2411 Bunting Ave. Roll # 2 Frame # 10 Looking southeast Grand Junction, Mesa County, CO WHF BA010A1X0N NNN- 2 5652 00291,5 011 share 54725