

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

Official eligibility determination (OAHP use only)

Date _____ Initials _____

- Determined Eligible- NR
- Determined Not Eligible- NR
- Determined Eligible- SR
- Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District
- Noncontributing to eligible NR District

I. Identification

1. Resource number: 5ME.14808
2. Temporary resource number: 1620.NINT
3. County: Mesa
4. City: Grand Junction
5. Historic building name: n/a
6. Current building name: n/a
7. Building address: 1620 N. 19th Street
8. Owner name and address: Steven R Hejl
667 24 1/2 Rd Grand Junction, CO 81505-1246

II. Geographic Information

9. P.M. Ute Principal Meridian Township 1 South Range 1 West
NW 1/4 of SW 1/4 of NW 1/4 of SE 1/4 of section 12
10. UTM reference
Zone 1 2; 7 1 2 5 3 9 mE 4 3 2 8 7 8 7 mN
11. USGS quad name: Grand Junction Quadrangle
Year: 1962 rev.1973 Map scale: 7.5' X 15' *Attach photo copy of appropriate map section.*
12. Lot(s): 9 Block: 1
Addition: Delmar Pk & Hickman Year of Addition: 1950
13. Boundary Description and Justification: Legal description of the site is: Lot 9 Blk 1 Del Mar Park Refile
Assessors Office Parcel ID # 2945-124-14-004
This description was chosen as the most specific and customary description of the site.

III. Architectural Description

14. Building plan (footprint, shape): Rectangular Plan
15. Dimensions in feet: Length 24' x Width 30'
16. Number of stories: 1
17. Primary external wall material(s) (enter no more than two): Brick, Wood Horizontal Siding
18. Roof configuration: (enter no more than one): Side Gabled Roof
19. Primary external roof material (enter no more than one): Asphalt Roof
20. Special features (enter all that apply): Car port

Resource Number: 5ME.14808
Temporary Resource Number: 1620.NINT

Architectural Inventory Form
(page 2 of 4)

21. General architectural description: This is a simple rectangular wood frame house with a moderately pitched side gable roof. The ridge runs north/south and the principal façade faces west. The roof has a minimal overhang on the gable ends, but a longer overhang on the front eave. The entry door is generally centered with a single concrete step up to the door. A sliding glass door is located to the right of the door. A single horizontally proportioned window is located to the left side with a single vertical muntin. The window heads align and are just below the level of the overhang soffit. The street facing wall has a brick veneer which extends off the left side of the house a couple of feet, about 4' high. The sides have horizontal siding with vertical siding at the gable ends. A simple shed roof carport is located on the south side.
22. Architectural style/building type: Ranch Type
23. Landscaping or special setting features: The house sits on a almost the full width of a long narrow lot with a number of trees and shrubs, otherwise the yard is predominantly lawn.
24. Associated buildings, features, or objects: none

IV. Architectural History

25. Date of Construction: Estimate: 1953 Actual: _____
Source of information: Mesa County Assessors Office
26. Architect: unknown
Source of information: _____
27. Builder/Contractor: unknown
Source of information: _____
28. Original owner: unknown
Source of information: _____
29. Construction history (include description and dates of major additions, alterations, or demolitions): Window replacement and carport added; dates unknown
30. Original location Moved _____ Date of move(s): _____

V. Historical Associations

31. Original use(s): Domestic, Single Dwelling
32. Intermediate use(s): _____
33. Current use(s): Domestic, Single Dwelling
34. Site type(s): Residential Neighborhood
35. Historical background: H. C. Brown is shown as occupant in the 1955 directory, but otherwise no specific associations were found.
36. Sources of information: Mesa County Assessors Office; Museum of Western Colorado Archives; Polk Directories 1955, 1956, 1957

Resource Number: 5ME.14808
Temporary Resource Number: 1620.NINT

Architectural Inventory Form
(page 3 of 4)

VI. Significance

37. Local landmark designation: Yes No Date of designation: _____
Designating authority: _____

38. Applicable National Register Criteria:

- A. Associated with events that have made a significant contribution to the broad pattern of our history;
- B. Associated with the lives of persons significant in our past;
- C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
- D. Has yielded, or may be likely to yield, information important in history or prehistory.
- Qualifies under Criteria Considerations A through G (see Manual)
- Does not meet any of the above National Register criteria

39. Area(s) of significance: Architecture, Community Development and Planning

40. Period of significance: 1953; 1943 to 1957 Uranium Boom

41. Level of significance: National State Local

42. Statement of significance: The development in this area is a direct result of the nation's involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production.

43. Assessment of historic physical integrity related to significance: The house appears generally intact with some material replacement.

Resource Number: 5ME.14808
Temporary Resource Number: 1620.NINT

Architectural Inventory Form
(page 4 of 4)

VII. National Register Eligibility Assessment


44. National Register eligibility field assessment:
Eligible Not Eligible Need Data
45. Is there National Register district potential? Yes No Discuss: _____
If there is National Register district potential, is this building: Contributing _____
Noncontributing _____
46. If the building is in existing National Register district, is it: Contributing _____
Noncontributing _____

VIII. Recording Information

47. Photograph numbers: Roll # 2 Frame # 14
Negatives filed at: City of Grand Junction Planning Dept.
48. Report title: Grand Junction Phase 3 Survey 49. Date(s): March 2005
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia Herron
51. Organization: Reid Architects, Inc.
52. Address: PO Box 1303 Aspen, Colorado 81612
53. Phone number(s): 970 920 9225

NOTE: Please attach a sketch map, a photocopy of the USGS quad. map indicating resource location, and photographs.

Colorado Historical Society - Office of Archaeology & Historic Preservation
1300 Broadway, Denver, CO 80203 (303) 866-3395




1620 N. 19th Street



North

Grand Junction, Colorado
image from 2002 aerial map

City of Grand Junction • Phase Three Survey
2004



TN MN
11 1/4°



Map created with TOPO!® ©2003 National Geographic (www.nationalgeographic.com/topo)

GRAND JUNCTION, COLORADO

Phase Three Historic Survey

2004



5ME.14808

1620 N. 19th Street

Roll # 2 Frame # 14

Looking northeast

Grand Junction, Mesa County, CO

WHF BA010A1X0N NNN+ 1 5652 002915

015

sharp

54729