OAHP1403 Rev. 9/98

per.

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

1 of 4

Official eligibility determination (OAHP use only) Date ______Initials ______ Determined Eligible- NR Determined Not Eligible- NR

- Determined Eligible- SR Determined Not Eligible- SR
- Need Data
- Contributes to eligible NR District
 - Noncontributing to eligible NR District

I. Identification

- 1. Resource number: 5ME.14812
- 2. Temporary resource number: 1525.TWFS
- 3. County: <u>Mesa</u>
- 4. City: Grand Junction
- 5. Historic building name: _____n/a_____
- 6. Current building name: _____n/a___
- 7. Building address: 1525 N. 21st Street
- 8. Owner name and address: Richard W Rogers

1525 N 21st St Grand Junction, CO 81501-6629

II. Geographic Information

10. UTM reference

- Zone <u>1</u> <u>2</u>; <u>7</u> <u>1</u> <u>2</u> <u>6</u> <u>9</u> <u>9</u> mE <u>4</u> <u>3</u> <u>2</u> <u>8</u> <u>6</u> <u>9</u> <u>5</u> mN
- 11. USGS quad name:
 Grand Junction Quadrangle

 Year:
 1962 rev.1973

 Map scale:
 7.5' X

 15' Attach photo copy of appropriate map section.
- 12. Lot(s): 12
 Block: 2

 Addition: Delmar Park & Hickman
 Year of Addition: 1950
- 13. Boundary Description and Justification: Legal description of the site is: Lot 12 Blk 2 Del Mar Park Refile

Assessors Office Parcel ID # 2945-124-13-009

This description was chosen as the most specific and customary description of the site.

III. Architectural Description

- 14. Building plan (footprint, shape): Rectangular Plan
- 15. Dimensions in feet: Length 24' x Width 30'
- 16. Number of stories: 1
- 17. Primary external wall material(s) (enter no more than two): Brick, Wood Shingle
- 18. Roof configuration: (enter no more than one): Side Gabled Roof
- 19. Primary external roof material (enter no more than one): Asphalt_Roof____
- 20. Special features (enter all that apply): Fence

Resource Number:_ 5ME.14812 Temporary Resource Number: 1525, TWFS

Architectural Inventory Form (page 2 of 4)

- 21. General architectural description: This is a simple rectangular wood frame house with a moderately pitched side gable roof. The ridge runs north/south and the principal facade faces east. The roof has a minimal overhang on the gable ends, but a longer overhang on the front eave. The entry door is generally centered with a single concrete step up to the door. A large window group is located to the right of the door with two over three fixed and awning units. A single horizontally proportioned window is located to the left side with a single vertical muntin. The window heads align and are just below the level of the overhang soffit. The main facade has a brick veneer over the whole surface. The sides have wood shingle siding and two horizontally proportioned windows, evenly distributed.
- 22. Architectural style/building type: Ranch Type
- 23. Landscaping or special setting features: The house sits on a almost the full width of a long narrow lot with a number of trees and shrubs, otherwise the yard is predominantly lawn.
- 24. Associated buildings, features, or objects: none

IV. Architectural History

Actual: 25. Date of Construction: Estimate: 1953 Source of information: Mesa County Assessors Office

000000000		interest of the second se	
26. Architect:		unknown	
Source of int	formation:		
27. Builder/Cont	ractor:	unknown	
Source of inf	formation:		
28. Original owr	ner:	unknown	
Source of inf	formation:		

- 29. Construction history (include description and dates of major additions, alterations, or demolitions): <u>No alterations are apparent</u>
- 30. Original location X Moved Date of move(s):

V. Historical Associations

- 31. Original use(s): _____ Domestic, Single Dwelling
- 32. Intermediate use(s): ____
- Domestic, Single Dwelling 33. Current use(s):
- 34. Site type(s): ____ Residential Neighborhood
- 35. Historical background: No specific associations were found.
- 36. Sources of information: Mesa County Assessors Office; Museum of Western Colorado Archives; Polk Directories 1955, 1956, 1957

Resource Number: 5ME.14812 Temporary Resource Number: 1525.TWFS

Architectural Inventory Form (page 3 of 4)

VI. Significance


- 37. Local landmark designation: Yes _____ No <u>X</u> Date of designation: ______
 Designating authority: ______
- 38. Applicable National Register Criteria:
 - X A. Associated with events that have made a significant contribution to the broad pattern of our history;

B. Associated with the lives of persons significant in our past;

- X C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
- D. Has yielded, or may be likely to yield, information important in history or prehistory.
- ____Qualifies under Criteria Considerations A through G (see Manual)
 - Does not meet any of the above National Register criteria
- 39. Area(s) of significance: Architecture, Community Development and Planning
- 40. Period of significance: 1953; 1943 to 1957 Uranium Boom
- 41. Level of significance: National ____ State ____ Local X
- 42. Statement of significance: <u>The development in this area is a direct result of the nation's involvement in WWII and the drive for the development of nuclear weapons. The discovery of significant sources of Uranium in the region initiated development in Grand Junction that supported both the mining of the materials and the administration of programs related to the development of weapons. The building types, materials and neighborhood layout are all indicative of the national trends which were driven by the proliferation of the automobile and the enormous demand for single family homes. House designs departed from the romantic and revival styles that were prevalent in the earlier part of the 20th century and took on a California inspired design that was characterized by simple horizontally proportioned forms. Houses were typically mass produced on previously undeveloped tracts of land at the periphery of earlier development. These groups of houses were typically based on one or two plan types with a limited number of roof and exterior finish variations, further reinforcing the characteristics of mass production.</u>
- 43. Assessment of historic physical integrity related to significance: <u>The house is generally</u> intact.

Architectural Inventory Form (page 4 of 4)	
VII. National Register Eligibility Assessment	
44. National Register eligibility field assessment:	
Eligible Not Eligible _X Need Data	
45. Is there National Register district potential? Yes No X_	Discuss:
If there is National Register district potential, is this building:	Contributing
	Noncontributing
46. If the building is in existing National Register district, is it:	Contributing
	Noncontributing
VIII. Recording Information	
47. Photograph numbers: Roll # 1 Frame # 27	
Negatives filed at: City of Grand Junction Planning Dept.	
48. Report title: <u>Grand Junction Phase 3 Survey</u> 49. Date(s): <u>N</u>	larch 2005
50. Recorder(s): Suzannah Reid, Patrick Duffield and Lydia H	lerron
51. Organization: Reid Architects, Inc.	
52. Address: PO Box 1303 Aspen, Colorado 81612	· · · · · · · · · · · · · · · · · · ·
53. Phone number(s): 970 920 9225	

Colorado Historical Society - Office of Archaeology & Historic Preservation 1300 Broadway, Denver, CO 80203 (303) 866-3395




1525 N. 21st Street



Grand Junction, Colorado *image from 2002 aerial map*

City of Grand Junction • Phase Three Survey 2004



Map created with TOPO @ 2003 National Geographic (www.nationalgeographic.com/topo)

GRAND JUNCTION, COLORADO

Phase Three Historic Survey 2004



5ME.14812 1525 N. 21st Street Roll # 1 Frame # 27 Looking northwest Grand Junction, Mesa County, CO WHF BA010A1X0N NNN 0 5650 002913 54666 027 share CONTRACTOR CONTRA