COLORADO HISTORICAL SOCIETY
Office of Archaeology and Historic Preservation
1300 Broadway Denver, Colorado 80203

HISTORIC BUILDING INVENTORY RECORD

| project name: | Grand Junction Down | itown Surve | У | | | | |
|--|-------------------------------------|-------------|-----------|------------|----------|--|--|
| county: | Mesa | city: | Grand J | unction | | | |
| state ID no. | 5ME 4198 | temp | orary no | | | | |
| current buildi | ng name: Schiesswoh | l Building | | | | | |
| address: | 560 Colorado 126 S. Sixth Street | , Grand Ju | nction, | CO 81501 | | | |
| owner: | R. Schiesswohl, 570 81501-2138 | Hall Ave. | , Grand | Junction | | | |
| township: 15 | range: 1W sect | ion: 14, | SE 1/4, | SW 1/4 | | | |
| historic name: | | | | | | | |
| USGS quad name: Grand Jct., CO 1962 N3900-W10830 X 7.5' 15 | | | | | | | |
| district name: | | | | | | | |
| block: 117 lot(s) 17-21 addition: City | | | | | | | |
| yr. of addition | n | | | | | | |
| film roll by: Marty Alexandroff no. | | | | | | | |
| negative nos. | 6835-18 | | | | | | |
| location of negatives: City of Grand Junction | | | | | | | |
| date of construction estimate1908_actual | | | | | | | |
| source: 1993 | Historic Building In | ventory Re | cord | | | | |
| use: comme | rcial present | comm | ercial | historic | Z | | |
| condition:deteriorat | excellent X | good | fair | | | | |
| extent of alter | rations:minor | X modera | tema | ajor | | | |
| describe: New windows, recess | windows on second l sed doors | evel, pain | ted bricl | c, display | | | |
| style: Commercial/Italianate | | | | | | | |

if inventoried, list ID nos.

architectural description: Two-story, simple Italianate design typical of the early 20th Century commercial architecture. The first floor of the front facade has four storefront bays, each with a large display window and a single wood and glass door. Clerestories are boarded with wood, but original glazing pattern is still evident in the remaining nuntins. At the south end of the bays is a double-door entry with glass transom to the second floor. The second story of the front facade has eight evenlyspaced, one-over-one new windows and two-over-two window located over the second floor entry. The windows are accented by sandstone caps and the arched window features a Romanesque arched voussoir also in sandstone. The front rises above the actual roofline of the building and has an elaborate sheet metal cornice topped by a brick parapet with inlaid brick panels and a decorative sandstone cap. The back facade of the building is very plain and functional with two entries and two upper floor windows. The side facades are not as detailed as the front, each having only a few simple windows. The stone accents are repeated on the second floor window of the north, alley-facing facade. A wing was added in 1934 which is now 560 Colorado. It has an angled corner and commercial display windows.

architect: J. B. Boyer, J. R. Wilson source: 1993 Historic Inventory Record

original owner: Jacob H. Schiesswohl source: 1993 Historic Inventory Record

builder/contractor: Louis Spallone & Nunzio Grasso/R. A. Mathews

Construction Co.

source: 1993 Historic Inventory Record

theme(s): Plateau Country/commerical

construction history: (description, names, dates, etc. relating to major additions or alterations to original structure)

The original two-story recgangular structure of the Schiesswohl building was constructed in phases with different contractors used for each phase. In 1925 Schiesswohl built a filling station for and leased the two adjacent lots to the south of his building. A larger station was completed in 1934.

historic background (discuss important persons and events associated with this structure)

Jacob H. Schiesswohl was a successful real estate and insurance businessman in Grand Junction in the late 1890s and early 1900s. He built himself and office with additional space he could lease for added business income.

significance: (check appropriate categories and briefly justify
 below)

| | architectural: | | hi | storic significance |
|-----|----------------|------------------|------|---------------------|
| | represents the | work of a master | X | associated with |
| 11- | | | sign | ificant persons |
| | possesses high | artistic values | X | associated with |
| | | | | significant events |
| | | | or r | patterns |

X represents a type, period or method of construction

X contributes to an historic district

statement of significance:

Contributing; The Schiesswohl Building is architecturally significant because it is the best preserved example of a structure of this period and type in the Grand Junction downtown area. Its location just off of Main Street saved it from the ravages of alterations suffered by most other, more preominent buildings of its period. Historically, the Schiesswohl Building has mirrored the prevailing conditions of the local economy, serivng at verious times a wide variety of office, retail, commercial, and even residential uses.

references (be specific)
1993 Historic Building Inventory Record

Surveyed by: Marty Alexandroff affiliation: Winter & Company date: July, 1994



560 Colorado Avenue

Current Google Street View

July 2012