COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, Colorado 80203

HISTORIC BUILDING INVENTORY RECORD

	Project name:	Grand Junction Downtown Survey			
	County:	Mesa	City:	Grand Junction	
	State ID no.	5ME 4128	Temp	orary no.	
	Current building name: A.G. Edwards / Back Porch Music				
	Address:	501/511 Main, Grand Junction, CO 81501			
	Owner:	Sanna Marie Foster, C.A. Newton & A.D. Raso, 3525 Senna Way, Grand Junction, CO 81506-8488			
	Township: 1S	range: 1W section	n: 14,	NE I/4, SW I/4	
	Historic name: The Fair Building				
	USGS quad name: Grand Jct., CO 1962 N3900-W10830 _X 7.5' _15'				
	District name:				
	Block: 117 lot(s) 1, 2, 3 Addition: City				
	Yr. of addition				
	Film roll by: Marty Alexandroff no.				
	Negative nos. 6138-7, 5858-14				
	Location of negatives: City of Grand Junction				
	Date of construction: 1905-10 estimateactual Source: 1992 Historic Building Inventory Record				
	Use:comme	rcialpresent		commercialhistoric	
	Condition:X_ excellent goodfairdeteriorating				

Extent of alterations:minormoderate _X_major				
Describe: Painted brick, new display windows, entries; alterations are compatible				
Style: Commercial/19 th Century Vernacular				
Stories: 2				
X_originalmoved date(s) of move:				
Materials: Brick (painted), stone, iron				
Square footage: 31500				
National Register Eligibility: Individual: _Xyesno Contributing to district: _Xyesno				
Local landmark designation:namedate				
Associated buildings?yes type:				
If inventoried, list ID nos.				
Architectural description: Two-story brick structure; a simple unadorned example of turn-of-the-century Vernacular Commercial style. Evenly spaced windows with flatstone arches and sills, and indented pediment pattern in the brickwork; display windows on the Main Street side with etched glass panes above them.				
Architect: unknown Source:				
Original owner: William J. Moyers Source: 1992 Historic Building Inventory Form				
Builder/contractor: unknown				

Theme(s): Plateau Country/commercial

Construction history (description, names, dates, etc. relating to major additions or alterations to original structure): The Fair Building was built around 1910 to house a thriving mercantile store owned by William J. Moyers. It continued in this use until the Great Depression when the store failed. A Montgomery Wards outlet occupied the space in 1936. The owners attached a corrugated metal façade, changed the display windows and blocked in the windows on the west side, after the style of the 1940s and

1950s to "modernize" the look of the store. This façade was removed in 1983 when a rehabilitation project designed by architect Robert Jenkins attempted to restore the building to its original Main Street front.

Historic background (discuss important persons and events associated with this structure): This building housed one of the largest department stores on the western slope of Colorado. William J. Movers opened his first "Fair" store in 1890 in a small frame building on the south side of Main Street in Grand Junction. His store became known for its fine merchandise and good service. The store prospered and outgrew its location twice before Moyers had the building at 501 Main built in 1910. For the next twenty-five years "The Fair" was in its heyday, handling high quality merchandise that included everything from clothing to household goods. Moyers himself was the driving force behind the success of the store. He was reputed to insist on good quality and attempted to provide a good working atmosphere for his employees. He was a business leader and philanthropist in the local community with a reputation for great generosity. He contributed to many public projects, including the construction of many roads in western Colorado before the state began to fund highway projects. His most notable local contribution was that of a public swimming pool, given to the residents of the city of Grand Junction in June 1922, stipulating that the children should have two days a week to swim free of charge.

Significance: (check appropriate categorial	ories and briefly justify below)		
Architectural significance:	Historic significance:		
represents the work of a master	_X_ associated with significant persons		
possesses high artistic values	X associated with significant events		
	or patterns		
X represents a type, period or method of construction	X contributes to an historic district		

Statement of significance:

Contributing; "The Fair" Building is important because it represent a good example of a historic commercial enterprise and has been restored to its original style and use and serves as a memorial to William J. Moyers, who contributed a great deal to the community of Grand Junction.

References (be specific)
1981 Historic Survey of City
1992 Historic Building Inventory Form

Surveyed by: Marty Alexandroff affiliation: Winter & Company

Date: July, 1994





