2

.

COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203		SITE NO.: 5ME8297 Eligible for National Registeryesno dateinitials CriteriaABCD
HISTORIC BUIL	DING INVENTORY	Contributes to a potential National Register districtyesno district name:
COUNTY: Mesa	City: Grand Junction	dateinitialsicic Criteriaabcde Areas of significance:
HISTORIC BUILDING NAME: The house at 1015 N. 4th Street		Period of significanceinitiais
CURRENT BUILDING NAME: Resce Residence		LOCAL LANDMARK DESIGNATION: [] yes [X] no Date of designation: N/A
ADDRESS: 1015 N. 4th St., Grand Junction,	CO 81501-7502	Designating authority: N/A
		P.M.: UTE township: 1S range:1W NE ¼ of NE ¼ of NW¼ of NW¼ of section 14
OWNER NAME & ADDRESS: Carmelia S. Reece, 1015 N. 4th St., Grand Junction, CO 81501-7502		UTM REFERENCE-12 Easting: 710560 Northing: 4327960
		USGS QUAD NAME: Grand Junction
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'
STYLE: Bungalow		Block: 9 Lot(s): S47,5' of 12 - 16 Addition: Year of addition:
BUILDING TYPE:		[X] original location [] moved
		Date of moves(s);
MATERIALS: Concrete Foundation - Wood Frame - Asphalt Shingle Roof		HISTORIC USE: Domestic
		PRESENT USE: Domestic
STORIES: 1	SQUARE FOOTAGE: 1120	DATE OF CONSTRUCTION- estimate: 1929 actual: Source of information: Tax Assessor's Records
PLAN SHAPE:	north arrow	ARCHITECT: Unknown
	\Leftrightarrow	Source of information:
5		BUILDER/CONTRACTOR: Unknown
لــــــــــــــــــــــــــــــــــــ		Source of information:
Г		ORIGINAL OWNER: W.H. Andregg
	8	Source of information: Lot and Block Books
L	7	ASSOCIATED BUILDINGS- [X] YOB [] NO
		Type: Garage/Shed

over paneled front door with a fan light. A Ch double hung wood sash, two, three and four, steps. Gray composition shingle roof with bar Landscaped with lawn and large arborvita Ash tree in parking area.	icago window is on each side of the facade, and o over one. Aluminum frame storm windows. White geboards. Brick chimney on south slope. S on each side of facade. Large roses on north ar n composition shingle roof, white vertical siding an	the steps and stoop with iron railing, lead up to gabled hight trellis is on both sides of the portico. Storm door ne on the south elevation. Windows around house are narrow lapped siding and trim. Green foundation and nd south edges of lawn. Chain link fence around yard. Id metal door. Alley access. Small storage building in
PHOTOGRAPHS (include photographs showing	each side of building and any associated buildings))
Film roll no.: 29 Negative no.: 20	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction	n
CONSTRUCTION HISTORY (Include description and in Assessor's records.	d dates of major additions, alterations, or demolitio	ns): Additional construction or modifications not noted
Norron, ca. 1929, and sold to W. Herman And	egg. Andregg was the owner/occupant ca. 1930-1 s owners/residents ca. 1939-1941. Carmella and H	he house was apparently constructed by Harter and 1935. Robert and C.F. Mitchell, a construction worker, Hollister H. Reece, a engineer for the Denver and Rio
INFORMATION SOURCES (be specific): Plat Map	Appraisal Card, Lot and Block Books, Grand Junc	tion City Directories
SIGNIFICANCE (check appropriate categories)		THEME(S):
Architectural significance:] represents the work of a master] possess high artistic value [X] represents a type, period, or method of	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district	
construction		
construction National Register eligibility: Individual [] yes [X] no Criteria: [] A [] B [] C [] D	Contributes to a potential district: []yes [X]no District name:	
	[]yes [X]no	
construction National Register eligibility: Individual [] yes [X] no Criteria: [] A [] B [] C [] D Area(s) of significance: Architecture Period of significance: 1929	[jyes [X]no District name: gnificance checked above): There are few Bunga	low features on this house. The most distinctive detail r the National Register, this house may contribute to a
construction National Register eligibility: ndividual [] yes [X] no Criteria: [] A [] B [] C [] D Area(s) of significance: Architecture Period of significance: 1929 STATEMENT OF SIGNIFICANCE (briefly justify the si is the three Chicago windows, which are often to boal register.	[jyes [X]no District name: gnificance checked above): There are few Bunga seen in this neighborhood. Although not eligible fo	low features on this house. The most distinctive detail r the National Register, this house may contribute to a DATE: 3/29/96
construction National Register eligibility: Individual [] yes [X] no Criteria: [] A [] B [] C [] D Area(s) of significance: Architecture Period of significance: 1929 STATEMENT OF SIGNIFICANCE (briefly justify the si s the three Chicago windows, which are often o	[jyes [X]no District name: gnificance checked above): There are few Bunga seen in this neighborhood. Although not eligible fo	r the National Register, this house may contribute to a




 1015 N. 4th St., Grand Junction, Mesa Co, CO

 2945-142-03-007
 02/07/1996

 Roll
 29 Frame
 20 View E
 Dir NW

 5mE82.97
 5mE82.97
 5mE82.97
 5mE82.97



 1015 N. 4th St., Grand Junction, Mesa Co, CO

 2945-142-03-007
 02/07/1996

 Roll
 29
 Frame
 20
 View E
 Dir NW

 SME
 8297

ŝ,