
OAHP1403.wp2

COLORADO	HISTORICAL SOCIETY	
Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203 HISTORIC BUILDING INVENTORY		SITE NO.: 5ME7436 Eligible for National Registeryesno
		dateinitials CriteriaABCD Contributes to a potential National Register district yesno district name:
COUNTY: Mesa	CITY: Grand Junction	Eligible for State Registeryesno dateinitials Criteriaabcde Areas of significance:
HISTORIC BUILDING NAME: Miller, Florence, House		Period of significance Initials
CURRENT BUILDING NAME: Blackburn Residence ADDRESS: 624 N. 15th St., Grand Junction, CO 81501-4422		LOCAL LANDMARK DESIGNATION: [] YES [X] NO
		Date of designation: N/A Designating authority: N/A
		P.M.: UTE township: 1S range:1W NW ¼ of NW ¼ of SE¼ of NW¼ of section 13
OWNER NAME & ADDRESS: Olive L. Blackburn, 624 N. 15th St., Grand Junction, CO 81501-4422		UTM REFERENCE-12 Easting: 712180 Northing: 4327510
		USGS QUAD NAME: Grand Junction
Part Purcha Part at		Year: 1962; photorevised 1973 [X] 7.5' [] 15'
STYLE: Pueblo Revival BUILDING TYPE:		Block: 9 Lot(s): 7-9 Addition: Slocumb Year of addition: 1906
		[X] original location [] moved
		Date of moves(s):
MATERIALS: Concrete Foundation; Frame Stucco; Asphalt Shingle Roof		HISTORIC USE: Domestic
		PRESENT USE: Domestic
TORIES: 1	SQUARE FOOTAGE: 840	DATE OF CONSTRUCTION- estimate: 1946 actual: Source of information: Tax Assessor's Records
AN SHAPE:	north arrow	ARCHITECT: Unknown
	·	Source of information:
		BUILDER/CONTRACTOR: Unknown
	1	Source of information:
	1	ORIGINAL OWNER: Florence Miller
	4. 6	Source of information: Lot and Block Books
		Associated Buildings- (X) yes () no
		Type: Carport

with plain window surrounds. Removable awning	picture window on south facade of house. Oth s over windows and front door. Stucco walls. s on facade and sides of house. Picket fence a	rought iron railings, and concrete front stoop lead to flush her windows are double hung wood sash, six-over-one around back yard containing Red Bud and Missouri
PHOTOGRAPHS (Include photographs showing each	n side of building and any associated buildings))
Film roll no.: 7 Negative no.: 21	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction	
CONSTRUCTION HISTORY (include description and d modifications not noted in Assessor's Records.	ates of major additions, alterations, or demolitio	ins): Metal awnings. Additional construction or
Florence (Mrs. George) Miller. According to long-	time owner Mrs. Olive (Roy) Blackburn, ca. 194 y who owned cabins across the street. Mrs. Bl	Constructed ca. 1946, this residence was first owned by 46-present, the house was actually constructed in 1942 lackburn remembers purchasing the house in 1946 from Directories.
SIGNIFICANCE (check appropriate categories) Architectural significance: [] represents the work of a master [] possess high artistic value [X] represents a type, period, or method of construction	Historical significance:] associated with significant person(s)] associated with significant event] associated with a pattern of events] contributes to an historic district	Theme(s):
National Register eilgibility: Individual [] yes [X] no Criteria: [] A [] B [3 C [] D Area(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:	
Period of significance: 1946		
in the early 1940s to the east of the original square	icance checked above): This Pueblo Revival a mile of the city of Grand Junction. The flat ro bouse has a raised foundation in keeping with	I house represents the middle-class housing expansion of and stucco walls had an economic appeal to builders in the other houses in the neighborhood.
with limited resources. Not typical of this style, this		
		DATE: 2/14/96
with limited resources. Not typical of this style, this NVENTORY COMPLETED BY: Museum Group Staff NFFILIATION: Museum of Western Colorado		DATE: 2/14/96 Рноме: (970) 241-9117





624 N. 15th St. Grand Junction, Mesa Co, CO 2945-132-05-007 5ME7436