COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203		SITE NO.: 5ME7770
		Eligible for National Registeryesno
HISTORIC BUILDING INVENTORY		dateinitials
County: Mesa	Слу: Grand Junction	Eligible for State Registeryesno dateinitials  Criteriaabcde  Areas of significance:
HISTORIC BUILDING NAME: Hinman, Willis, House		Period of significance
CURRENT BUILDING NAME: Cochran Residence		LOCAL LANDMARK DESIGNATION: [ ] yes [X] no
ADDRESS: 1105 Grand Ave., Grand Junction, CO 81501-3429		Date of designation: N/A Designating authority: N/A
		P.M.: UTE township: 1S range:1W NW ½ of NE ½ of NE½ of SE½ of section 14
OWNER NAME & ADDRESS: Cleo Cochran, 1105 Grand Ave., Grand Junction, CO 81501-3429		UTM REFERENCE-12 Easting: 711650 Northing: 4327210
		USGS QUAD NAME: Grand Junction
		Year: 1962; photorevised 1973 [X] 7.5' [ ] 15'
STYLE: Bungalow		Block: 88 Lot(s): 1 and 2 Addition: Year of addition:
BUILDING TYPE:		[X] original location [] moved
MATERIAL CONTENTS Block Foundation Missel Form Assembly Block Book		Date of moves(s):  HISTORIC USE: Domestic
MATERIALS: Concrete Block Foundation - Wood Frame - Asphalt Shingle Roof		
		PRESENT USE: Domestic
STORIES: 1	SQUARE FOOTAGE: 1434	DATE OF CONSTRUCTION- estimate: 1905 actual: Source of information: Tax Assessor's Records
PLAN SHAPE:	north arrow	ARCHITECT: Unknown
		Source of Information:
F-4-7	<u>e</u>	Builder/contractor: Unknown
177		Source of information:
		ORIGINAL OWNER: Dr. A.P. Hubbard
		Source of information: Lot and Block
		Associated Buildings- [X] yes [] no
1 -1-	_1	Type: Garage
	·	

ARCHITECTURAL DESCRIPTION: One story with cross gables. Painted concrete block foundation. Concrete steps lead up to sunporch/entry with gable roof extending across west three-quarters of the facade. Ribbons of casement windows on three sides of sunporch have twelve lights each. Front door is paneled and has a four light window. Small, canvas awning overdoor. Windows around house are double hung wood sash, twelve and six over one; on he east elevation, they are one-over-one. All have storm windows. A gabled wing on the west elevation has another sun room with ribbons of six over one windows. A bay window with shed roof is on east elevation. Clapboard siding and foundation is barn red. Gables have the same siding with lecorative vertical half timbering. Door and window surrounds, doors, bargeboards and half timbering are peach. Windows frames and muntins are dark treen. Red composition shingle roof with two brick chimneys on east slope.

Landscaped with lawn, japonica bushes on west lawn and hedge and spirea on east lawn. Elm trees along parking area. Basket weave fence round back yard. Many cedar trees in backyard.

One car garage at rear with front gable, red simple drop siding, composition shingle roof and batten swinging doors.

FILIATION: Museum of Western Colorado

DRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020

HOTOGRAPHS (include photographs showing e	each side of building and any associated buildings)		
ilm roll no.: 17 legative no.: 2	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction		
ONSTRUCTION HISTORY (include description an nodifications not noted in Assessor's records.	d dates of major additions, alterations, or demolitions)	: Storm windows. Additional construction or	
908, was Dr. Allen P. Hubbard who was living orbeck's were prominent local merchants who inman, a well-known local attorney, political a	rsons and events associated with this building): The it is there in 1910. From ca. 1913-1922, the residents/over the residents/over as a sporting goods store. Mrs. Vorbeck was active and community leader, owned/resided in the house fro- il ca. 1973. Mrs. Hinman lived there until her death.	vners were Marguerite and Herman W. Vorbeck, The e in the Republican Party, Grace and Willis R,	
FORMATION SOURCES (be specific): Plat Map, unction, Grand Junction Daily Sentine) News	Appraisal Card, Lot and Block Books, Grand Junction spaper, 17 Nov 1942, p2.	City Directories, 1981 Historic Survey of Grand	
GNIFICANCE (check appropriate categories)		THEME(s):	
chitectural significance: represents the work of a master possess high artistic value ] represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district		
ational Register eligibility: dividual [] yes [X] no iteria: [] A [] B [] C [] D ea(s) of significance: Architecture	Contributes to a potential district: []yes [ X]no District name:		
eriod of significance: 1905			
ngalows. Bungalows which are built on corn	gnificance checked above): A large Bungalow with her lots occasionally have two sun porches. One facestion to Mr. Hinman suggests possible local eligibility.	alf-timbering in the gables, uncommon for the avenue on the facade. Another porch on the	
/ENTORY COMPLETED BY: Museum Group Staff		DATE: 2/14/96	

PHONE: (970) 241-9117

Resources Survey, Phase 2

PROJECT NAME: Grand Junction Historic



1105 Grand Ave.

Grand Junction, Mesa Co, CO

2945-144-01-001

01/12/1996 Roll 17 Frame 02

View N Dir SE

5ME7770

5ME7770



1105 Grand Ave. Grand Junction, Mesa Co, CO 2945-144-01-001 5ME7770