COLORADO HISTORICAL SOCIETY		SITE NO.: 5ME7776
Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203		Eligible for National Registeryesno
HISTORIC BUILDING INVENTORY		dateinitials
County: Mesa	City: Grand Junction	Eligible for State Registeryesno dateinitials Criteriaabcde Areas of significance:
HISTORIC BUILDING NAME: Best, Robert, House		Period of significance
CURRENT BUILDING NAME: Flynn Residence		LOCAL LANDMARK DESIGNATION: [] yes [X] no
ADDRESS: 1025 Grand Ave., Grand Junction, CO 81501-3427		Date of designation: N/A Designating authority: N/A
		P.M.: UTE township: 1S range:1W NE ½ of NW ½ of NE½ of SE½ of section 14
OWNER NAME & ADDRESS: Mary A. Flynn, 1025 Grand Ave., Grand Junction, CO 81501-3427		UTM REFERENCE-12 Easting: 711550 Northing: 4327210
		USGS QUAD NAME: Grand Junction
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'
STYLE: Queen Anne		Block: 87 Lot(s): E 21' of 5 all 6 and 7 Addition: Year of addition:
BUILDING TYPE:		[X] original location [] moved
		Date of moves(s):
MATERIALS: Mud Sills - Wood Frame - Asphalt Shingle Roof		HISTORIC USE: Domestic
		PRESENT USE: Domestic
STORIES: 1.5	SQUARE FOOTAGE: 949	DATE OF CONSTRUCTION- estimate: 1902 actual: Source of information: Tax Assessor's Records
PLAN SHAPE:	north arrow	ARCHITECT: Unknown
	ED	Source of information:
Cap. CD		BUILDER/CONTRACTOR: Unknown
Gr SHED	1	Source of information:
	ነ	ORIGINAL OWNER: Robert and Winifred Best
		Source of information: Lot and Block
	40	ASSOCIATED BUILDINGS- [X] yes [] no
	EP	Type: Barn/Garage

ARCHITECTURAL DESCRIPTION: One and a half story with front and cross gables. Foundation is skirted with siding. Wood steps lead up to sunporch entry with hip roof extending across facade. Porch has half-wall with lapped siding and four squared, fluted, full height columns and four mullions evenly spaced across porch facade. Paneled porch door with three horizontal lights and two sidelights. Small pedimented cross gable over the porch door. Glazing on porch is wood casement windows with three horizontal lights each. Atop each pair of casements, is a narrow transom with three lights. Front door inside porch is paneled with a large light. Windows on first floor are double hung wood sash, one-over-one. On east elevation is a transom window with stained glass in the upper light. Shallow bay on west elevation with hip roof. Second floor windows are double hung wood sash, four vertical lights over one. White lapped siding. All trim is white except for black window frames. Light green composition shingles. There is a flared catslide eave on half of the east elevation. The large gable on the facade has a pair of windows on the second story. The windows are flanked by half a sunburst on each side. Over the windows, there are fishscale shingles to the apex. On the east elevation is another gable with the same motifs. A small wall dormer on the west elevation has diagonal siding flanking the windows. Brick chimney on east slope.

Landscaped with lawn, large evergreens across facade, an ash tree on the east lawn, and a trellis on east end of porch. Elm trees in parking area. A two story barn is by alley with a side hip on gable roof with light green composition shingles, white simple drop siding and double hung wood sash windows, four vertical lights over one. The barn has an attached one car garage with white flush siding, light green composition shingle roof and batten swinging doors.

PHOTOGRAPHS (include photographs showing (each side of building and any associated buildings)
Film roll no.: 17 Negative no.: 6	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction	
CONSTRUCTION HISTORY (include description and indetermined.	d dates of major additions, alterations, or demolitio	ns): Roof materials modified to asphalt, date
IISTORICAL BACKGROUND (discuss important per vere the occupants/owners from ca. 1902-195	rsons and events associated with this building): W	Vinifred and Robert Best, a painter/interior decorator,
NFORMATION SOURCES (be specific): Plat Map, unction.	Appraisal Card, Lot and Block Books, Grand Junc	tion City Directories, 1981 Historic Survey of Grand
IGNIFICANCE (check appropriate categories)		THEME(S):
rchitectural significance: represents the work of a master possess high artistic value ? represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district	
ational Register eligibility: dividual [] yes [X] no riteria: [] A [] B [] C [] D rea(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:	
∍riod of significance: 1902		
ATEMENT OF SIGNIFICANCE (briefly justify the sign and roof are one of a kind. The diagonal stional Register, this house may contribute to	siding and sunburst split in half on either side of wi	al Queen Anne style, highly individual house. The indows is uncommon. Although not eligible for the

DATE: 2/14/96

PHONE: (970) 241-9117

Resources Survey, Phase 2

PROJECT NAME: Grand Junction Historic

/ENTORY COMPLETED BY: Museum Group Staff

DRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020

FILIATION: Museum of Western Colorado



1025 Grand Ave. Grand Junction, Mesa Co, CO 2945-144-02-003

5ME7776

01/12/1996 Roll 17 Frame 06 View N Dir S/SE 5ME7776



1025 Grand Ave. Grand Junction, Mesa Co, CO 2945-144-02-003 5ME7776