COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203			SITE NO.: 5ME7786
		Eligible for Nationa	Registeryesno
HISTORIC BUILDING INVENTORY		date initials CriteriaABCD Contributes to a potential National Register districtyesno district name:	
COUNTY: Mesa	Спу: Grand Junction	Eligible for State Registeryesno dateinitials Criteriaabcde Areas of significance:	
HISTORIC BUILDING NAME: Reeme, E.W., Ho	Period of significant	ce initials	
CURRENT BUILDING NAME:	LOCAL LANDMARK DE	ESIGNATION: [] yes [X] no	
ADDRESS: 761 White Ave., Grand Junction,	Date of designation: N/A Designating authority: N/A		
	P.M.: UTE township: 1S range:1W SE ½ of NW ½ of NW% of SE½ of section 14		
OWNER NAME & ADDRESS: Carol Fritz, 2900 981503-2361	Victoria Dr., Grand Junction, CO	UTM REFERENCE-12 Easting: 711180 Northing: 4327100	
	USGS QUAD NAME: Grand Junction		
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'	
STYLE: Classic Cottage		Block: 93 Lot(s): 17 and W2 18 Addition: Year of addition:	
BUILDING TYPE:	[X] original location [] moved		
	Date of moves(s):		
WATERIALS: Concrete Battered Foundation - N	HISTORIC USE: Domestic		
	PRESENT USE: Domestic		
STORIES: 1.5	SQUARE FOOTAGE: 1096		ion- estimate: 1905 actual: n: Tax Assessor's Records
LAN SHAPE:	north arrow	ARCHITECT: Unknow	/n
6	V	Source of information:	
	EP.	BUILDER/CONTRACTOR: Unknown	
Î		Source of information:	
		ORIGINAL OWNER: Charles A. Newton	
		Source of Information: Lot and Block	
00		ASSOCIATED BUILDINGS- [X] yes [] no	
		Type: 2 Car Garage	

ARCHITECTURAL DESCRIPTION: One story with hip roof. Battered foundation. Concrete steps lead up to front porch with hip roof extending across three-quarters of facade. Porch half-wall is shingled down to ground level. Three Tuscan columns and two responds are placed around porch. Front door is paneled with large light. On east facade a pair of French doors open onto porch. Windows are double hung wood sash, one-over-one. Front dormer has a pair of windows and the upper sashes have twenty lights each. Yellow simple drop siding. Door and window surrounds, columns, porch half-wall and dormer cornices are brown. Battered foundations are skirted with brown cedar shingles. Green composition shingle roof with cornices and boxed flared eaves. Flared hip roof dormers on east and north slopes. Shed roof dormers on south and west slopes. Hip roof dormer walls are cedar shingles. Other dormers have brown siding. Two brick chimneys, one on ridge and one on south slope.

Landscaped with lawn, ash and locust trees on west elevation. Ash tree in parking.

Two car garage with side gable has alley access. Yellow simple drop siding. Green roll composition roofing. Two pairs of batten swinging doors.

PHOTOGRAPHS (include photographs showing e	ach side of building and any associated buildings)		
Film roll no.: 16 Negative no.: 24	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction		
Construction History (include description and nasessor's records.	d dates of major additions, alterations, or demolition	s): Additional construction or modifications not noted	
l908-1923. Dorothy, Reeme Realty, and E. W	rst owner/occupant, ca. 1905-1907. Charles Burg, . Reeme, manager of the Mesa County Abstract Co 946. The occupants were Mary J. Stallard, departm	aries A. Newton, President and Manager of the Grand a rancher, was the owner/occupant from ca. mpany, were the owners/occupants ca. 1924-1945. ent manager of Montgomery Ward and Company, and	
NFORMATION SOURCES (be specific): Plat Map, unction City Directories, 1981 Historic Survey	Appraisal Card, Lot and Block Books, Obituary Inde of Grand Junction.	ex, Grand Junction <u>Daily Sentinel</u> Newspaper, Grand	
GIGNIFICANCE (check appropriate categories)		THEME(S):	
rehitectural significance: represents the work of a master possess high artistic value () represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district		
ational Register eligibility: idividual [] yes [X] no riteria: [] A [] B [] C [] D rea(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:		
eriod of significance: 1905			
TATEMENT OF SIGNIFICANCE (briefly justify the significance) chitecture. Battered foundation, shingled half- igible for the National Register, this house may	inificance checked above): A Classic Cottage with wall, flared roof and flared shingled dormers are un contribute to a local register.	styling elements from the shingle school of usual features on a Classic Cottage. Although not	
VENTORY COMPLETED BY: Museum Group Staff		DATE: 2/14/96	
FILIATION: Museum of Western Colorado		PHONE: (970) 241-9117	
DDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2	



760 Colorado Ave. Grand Junction, Mesa Co, CO 2945-144-20-007 5ME7807 01/12/1996 Roll 15 Frame 13 View S Dir NW 5ME7807



761 White Ave. Grand Junction, Mesa Co, CO 2945-144-08-006 5ME7786