	Office of Archaeology	TORICAL SOCIETY and Historic Preservation Denver, CO 80203
	HISTORIC BUIL	DING INVENTORY
COUNTY: Mesa		City: Grand Junction

1300 Broadway Denver, CO 80203 HISTORIC BUILDING INVENTORY		Eligible for National Registeryesno dateinitials CriteriaABCD Contributes to a potential National Register district yesno district name:	
County: Mesa	City: Grand Junction	Eligible for State Register ves no date initials Criteria a b c d e Areas of significance:	
HISTORIC BUILDING NAME: Collinson, Ralph, House		Period of significance Needs data date initials	
CURRENT BUILDING NAME: Wolf Residence		LOCAL LANDMARK DESIGNATION: [] yes [X] no Date of designation: N/A Designating authority: N/A	
ADDRESS: 309 Hill Ave., Grand Junction, CO 81501-2431			
		P.M.: UTE township: 1S range:1W SW ¼ of SE ¼ of NW¼ of NW¼ of section 14	
Owner NAME & ADDRESS: Robert B. Wolf, 309 Hill Ave., Grand Junction, CO 81501-2431		UTM REFERENCE-12 Easting: 710470 Northing: 4327700	
		USGS QUAD NAME: Grand Junction	
	and the second sec	Year: 1962; photorevised 1973 [X] 7.5' [ ] 15'	
STYLE: Bungalow BUILDING TYPE:		Block: 36 Lot(s): E 1/3 of 2 all of 3 and W 1/3 of 4 Addition: Year of addition:	
			[X] original location [] moved
MATERIALS: Concrete Foundation - Wood Frame - Asphalt Shingle Roof		HISTORIC USE: Domestic	
		PRESENT USE: Domestic	
STORIES: 1	SQUARE FOOTAGE: 873	DATE OF CONSTRUCTION- estimate: 1923 'actual: Source of information: Tax Assessor's Records	
PLAN SHAPE:	north arrow	ARCHITECT: Unknown	
		Source of information:	
		BUILDER/CONTRACTOR: Unknown	
		Source of information:	
		ORIGINAL OWNER: Frank R. Hall	
		Source of Information: Lot and Block Books	
		Associated Buildings- [X ] yes [ ] no	
		Type: 2 Car Garage	

SITE NO.: 5ME8344

ARCHITECTURAL DESCRIPTION: One story with side gables. Battered foundation. Concrete steps and stoop with wrought iron railings lead up to gabled screened porch extending across the most of the facade. Flush siding on low half-wall. Full height, 6 x 6 posts on the front corners of porch. Screen door. The front door is paneled and has a light. On the facade, foundation and flared porch base have wide clapboard siding. Windows are double hung wood sash, one-over-one. Most windows have vinyl frame storm windows. White, narrow lapped, wood siding. Door and window surrounds, corner boards, porch posts, half-wall, screen door and screen framing and bargeboards are light blue. Gray composition shingle roof. A brick chimney on the south slope.

Lawn with large lilac on east facade and aspen trees on west facade. A large sycamore tree in parking area.

Metal two car garage at rear with side gable, corrugated metal roof, metal vertical siding, and metal doors. One stall opens to the alley, the other opens toward house.

. 1

PHOTOGRAPHS (include photographs showing each side of building and any associated buildings)			
Film roll no.: 27	Photographer: Carolyn Howard		
Vegative no.: 7	Location of negatives: City Of Grand Junction		

CONSTRUCTION HISTORY (include description and dates of major additions, alterations, or demolitions): Vinyl frame storm windows. Additional construction ir modifications not noted in Assessor's records.

ISTORICAL BACKGROUND (discuss important persons and events associated with this building): Frank R. Hall was the first owner, ca. 1924. Cora M. and talph Collinson, ilvestock, and later an undersheriff, were the owners/occupants ca. 1925-1935. Eleanor Wilson owned the house ca. 1936; the collinsons re-acquired and owned the house ca. 1937-1939. Lucien Horr, a railroader, was the renter ca. 1937-1939. Pete Bosma, manager of the ivoli-Union Brewery, was the renter ca. 1940, and Orville Bishop, the absentee owner. Bernice and Harold Stocker, a railroad machinist, were the wners/occupants ca. 1942 through at least 1951.

FORMATION SOURCES (be specific): Plat Map, Appraisal Card, Lot and Block Books, Grand Junction City Directories.

IGNIFICANCE (check appropriate categories)		THEME(S):
rchitectural significance: represents the work of a master possess high artistic value (] represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district	
ational Register eligibility: .dividual [] yes [X] no riteria: [] A [] B [] C [] D rea(s) of significance: Architecture	Contributes to a potential district: []yes [ X]no District name:	
ariod of significance: 1923		

TATEMENT OF SIGNIFICANCE (briefly justify the significance checked above): A Bungalow with few changes. The foundation on the facade has wide apboards, which is an anomaly. Although not eligible for the National Register, this house may contribute to a local register.

ventory completed by: Museum Group Staff	DATE: 5/31/96
Filiation: Museum of Western Colorado	PHONE: (970) 241-9117
DRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020	PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2




 309 Hill Ave., Grand Junction, Mesa Co, CO

 2945-142-22-002
 02/06/1996

 Roll
 27
 Frame 7
 View N
 Dir SE

 Sm∈
 834 C|



 309 Hill Ave., Grand Junction, Mesa Co, CO

 2945-142-22-002
 02/06/1996 

 Roll 27 Frame 7 View N Dir SE

  $5 m \in 8344$ 

÷.