| COLORADO HISTORICAL SOCIETY | | SITE NO.: 5ME8348 |
|---|---------------------|---|
| Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203 HISTORIC BUILDING INVENTORY | | Eligible for National Registeryesno date initials CriteriaABCp Contributes to a potential National Register districtyesnodistrict name: |
| County: Mesa | Спу: Grand Junction | Eligible for State Register yes no date initials Criteria a b c d e Areas of significance: |
| HISTORIC BUILDING NAME: The house at 515 N. 5th Street | | Period of significance Needs data date initials |
| CURRENT BUILDING NAME: | | LOCAL LANDMARK DESIGNATION: [] yes [X] no |
| ADDRESS: 515 N. 5th St., Grand Junction, CO 81501-2633 | | Date of designation: N/A Designating authority: N/A |
| | | P.M.: UTE township: 1S range:†W NW ¼ of SW ¼ of SE¼ of NW¼ of section 14 |
| OWNER NAME & ADDRESS: Barbara J. Yeager, 1304 Ouray Ave., Grand Junction, CO 31501-4458 | | UTM REFERENCE-12 Easting: 710720 NorthIng: 4327360 |
| | | USGS QUAD NAME: Grand Junction |
| | | Year: 1962; photorevised 1973 [X] 7.5' [] 15' |
| STYLE: Vernacular Wood Frame | | Block: Lot(s): Beg NE cor Lot17 Blk59 S39.32' W18' N68 deg 08 mln W14.87' W31.35' N32.92+ Addition: Year of addition: |
| DUILDING TYPE: | | [X] original location [] moved |
| | | Date of moves(s): |
| ATERIALS: Concrete Foundation - Wood Frame - Asphalt Shingle Roof | | HISTORIC USE: Domestic |
| | | PRESENT USE: Domestic |
| TORIES: 1 | SQUARE FOOTAGE: 712 | DATE OF CONSTRUCTION- estimate: 1905 actual; Source of information: Tax Assessor's Records |
| LAN SHAPE: | north arrow | ARCHITECT: Unknown |
| | ³⁶⁰ ⇒ | Source of information: |
| | | BUILDER/CONTRACTOR: Unknown |
| | | Source of information: |
| | 4 | ORIGINAL OWNER: Charles V. Osgood |
| | | Source of information: Lot and Block Books |
| | | ASSOCIATED BUILDINGS- [X] yes [] no |
| | | Type: Shed |

ARCHITECTURAL DESCRIPTION: One story with front gable. Concrete foundation. Carpeted wood steps with wrought iron railings. Gabled sunporch/entry, with asymmetrical slopes with a longer slope on the north side, extends across north three-fourths of facade. Porch is enclosed with siding and is glazed on the facade and south elevation with wide, fixed sash windows with four horizontal lights each. On the north elevation is a pair of wood casement windows with six lights each. Storm door over white flush door. Original windows around house are double hung wood sash, one-over-one. Some replacements are small pairs of metal framed, single light, sliding windows. Wide, white metal clapboard width siding. Door and window surrounds, corner boards, bargeboards and knee braces are lime green. Light green composition shingle roof with exposed rafter tails. A brick chimney is on the north slope.

Small lawn with pyracantha, evergreens and lilac across the facade. Two elm trees in parking area. Chain-link fence around the yard. Small metal storage building in the backyard.

PHOTOGRAPHS (include photographs showing each side of building and any associated buildings)

Film roll no.: 24 Negative no.: 10 Photographer: Carolyn Howard

Location of negatives: City Of Grand Junction

CONSTRUCTION HISTORY (include description and dates of major additions, alterations, or demolitions): Metal siding, sliding metal windows, porch windows, front door. Additional construction or modifications not noted in Assessor's records.

distorical background (discuss important persons and events associated with this building): The property was owned by Charles V. Osgood, ca. 1901-1920. This residence, which may have first been a garage, was not listed in the City Directories by 1926. Clark J. and Olive B. Martin were the absentee owners, ca. 1923-1927. Wilma and Leonard Andregg, a carpenter, were the renters ca. 1926. Renters, ca. 1928-1931, included a railroader. Occupants, ca. 1933-1944, while the property was owned by the Charles and Ivan Dixon families, included a salesman for Western Slope Auto, a collector, and a meat cutter. Clair and Ruby Trader were the owners ca. 1946, and Marvine and Ernest Elbon, a railroader, the occupants.

THEME(S):

NFORMATION SOURCES (be specific): Plat Map, Appraisal Card, Lot and Block Books, Grand Junction City Directories.

SIGNIFICANCE (check appropriate categories)

vrchitectural significance:

represents the work of a master

possess high artistic value

K] represents a type, period, or method of

construction

lational Register eligibility:

ndividuai [] yes [X] no riteria: [] A [] B [] C [] D

rea(s) of significance: Architecture

Historical significance:

[] associated with significant person(s)

[] associated with significant event

[] associated with a pattern of events

[] contributes to an historic district

Contributes to a potential district:

[]yes [X]no District name:


eriod of significance: 1905

TATEMENT OF SIGNIFICANCE (briefly justify the significance checked above): Bungalow massing and roof are maintained. However, the siding and porch lazing is inappropriate. Although not eligible for the National Register, this house may contribute to a local register.

| VENTORY COMPLETED BY: Museum Group Staff | DATE: 5/31/96 |
|--|--|
| FFILIATION: Museum of Western Colorado | PHONE: (970) 241-9117 |
| DDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020 | PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2 |



515 N. 5th St., Grand Junction, Mesa Co, CO 2945-142-33-010 02/05/1996 Roll 24 Frame 10 View E Dir NW Sm∈8348



515 N. 5th St., Grand Junction, Mesa Co, CO 2945-142-33-010 02/05/1996 Roll 24 Frame 10 View E Dir NW Sme 8348