COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203 HISTORIC BUILDING INVENTORY		SITE NO.: 5ME8372
		Eligible for National Registeryesno date initials CriteriaABCD Contributes to a potential National Register district
		yesno district name:
COUNTY: Mesa	Crry: Grand Junction	Eligible for State Register
HISTORIC BUILDING NAME: Jacques, Anna, House		Period of significance Needs data date initials
CURRENT BUILDING NAME: Knauer Residence		LOCAL LANDMARK DESIGNATION: [] yes [X] no Date of designation: N/A Designating authority: N/A
ADDRESS: 1117 Hill Ave., Grand Junction, CO 81501-3236		
		P.M.: UTE township: 1S range:1W SW 1/2 of SE 1/4 of NE1/4 of NE1/4 of section 14
OWNER NAME & ADDRESS: Helen B. Knauer, 1117 Hill Ave., Grand Junction, CO 81501-3238		UTM REFERENCE-12 Easting: 711685 Northing: 4327720
		USGS QUAD NAME: Grand Junction
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'
STYLE: Bungalow		Block: 44 Lot(s): 5 and 6 Addition: Year of addition:
BUILDING TYPE:		[X] original location [] moved
		Date of moves(s):
MATERIALS: Concrete Foundation-Wood Frame-Aluminum Siding- Asphalt Shingle Roof		HISTORIC USE: Domestic
		PRESENT USE: Domestic
STORIES: 1	SQUARE FOOTAGE: 1030	DATE OF CONSTRUCTION- estimate: 1922 actual: Source of information: Tax Assessor's Records
PLAN SHAPE:	north arrow	ARCHITECT: Unknown
<u>;</u> — -	P-7.	Source of information:
	R G	BUILDER/CONTRACTOR: Unknown
	7	Source of Information:
		ORIGINAL OWNER: Anna Jacques
]	51 L	Source of information: Lot and Block Books
00		ASSOCIATED BUILDINGS- [X] yes [] no
		Type: Garage

ARCHITECTURAL DESCRIPTION: One story with front gable roof. Gable wing projecting from east half of facade. Concrete steps with wrought iron railing arranged parallel to the street, leads to a screened porch integral in the west half of facade. Porch half-wall is sided with aluminum clapboard siding down to ground level. Single, full height, squared corner porch post. Ribbons of wood frame screens with screened transoms around both sides of porch. Wood framed porch screen door. Main door is glazed. Windows are varied. Large mull window in facade. Remaining windows are sash and sliding windows. All windows have metal frames and storm windows. Projecting bay with gable roof and knee braces on east elevation. Gray composition shingle roof with overhanging eaves with knee braces and exposed rafters. White aluminum clapboard siding. Screened porch door, steps, porch screen frames, porch posts, knee braces, exposed rafters and bargeboards are white. Brick chimney on west slope.

Lawn with two saplings along street. Pine sapling in front yard. Row of large shrubs along west perimeter of lot. Chain-link fence with gate, flush with

east side of facade. Tall wood fence along rear of lot.

Single car garage in rear with front gable, knee braces and exposed rafters. Roof shingles and siding same as house.

PHOTOGRAPHS (include photographs showing a	each side of building and any associated building	
Film roll no.: 32		8)
Negative no.: 24	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction	on
CONSTRUCTION HISTORY (include description an construction or modifications not noted in Asse	d dates of major additions, alterations, or demoliti ssor's records.	ions): Siding and replaced windows. Additional
owners/occupants ca. 1925-1926. Anna Heldr owners/occupants ca. 1925-1926. Anna Heldr Stommel, a junior high teacher, were the rente John H. Freeman, a repairman, were the rente Forrest W. Daniels, were the owners/occupants	Anna M. and Stewart L. Jacques, a foreman for nan was the owner/occupant, ca. 1926-1930, and rs, ca. 1931. Mrs. Heldman and Minda Heldman rs, ca. 1935, and Charlotte and Charles Wilcox, a s, ca. 1946.	i the absentee owner, ca. 1931. Mary and Herman G. were the absentee owners/ ca. 1932-1941. Mima and in assistant railroad engineer, ca. 1937-1941. Hallie and
	Appraisal Card, Lot and Block Books, Grand Jur	action City Directories.
SIGNIFICANCE (check appropriate categories)		THEME(s):
Architectural significance: represents the work of a master possess high artistic value XJ represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district	
lational Register eligibility: ndividual [] yes [X] no :riteria: [] A [] B [] C [] D .rea(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:	
eriod of significance: 1922		
TATEMENT OF SIGNIFICANCE (briefly justify the sign ppropriate. Aithough not eligible for the Nation	nificance checked above): Massing of this house al Register, this house may contribute to a local i	se is unaltered, but the siding and windows are not register.
VENTORY COMPLETED BY: Museum Group Staff		DATE: 5/31/96
FILIATION: Museum of Western Colorado		PHONE: (970) 241-9117
ODRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2



1117 Hill Ave., Grand Junction, Mesa Co, CO 2945-141-19-003 02/29/1996 Roll 32 Frame 24 View N Dir S/SE 5ME 3372



1117 Hill Ave., Grand Junction, Mesa Co, CO 2945-141-19-003 02/29/1996 Roll 32 Frame 24 View N Dir S/SE 5ME 8372