COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation		SITE NO.: 5ME8373
1300 Broadway	Denver, CO 80203	Eligible for National Registeryesno dateinitials
HISTORIC BUILDING INVENTORY		CriteriaABCD Contributes to a potential National Register districtyesno district name:
County: Mesa	Спу: Grand Junction	Eligible for State Registeryesno date initials Criteria ab cde Areas of significance:
HISTORIC BUILDING NAME: Reeds, Frank, House		Period of significance
CURRENT BUILDING NAME:		LOCAL LANDMARK DESIGNATION: [] yes [X] no Date of designation: N/A Designating authority: N/A
ADDRESS: 1129 Hill Ave., Grand Junction, CO 81501-3236		
		P.M.: UTE township: 1S range:1W SE ½ of SE ½ of NE½ of NE½ of section 14
OWNER NAME & ADDRESS: Jeffrey D. Hurd, PO Box 3334, Grand Junction, CO 81502-3334		UTM REFERENCE-12 Easting: 711680 Northing: 4327720
		USGS QUAD NAME: Grand Junction
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'
STYLE: Bungalow		Biock: 44 Lot(s): 7 and 8 Addition: Year of addition:
BUILDING TYPE:		[X] original location [] moved
		Date of moves(s):
MATERIALS: Concrete Foundation - Wood Frame - Asphalt Shingle Roof		HISTORIC USE: Domestic
		PRESENT USE: Domestic
STORIES: 1	SQUARE FOOTAGE: 990	DATE OF CONSTRUCTION- estimate: 1924 actual: Source of information: Tax Assessor's Records
LAN SHAPE:	north arrow	ARCHITECT: Unknown
		Source of information:
(B)		BUILDER/CONTRACTOR: Unknown
		Source of information:
		Original owner: William W. DeVoe
		Source of information: Lot and Block Books
	· M. · · · · · · · · · · · · · · · · · ·	ASSOCIATED BUILDINGS- [X] yes [] no
		Type: Garage

ARCHITECTURAL DESCRIPTION: One story with side gable roof. Concrete steps and brick piers with concrete coping lead to large enclosed sunporch/entry with front gable roof with knee braces, extending across east three-quarters of facade. Wood shake shingle siding from half-wall down to ground level. Squared, corner porch posts covered with shake shingles. Porch glazing is varied. Large double hung wood sash window, ten over one in facade. Windows on both ends of porch are wood frame casements with four light transoms. Porch door is paneled and has a large light, and is flanked by tail, narrow side lights with four light transoms. Wood trellis on west end of porch. Majority of windows around house are double hung wood sash, five-over-one. Small windows divided into six lights in side gable faces of house. Shed roof bay window with knee braces on east elevation. Black composition shingle roof with overhanging eaves and knee braces. House faced with wood red shake shingles. Window frames and surrounds and raking comices are white. Porch door is dark gray. Knee braces are red. Brick chimney on south slope.

Lawn with young tree along street. Low shrub along front of porch. Plant growing up porch trellis. Rear and west side of lot enclosed by combination of chain-link, wire and wood fence. Low picket fence extends along west side of front yard to the sidewalk.

Single car garage in rear with front gable, black composition shingle roof with overhanging eaves, and red simple drop siding. Corner boards are white.


PHOTOGRAPHS (Include photographs showing e	each side of building and any associated building	5)
Film roll no.: 33 Negative no.: 1	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction	on
CONSTRUCTION HISTORY (include description an modifications not noted in Assessor's records.	d dates of major additions, alterations, or demoliti	ons): Porch enclosed. Additional construction or
Mesa County Credit Union, were the renters, c	16I. I Ne Keeds continued as absentee owners (The house was owned/occupied, ca. 1926-1928 by Ruth ca. 1929-1937. Ida and Oliver Reed, manager of the of the Sinclair Refining Company, and later of Power Oil layden McCormick, a foreman.
NFORMATION SOURCES (be specific): Plat Map,	Appraisal Card, Lot and Block Books, Grand Jur	nction City Directories.
SIGNIFICANCE (check appropriate categories)		THEME(s):
\rchitectural significance: represents the work of a master possess high artistic value x represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district	
lational Register eligibility: ndividual [] yes [X] no interia: [] A [] B [] C [] D rea(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:	
eriod of significance: 1924		
TATEMENT OF SIGNIFICANCE (briefly justify the sign of the hold linter heights match the main body of the hold linter heights match the m	gnificance checked above); The porch on this house. Although not eligible for the National Regis	ouse is enclosed with more care than is usual. The sill ter, this house may contribute to a local register.
VENTORY COMPLETED BY: Museum Group Staff		DATE: 5/31/96
FFILIATION: Museum of Western Colorado		PHONE: (970) 241-9117
DORESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic

PROJECT NAME: Grand Junction Historic

Resources Survey, Phase 2



1129 Hill Ave., Grand Junction, Mesa Co, CO 2945-141-19-004 02/29/1996 Roll 33 Frame 1 View N Dir S/SW 5ME 3373



1129 Hill Ave., Grand Junction, Mesa Co, CO 2945-141-19-004 02/29/1996 Roll 33 Frame 1 View N Dir S/SW 5ME 8373