	STORICAL SOCIETY and Historic Preservation Denver, CO 80203	SITE NO.: 5ME8384
1300 Broadway		Eligible for National Registeryesno
HISTORIC BUILDING INVENTORY		dateinitials CriteriaABCD Contributes to a potential National Register districtyesno district name:
County: Mesa	CITY: Grand Junction	Eligible for State Register
HISTORIC BUILDING NAME: Wiggins, Autraus, House		Period of algnificance
CURRENT BUILDING NAME: Valles Residence		LOCAL LANDMARK DESIGNATION: [] yes [X] no
ADDRESS: 847 Belford Ave., Grand Junction, CO 81501-3130		Date of designation: N/A Designating authority: N/A
		P.M.: UTE township: 1S range:1W SE ¼ of NE ¼ of NW¼ of NE½ of section 14
OWNER NAME & ADDRESS: Margaret R. Valles, 847 Belford Ave., Grand Junction, CO 81501-3130		UTM REFERENCE-12 Easting: 711295 Northing: 4327880
		USGS QUAD NAME: Grand Junction
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'
STYLE: Post World War II		Block: 19 Lot(s): N80.15' lot 12+13; N80.15' W2 lot 14+W12' of S45' lot 12 Addition: Year of addition:
BUILDING TYPE:		[X] original location [] moved
MATERIALS: Concrete Foundation - Wood Frame - Asphalt Shingle Roof		Date of moves(s):
- Asphal Shingle Root		HISTORIC USE: Domestic PRESENT USE: Domestic
STORIES: 1	SQUARE FOOTAGE: 864	DATE OF CONSTRUCTION- estimate: 1950 actual: Source of Information: Tax Assessor's Records
PLAN SHAPE:	north arrow	ARCHITECT: Unknown
C.S.	₽	Source of information:
12		BUILDER/CONTRACTOR: Unknown
Ī		Source of information:
		ORIGINAL OWNER: Rex Rankin and S.J. Bond
Ł	1 00	Source of information: Lot and Block Books
		ASSOCIATED BUILDINGS- [X] yes [] no
		Type: Storage Shed


ARCHITECTURAL DESCRIPTION: One story with side gable. Concrete foundation. Carpeted concrete steps lead up to a screen porch, with an extended shed roof, across the west half of the facade. Flush panels on half-wall. Screen door has a white wood frame. Front door is paneled with six small lights and a metal frame storm door. Windows are double hung wood sash, two horizontal lights over two. Plank shutters. A large picture window is on the west facade, sheltered by the porch. Siding is white wood clapboard. The foundation, porch base, shutters and gables faces are light blue. The roof is light green composition shingles. The gable faces have vertical siding. Lawn with very large fir tree by west facade. A white wood lattice screens the west half of the screen porch. Roses and a large liliac are across the lawn. The back yard is enclosed by a white picket fence. Gravel in parking.

Small white frame storage building in back yard has side gable roof with brown composition shingles.

PHOTOGRAPHS (include photographs showing e	each side of building and any associated buildings)
Film roll no.: 32 Negative no.: 18	Photographer: Carolyn Howard Location of negatives: City Of Grand Junctio	n
Construction History (include description and Assessor's records.	d dates of major additions, alterations, or demolitic	ons): Additional construction or modifications not noted
zenzin and 9. 2. Bond, and telled, 69. 1801-1	rsons and events associated with this building): 0 955, by Katherine and Autraus W.Wiggins, a cond th Daniels Enterprises, were the occupants ca. 18	Constructed ca. 1950, the house was first owned by Rex ductor with the Denver and Rio Grande Railway. 956, and Charles V. Cox, ca. 1957.
NFORMATION SOURCES (be specific): Plat Map,	Appraisal Card, Lot and Block Books, Grand Jun	ction City Directories.
IGNIFICANCE (check appropriate categories)		THEME(S):
rehitectural significance: represents the work of a master possess high artistic value (] represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district	
ational Register eligibility: dividual [] yes [X] no riteria: [] A [] B [] C [] D rea(s) of significance: Architecture	Contributes to a potential district: [[yes [X]no District name:	
ariod of significance: 1950		
TATEMENT OF SIGNIFICANCE (briefly justify the significant of clapboard and platformal Register, this house may contribute to a	aπk snutters. A screen porch on the facade is no	has the typical features of the time, including the typical of 1950, however. Although not eligible for the
ENTORY COMPLETED BY: Museum Group Staff		DATE: 5/31/96
FILIATION: Museum of Western Colorado		PHONE: (970) 241-9117
DRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2



847 Belford Ave., Grand Junction, Mesa Co, CO 2945-141-10-006 02/29/1996 Roll 32 Frame 18 View N Dir S/SW 5ME \3\(\text{-1}\)



847 Belford Ave., Grand Junction, Mesa Co, CO 2945-141-10-006 02/29/1996 Roll 32 Frame 18 View N Dir S/SW 5ME 중공왕식