\mathbb{Q}^{n}

10

. .

COLORADO HISTORICAL SOCIETY		SITE NO.: 5ME8500	
Office of Archaeology and Historic Preservation		Elizible for National Register yes no	
1300 Broadway Denver, CO 80203		Eligible for National Registeryesno date initials	
		Criteria A B C D	
		Contributes to a potential National Register district	
HISTORIC BUILDING INVENTORY		yesno district name:	
	[Eligible for State Registervesno	
COUNTY: Mesa	CITY: Grand Junction	date initials Criteriaabcde	
		Areas of significance:	
	<u> </u>		
HISTORIC BUILDING NAME: Lang, J.W., House			
		Period of significance initials	
CURRENT BUILDING NAME:	LOCAL LANDMARK DESIGNATION: [] yes [X] no		
	Date of designation: N/A		
ADDRESS 719 N. 4th St., Grand Junction,	Designating authority: N/A		
	P.M.: UTE township: 1S range:1W		
		NE ¼ of NE ¼ of SW¼ of NW¼ of section 14	
OWNER NAME & ADDRESS: Elva M. Conrow, 3125 Cloverdale Ct., Grand Junction CO		UTM REFERENCE-12	
81506-1952		Easting: 710560	
		Northing: 4327580	
		USGS QUAD NAME: Grand Junction	
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'	
STYLE: Bungalow		Block: 36	
	Lot(s): 17 and 18		
	Addition:		
		Year of addition:	
BUILDING TYPE:		[X] original location [] moved	
		Date of moves(s):	
MATERIALS: Concrete Foundation - Wood Frame - Asphalt Shingle Roof			
	Brentha (an) Democht		
	PRESENT USE: Domestic		
1.1450 (M)			
STORIES: 1	SQUARE FOOTAGE: 712	DATE OF CONSTRUCTION- estimate: 1915 actual:	
		Source of Information: Tax Assessor's Records	
PLAN SHAPE:	north arrow	ARCHITECT: Unknown	
		Source of information:	
1	a the and the state of the stat	BUILDER/CONTRACTOR: Unknown	
		Source of information:	
former, s	99-49 99-99 99-99 99-99	ORIGINAL OWNER: J.W. Lang	
	CI	Source of information: Lot and Block Books	
Ö			
[ASSOCIATED BUILDINGS- [] yes [X] no	
		Туре:	

ARCHITECTURAL DESCRIPTION: One story with front gable roof. Gable wing extends from the north elevation. Battered foundation skined with gray shake shingles. Concrete steps on south elevation lead to partially screened porch with hipped roof extending across three-quarters-of facade. Shake shingle siding on half-wall extends down to ground level. Metal screen door. Thin, wood screen frames. Squared half-height corner post. Front door is paneled and has a large single light. A set of narrow French doors with transom leads to sunporch on northern half of porch. Sunroom-glazed with ribbons of narrow, eight light casement windows. Windows are varied. A pair of double hung, wood sash, one-over-one, windows with wood screens on the south elevation. Two large, wood framed sliding windows on the north elevation. Gray false bevel siding. Window frames and surrounds, wood screens and corner boards are gray. Raking cornices, fascia and exposed rafter ends are white. Red octagon composition shingle roof with overhanging eaves and exposed rafter ends.

1 FORCE

Landscaped yard with mature trees and rose bushes next to street. Large rose bush and lilac along facade. Mature locust tree in back yard. South side of yard enclosed by chain-link fence.

PHOTOGRAPHS (include photographs showing each	side of building and any associated buildings)
Film roll no.: 26 Negative no.: 13	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction

CONSTRUCTION HISTORY (include description and dates of major additions, atterations, or demolitions): Additional construction or modifications not noted in Assessor's records.

HISTORICAL BACKGROUND (discuss important persons and events associated with this building). Genevieve and John W. Lang, an engineer with the Denver and Rio Grande Railway, were the original owners/occupants of the house, ca. 1915-1932. Genevieve was then the absentee owner, ca. 1933 through at least 1946. Ida Claire and Jack Cagle, an office manager for Safeway, were the renters, 1935 through 1940; Georgia and Norris A. Mathey, a forester with the U. S. Department of Grazing, ca. 1941; and Grace and Arthur Adams, a clerk at Ted's Grocery Market, ca. 1946.

SIGNIFICANCE (check appropriate categories)		THEME(S):	
rchitectural significance: represents the work of a master possess high artistic value (] represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district		
lational Register eligibility: ndividual [] yes [X] no riteria: [] A [] B [] C [] D rea(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:		
eriod of significance: 1915			

STATEMENT OF SIGNIFICANCE (briefly justify the significance checked above): The well executed porch on this house accommodates both screen and sunporch sections. Although not eligible for the National Register, this house may contribute to a local register.

INVENTORY COMPLETED BY: Museum Group Staff	DATE: 5/31/96	
AFFILIATION: Museum of Western Colorado	Рноке: (970) 241-9117	
ADDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020	PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2	

INFORMATION SOURCES (be specific): Plat Map, Appraisal Card, Lot and Block Books, Grand Junction City Directories.



 719 N. 4th St., Grand Junction, Mesa Co, CO

 2945-142-22-008
 02/06/1996

 Roll 26 Frame 13 View E Dir NW

 5ME8500



 719 N. 4th St., Grand Junction, Mesa Co, CO

 2945-142-22-008
 02/06/1996

 Roll
 26
 Frame 13
 View E
 Dir NW

 5mE8500
 500