102 112

COLORADO HISTORICAL SOCIETY		SITE NO.: 5ME8517	
Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203		Eligible for National Registeryesno	
		date initials CriteriaABCD	
HISTORIC BUILDING INVENTORY		Contributes to a potential National Register districtyesno district name:	
		Eligible for State Registeryesno	
County: Mesa	City: Grand Junction	date initials Criteria a b c de	
		Areas of significance:	
HISTORIC BUILDING NAME: Fancher, Charles, House			
		Period of significance initials	
CURRENT BUILDING NAME:		LOCAL LANDMARK DESIGNATION: [ ] yes [X] no	
		Date of designation; N/A	
ADDRESS: 1260 Rood Ave., Grand Junction, CO 81501		Designating authority: N/A	
		P.M.: UTE township: 1S range:1W	
		SW ½ of NW ½ of NW½ of SW½ of section 13	
Owner NAME & ADDRESS: C.M. Fancher, PO Box 608, Grand Junction, CO 81502-9698		UTM REFERENCE-12 Easting: 711920	
		Northing: 4327000	
		USGS QUAD NAME: Grand Junction	
		Year: 1962; photorevised 1973 [X] 7.5' [ ] 15'	
STYLE: Bungalow		Block; D Lot(s): 17 and 18	
		Addition: Keith Year of addition: 1890	
BUILDING TYPE:		[X] original location [] moved	
		Date of moves(s):	
MATERIALS: Concrete Foundation - Wood Frame - Asphalt Shingle Roof		HISTORIC USE: Domestic	
Time Staping Constitution Vision France Staping Consigner Con		PRESENT USE: Domestic	
		PRESENT USE, DOMESTIC	
STORIES: 1	SQUARE FOOTAGE: 942	DATE OF CONSTRUCTION- estimate: 1922 actual: Source of information: Tax Assessor's Records	
PLAN SHAPE:	north arrow	ARCHITECT: Unknown	
1		Source of information:	
	+ - <sub>1</sub>	BUILDER/CONTRACTOR: Charles Fancher	
- Parameter		Source of information: David Sundal, Oral History	
		Source of information: David Sundai, Oral history	
6		ORIGINAL OWNER: Charles Fancher	
		Source of information; Lot and Block Books	
		Associated Buildings- [X ] yes [] no	
		Type: Garage	


ARCHITECTURAL DESCRIPTION: One story, front gable roof: Battered basement skirted with simple drop aluminum siding. Concrete steps with wrought iron railings, lead to an enclosed porch with gable roof in center two-thirds of facade. Simple drop aluminum siding on half-wall extends down to ground level. Half-height, squared, tapered piers in corners. Ribbons of large fixed pane windows with single pane transoms on all three sides. Two large glass blocks appear on both sides of porch door below the sills of the windows. Porch has metal frame storm door with single light. Main door is flush with a diagonal arrangement of three small lights. Two large double hung wood frame picture windows with three light transoms in facade. East elevation has two fixed pane, metal frame windows and two small metal sash windows and one small metal sash window. Small, double pane basement windows on east elevation. White simple drop aluminum siding. Window surrounds, corner boards, barge boards, porch posts are blue. Gray composition shingle roof. Brick chimney on ridge.

Dirt and grass yard in corner lot. One mature and two young trees along street, Mature poplar tree in front yard. Two shrubs along facade. Section of wood fence on west side of lot.

One dangurage arroad with none game, gray o	omposition sningte root, and white talse bevel siding			
PHOTOGRAPHS (include photographs showing each side of building and any associated buildings)				
Film roll no.: 44 Negative no.: 15	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction			
CONSTRUCTION HISTORY (include description and da Additional construction or modifications not noted in	ates of major additions, alterations, or demolitions); in Assessor's records.	Aluminum siding. Metal frame windows.		
HISTORICAL BACKGROUND (discuss Important persons and events associated with this building). Built in 1922 and occupied by owner Charles Monte and Elizabeth Fancher through at least 1993. Mr. Fancher is listed as a mechanic for Murr-Harris and Rio Grande Motorway. He was a pioneer aviator in this area, and flew his plane from a nearby alfalfa field.				
INFORMATION SOURCES (be specific): Plat Map, Appraisal Card, Lot and Block Books, Grand Junction City Directories. Grand Junction Historic Survey, 1981.				
SIGNIFICANCE (check appropriate categories)		THEME(s):		
Architectural significance: [] represents the work of a master [] possess high artistic value [X] represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district			
National Register eligibility: Individual [] yes [X] no Criteria: [] A [] B [] C [] D Area(s) of significance: Architecture	Contributes to a potential district: []yes [ X]no District name:			
Period of significance: 1922				
STATEMENT OF SIGNIFICANCE (briefly justify the significance checked above): The small, high windows on the side elevations were used occasionally on Bungalows. Although not eligible for the National Register, this house may contribute to a local register.				
INVENTORY COMPLETED BY: Museum Group Staff		DATE: 5/31/96		
AFFILIATION: Museum of Western Colorado		PHONE: (970) 241-9117		
ADDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2		



1260 Rood Ave., Grand Junction, Mesa Co, CO 2945-133-05-015 05/14/1996 Roll 44 Frame 15 View S Dir NW 5ME 85/7



1260 Rood Ave., Grand Junction, Mesa Co, CO 2945-133-05-015 05/14/1996 Roll 44 Frame 15 View S Dir NW 5m £ 85/7